

1 Mar 71 11:47z

KIA

IMMEDIATE

* UNCLASSIFIED E F T O *

PT 00092

OTTEZYUW RUMOREA0132 0601039-EEEE-RUWTFJA.

ZNY EEEEE

0 P 010935Z MAR 71 ZFF-1

FM 56 CSG NKP APRT THAI

TO RUWTFJA/USAFMPC/DMPSC/RANDOLPH AFB TEX

RUEFHQA/CSAF/SSSKC

INFO RUHHABA/CINCPACAF/DPSP

RUMMRSA/7AF/DPSP TSN AB RVN

RUMMWKA/13AF/DPSP/CLARK AB PI

RUMOSRA/DEPCOMDR 7/13AF/UDORN AFLD THAI

RUMUHTA/COMUSMACV SAIGON RVN

RHMFTA/COMUSMACTHAI BANGKOK THAI

RUVEFFB/AEAFAC/AJC/DENVER COLO

BT

UNCLAS E F T O DBPO-PA

SUBJ: CASUALTY RPT, INITIAL MISSING RPT, NON-BATTLE.

A. TIJERINA REPEAT TIJERINA, ALBERT JR.

B. CAPTAIN

C. REPEAT [REDACTED] FV. AIR FORCE RESERVE, AIE

AFSN FV3176495 REPEAT FV3176495.

D. 21ST SPECIAL OPERATIONS SQUADRON, PACAF, NAKHON PHANOM
RTAFB THAILAND. DATED PCS SEA TOUR COMMENCED: 14 DEC 70.

PAGE 2 RUMOREA0132 UNCLAS E F T O

E. NORTHERN LAOS. GEOGRAPHICAL COORDINATES WILL BE FURNISHED
BY CLASSIFIED MESSAGE.

F. 1 MAR 71, 1130HOURS LOCAL.

G. CAPTAIN TIJERINA AS PILOT OF A CH-53 AIRCRAFT DEPARTED NAKHON
PHANOM RTAFB AT 0830 HOURS LOCAL 1 MAR 71 ON A CLASSIFIED MISSION.
LAST CONTACT WAS AT 1123 HOURS LOCAL. AIRCRAFT CRASHED AND
BURNED AT A CLASSIFIED LOCATION IN NORTHERN LAOS AT APPROXIMATELY
1130 HOURS LOCAL 1 MAR 71. CAUSE OF THE AIRCRAFT CRASH HAS
NOT BEEN DETERMINED. A GROUND TEAM IS SCHEDULED TO BE IN THE CRASH
AREA ON 2 MAR 71 FOR FUTHER INVESTIGATION.

H. [REDACTED], WIFE, [REDACTED]

SON [REDACTED]

SON [REDACTED]

[REDACTED], DAU:

FATHER, [REDACTED]

MOTHER, [REDACTED]

I. REQUEST ASSISTANCE OF USAFMPC (DPMSC) IN MAKING NOTIFICATION.

J. 27 AUG 70

K. [REDACTED], WIFE (100 PERCENT) [REDACTED]

1 MAR 71
1130HOURS
CLASSIFIED
14 DEC 70
100 PERCENT

IMMEDIATE

* UNCLASSIFIED E F T O *

Info removed by VNCA