

UNCLASSIFIED

DEPARTMENT OF THE ARMY
HEADQUARTERS 11TH COMBAT AVIATION GROUP
APO San Francisco 96349

AVBATS-C

16 April 1972

SUBJECT: Enemy Attacks on US Installations after action Report (Final)

THRU: Commanding General
1st Aviation Brigade
ATTN: AVBAGC
APO 96384

Commanding General
United States Army Vietnam
ATTN: AVHAV-OPT
APO 96375

TO: Commander
United States Military Assistance Command, Vietnam
ATTN: MACJ3-05
APO U.S. Forces 96222

1. 150240 April 1972.
2. 11th Combat Aviation Group.
3. BT 063736
4. Mortar
5. See Inclosure 1
6. N/A
7. N/A
8. N/A
9. Suspected Mortar Position at BT 046725.
10. Initial 3 rounds at 0240, then 22 rounds at 0303, Duration 23 minutes.
11. N/A
12. Light fire team and Flaeship sent up.
13. N/A

UNCLASSIFIED

201-07 (after cut)

File

UNCLASSIFIED

14. The mobile reaction force was assembled and perimeter defense were placed on 100 percent alert.

15. Colonel Robert A. Holloman III, Commander of 11th Combat Aviation Group.

16. 11th Combat Aviation Group.


17. a. E/A

b. Zulu Company (Guard Company) fired 81mm illumination rounds east of airfield.

c. See inclosure 2.

2 Incl

as



ROBERT A. HOLLAMAN III

COL, USAF
Commanding

UNCLASSIFIED

UNCLASSIFIED

DEPARTMENT OF THE ARMY
Headquarters, 11th Combat Aviation Group
APO San Francisco 96349

AFMPS-D-24

15 April 1972

SUBJECT: After Action Report

1. No. & Type Aircraft	Amount of Damage	Major Type Damage
69-15543 TH-1H	Major	sheetmetal, 1/2 blade chin bubbles, extensive electrical work
69-15527 TH-1H	Major	sheetmetal, chin bubbles, drive shaft, 1/2 blades, swash plate, windshield
70-15748 TH-1H	Major	chin bubbles, 1/2 blades 1/2 blade, 42 degree 1/3 sheetmetal, electrical work
68-15375 TH-1H	Major	sheetmetal, power train, 1/3 change
69-16030 OH-58A	Major	extensive sheetmetal, 1/2 blade
69-15207 TH-1H	Minor	sheetmetal, 1/2 blade, windshield, chin bubble
68-15678 TH-1H	Minor	1/2 blade
68-15674 TH-1H	Minor	sheetmetal
69-15508 TH-1H	Minor	sheetmetal, 1/2 blade
70-15738 TH-1H	Minor	sheetmetal
69-15619 TH-1H	Minor	sheetmetal, chin bubble 1/2 blades
70-15751 TH-1H	Minor	sheetmetal, chin bubble 1/2 blade
70-15044 TH-1H	Major	sheetmetal, 1/2 blade, 1/2 blades, both wind- shields and chin bubbles, excessive electrical damage

UNCLASSIFIED

UNCLASSIFIED

AFB 183-D-AM

SUBJECT: After Action Report

15 April 1972

<u>No. & Type Aircraft</u>	<u>Amount of Damage</u>	<u>Major Type Damage</u>
68-16776 OH-58A	Minor	sheetmetal
69-16117 OH-58A	Minor	H/R blade
68-16930 OH-58A	Minor	sheetmetal
68-16689 OH-58A	Minor	sheetmetal
66-18040 U-21A	Minor	sheetmetal
67-18020 U-21A	Minor	sheetmetal, deice boots props
67-18537 OH-47C	Minor	4 blades, chin bubble sheetmetal
70-15001 OH-47C	Minor	4 blades, sheetmetal
2. Total	Major Damage	Minor Damage
	5 - OH-1H	7 - OH-1H
	1 - OH-58A	4 - OH-58A
		2 - U-21A
		2 - OH-47C
Totals	6	15


3. All aircraft were in revetments.

Bruce C. Williamson Jr.
 BRUCE C. WILLIAMSON JR.
 CPT, PC
 Left Maint Officer

UNCLASSIFIED

UNCLASSIFIED

NORTH



ROUND IMPACT POINTS

- CHINOOK
- UH1H
- U21
- OH58

*** ONLY 24 IMPACT POINTS FOUND

**** ROUND LANDED 50 FEET SE CAUSING DAMAGE TO METAL SHEETING ON A STORAGE BLDG. (SLIGHT DAMAGE WAS ALL)

131ST MI

UNCLASSIFIED