

Helicopter 66-16117

Information on U.S. Army helicopter tail number 66-16117

Date: 670717

Accident case number: 670717041

Number killed in accident: 0 Injured: 0 Passengers: 0
costing 8228

Crew Members:

AC W1 JD OGLE

Accident Summary:

While on a short final, the main rotor blades struck a tree limb.

Information on U.S. Army helicopter tail number 66-16117

Date: 670721

Accident case number: 670721021 Total loss or fatality Accident

Number killed in accident: 0 Injured: 3 Passengers: 1
costing 228554

Crew Members:

AC W1 DL RANKIN

P O2 RL JANES

CE E5 JG THIBAULT

G E4 BK FENTON

Passengers:

X2 NO NAME, PAX, D;

Accident Summary:

The engine failed in flight due to fuel starvation. An autorotation was made to a rice paddy with termination on the right side.

Information on U.S. Army helicopter UH-1D tail number 66-16117

Date: 670727

South Vietnam

Loss to Inventory

Please send additions or corrections to:

Gary Roush

Email address: