

Helicopter 66-16105

Information on U.S. Army helicopter tail number 66-16105

The Army purchased this helicopter 0267

Total flight hours at this point: 00000298

Date: 670715

Accident case number: 670715091 Total loss or fatality Accident

Unit: 610 TRANS CO

Number killed in accident: 0 Injured: 3 Passengers: 0

costing 228554

Crew Members:

AC O2 DT EDWARDS

P W1 FE YUNGWIRT

CE E4 JD SCOTT

G E3 TM BUCKLES

Accident Summary:

□ The aircraft began climb out, lost RPM, and began to settle. In an effort to avoid a railroad abutment, the pilot flared the aircraft causing the tail rotor to strike a rice paddy. The aircraft regained RPM and lost directional control. The aircraft made a hard landing after several revolutions.

Information on U.S. Army helicopter UH-1D tail number 66-16105

The Army purchased this helicopter 0267

Total flight hours at this point: 00000298

Date: 670720

Unit: HHC2BDE 1CAVDIV

South Vietnam

Loss to Inventory

The following is Goldbook information on US Army helicopter tail number 66-16105

It is provided here as an ESTIMATE of the history of this helicopter and is not intended to be the final authority.

This helicopter was purchased by the US Army in 0267.

Please provide any additional information on this helicopter to the VHPA.

DATE	FLT	HRS	UIC	UNIT	AREA	POST	COUNTRY
6702	0	0	WOY6AA	TRAN MDMHELCO S	ALASKA		ALASKA
6703	0	0	WOMHAA	DIROF SUP TRAN	6TH ARMY	SHARPE GD	AVCOM
6704	41	41	WAGGAA	HHC2BDE 1CAVDIV	VIETNAM		RVN
6705	118	159	WAGGAA	HHC2BDE 1CAVDIV	VIETNAM		RVN
6706	123	282	WAGGAA	HHC2BDE 1CAVDIV	VIETNAM		RVN
6707	16	298	WC5GAA	610 TRANS CO	VIETNAM		RVN

Please send additions or corrections to:

Gary Roush

Email address:

