

AD 165 0349

DECLASSIFIED

RTTEZYOW RUMMWUA9026 1640430-EEEE--RUMMWUA.
ZNY EEEEE

P 130430Z JUN 69

FM CTU SEVEN ZERO PT EIGHT PT FIVE

TO RUMJAJA/COMCRUDESAPAC

RUMFBYM/CTG SEVEN ZERO PT EIGHT

INFO RUMFTIL/COMASWGRU ONE

ZEN/SRF SUBIC

ZEN/NSD SUBIC

ZEN/COMCRUDESAPAC LOGREP WESTPAC

RUMFBYM/COMCRUDESFLOT THREE

ZEN/COMDESKON TWENTY-THREE

ZEN/USC FRANK E. EVANS

RUMH6SAF/COMSLVENTHFLT

RUMYMBG/CTF SEVEN THREE

ZEN/CTU SEVEN THREE PT ONE PT TWO

RUMHUBA/COMSERVPAC

BT

UNCLAS E F T O

CTU SEVEN ZERO PT EIGHT PT ONE SENDS

STRIPPING OF FRANK E. EVANS SITREP 01

1. THIS INITIAL REPORT RECAPS ACTIONS TAKEN RELATIVE TO SUPPLY FUNCTIONS.

I-SRF
NSD
COMCRUDESAPAC LOGREP
CDR 23
EVANS
73.1.2

PAGE 2 RUMMWUA9026 UNCLAS E F T O

IN EVANS AND ADDRESSES REMOVAL OF ELECTRONICS, DASH AND SMALL ARMS.

2. DISBURSING: NO LOSS OF DISBURSING FUNDS. ALL RGRD REPORTS CONCERNING DISBURSING SERVICES HAVE BEEN SUBMITTED. ALL RETAINED RECORDS FORWARDED TO FEDERAL RECORDS CENTER.

3. SHIP STORE: ONE SHIPSTORE STOREROOM LOST. REMAINING STOCK REMOVED AND PLACED IN SECURE STORAGE. APPROX 90 PERCENT MATL RECOVERED. MATL TO BE INVENTORIED BY BOARD OF OFFICERS AND TURN-IN. MARKDOWN. SURVEY ACTION TAKEN AS APPROPRIATE. ALL CASH COLLECTED AND REPORTED IN FINAL DISB RETURNS. PORTION OF CURRENT SHIP STORE RECORDS DESTROYED OR MISSING. RECORDS KEEPER AND STORE OPERATOR RETURNED TO U.S. REQ ADVISE ACTION TO BE TAKEN FOR CLOSE OUT OF FINANCIAL ACCOUNTABILITY.

4. SUBSISTENCE: ALL PERISHABLE AND TWO NON-PERISHABLE STOREROOMS LOST. REMAINING ITEMS REMOVED FROM SHIP. NFI ITEMS BEING XFERRED TO NSD SUBIC BAY AND PIEDMONT. NFI ITEMS TO BE SURVEYED. SUBSISTENCE LEDGER DESTROYED. REQ ADVISE FINAL ACTION TO BE TAKEN TO CLOSE OUT ACCOUNT-ABILITY.

5. REPAIR PARTS: TWO REPAIR PARTS STOREROOMS (ORD AND MISC PARTS) LOST. APPROX 90 PERCENT OF ALL ONBOARD REPAIR PTS RECOVERED AND REMOVED WITH 80-90 PERCENT LOCATOR VALIDITY RETAINED. STORAGE AIDS BEING FABRICATED

130430Z JUN69/34

DECLASSIFIED

DECLASSIFIED

IN ORDER TO RETAIN LOCATOR SYSTEM AT WHICH TIME DISTRIBUTION TO BE MADE

PAGE 3 RUMHWOA9026 UNCLAS E F T O

IAN THEN CURRENT INSTRUCTIONS.

6. ELECTRONICS: 16978 PCS ELECTRONICS COMPONENTS AND 1475 PCS RADIAC EQUIP REMOVED AND TURNED OVER TO SRF SUBIC BAY FOR CORROSION CONTROL AND DETERMINATION OF CONDITION.

7. DASH: TWO DASH DRONES XFERRED TO PIEDMONT. SHIPBOARD EQUIPMENT REMOVED BY PIEDMONT WITH INVENTORY BEING TAKEN. SRF SUBIC BAY WITH ASSISTANCE OF DASH TECHRLPS WILL REMOVE REMAINING SHIPBOARD EQUIP.

8. SMALL ARMS: SMALL ARMS RECOVERED BY USS EVERETT F. LARSON WILL BE HELD BY NSD SUBIC BAY PENDING DISPOSITION INSTRUCTIONS.

9. ALL REMAINING EQUIPAGE ITEMS AND MISC LOOSE ITEMS OF VALUE REMOVED AND PLACED IN STORAGE PENDING INVENTORY AND DISPOSITION. FINAL SEARCH BEING CONDUCTED FOR ANY EQUIPAGE THAT MAY HAVE BEEN OVERLOOKED.

BT

#9026

NNNN#

DECLASSIFIED