

USNS GENERAL JOHN POPE (T-AP110)

DATE 25 FEB 67

REPAIR LIST REQUEST

SUBJECT RAДАР REPAIR

DATA 3 OM RADAR ROA MODEL N1A-75

LOCATION BRIDGE

CONDITION

QUANTITY/SIZE 1

RECOMMENDATION LOSS OF MAGNETRON CURRENT AND THYRATRON TUBE (5022)

DOES NOT TRIGGER WHEN RANGE IS SWITCHED FROM 2 MI TO 16 MI OR VICE VERSA
TROUBLE POSSIBLY IN TRIGGER CIRCUIT. POSSIBILITY RELAY K804 STICKING.

SIGNATURE

32K 11/14-75