

DEPARTMENT OF THE NAVY  
MILITARY SEA TRANSPORTATION SERVICE, PACIFIC AREA  
FORT MASON  
SAN FRANCISCO, CALIFORNIA

MSTSPAC 10160.1C  
P-4S2  
25 September 1962

MSTSPAC INSTRUCTION 10160.1C

From: Commander Military Sea Transportation Service, Pacific Area  
To: Distribution List

Subj: Shipboard chairs; replacement of

1. Purpose. To set forth the procedure for requisitioning shipboard chair replacements.

2. Cancellation. MSTSPAC Instruction 10160.1B is cancelled and superseded. \*

3. Information. A pool of renovated chairs is maintained at Naval Supply Center, Oakland for the replacement of ships' chairs requiring renovation. Chairs turned in during an in-port period will normally be replaced during the same in-port period. The following is a list of chairs maintained in the pool:

a. CHAIRS, NAVY TYPE I, with arms, padded back and 3" seat cushions, conforming with JAN-C-486 and MIL-C-903, Standard Stock No. H 2090-269-0983.

b. CHAIRS, NAVY TYPE II, without arms, padded back and 3" seat cushions, conforming with JAN-C-486 and MIL-C-903, Standard Stock No. H 2090-269-0984.

c. CHAIRS, NAVY TYPE III, lounge, adjustable back, 3" seat and back cushions, conforming with JAN-C-486 and MIL-C-903, Standard Stock No. H 2090-559-4658.

d. CHAIRS, NAVY TYPE IV, without arms, with padded back and 1" seat cushions, conforming with JAN-C-586 and MIL-C-903, Standard Stock No. H 2090-269-0981.

e. CHAIRS, USNS TRANSPORT TYPE, and/or TRI-WAY TYPE, without arms, with padded back and 1 1/2" seat cushions, Standard Stock No. H 2090-269-0981. \*

f. CHAIRS, USNS TRANSPORT TYPE, and/or TRI-WAY TYPE, with arms, padded back and 1 1/2" seat cushions, Standard Stock No. H 2090-269-0983. \*

4. Directive.

a. Shipboard chairs, similar to those maintained in the pool, requiring repair, shall be turned in to Building 122 Naval Supply Center, Oakland, with a covering "no charge" DOD Single Line Item Release (DD Form 1348-1) for the total number of chairs turned in and DOD Single Line Item requisition (DD Form 1348) for the total number of replacement chairs required. \*

MSTSPACINST 10160.1C  
25 September 1962

- \* The requisition and the invoice shall reference each other in the appropriate blocks. MSTS Fund Code "E7" which shall be shown on the requisition will be charged only for the cost of repairs to the chairs. The Naval Supply Center, Oakland will enter the unit prices on the requisition in accordance with present contract prices.
- \*
  - b. Chairs that are beyond economical repair shall be surveyed and disposed of in accordance with current disposal regulations. Chairs considered to be repairable shall be turned in to the chair pool at NSC, Oakland. These chairs will be inspected and a determination made if chairs are acceptable on an exchange basis from the pool.
  - c. Settees, non-standard lounges, transoms, high chairs, and cribs, are not included in the pool and requests for the repair of these items shall be processed through the COMSTSPACAREA Maintenance and Repair Office.

O. B. MURPHY  
Chief of Staff

DISTRIBUTION: (MSTSPACINST 5215.2C)  
SNDL 32Q, 41F, T-100 ... MSTSPACAREA activities only

Copy to:  
COMSTS  
COMSTSLANTAREA  
MSTSOHONO  
MSTSO SEATTLE

Authenticated:

  
H. MAUDSLEY  
Directives Control