

Housekeeping

Machine 2-11-2  
Rules 2-1-1, 2-1-2  
Stock Rooms 2-4-3  
General Hygiene 2-1-7  
Engine Spaces 2-16-22i.  
Warning Signs 2-1-6  
Hydraulic Systems 2-9-37  
Hydrocarbon Fuels 2-9-1 - 2-9-14  
Hydrocarbons 2-14-21  
Hygiene; General 2-1-7

I

Ignition; Causes of 2-9-8  
Illumination  
    (Housekeeping) 2-1-10  
    (Sewage and Water) 2-12-18  
    (Woodworking) 2-13-3c.  
Inerting & Pressing Up 2-8-49  
Injuries  
    Treatment 1-1-4j., 1-4-4  
    Reporting 1-3-2  
Insecticides 2-1-11  
Inspection & Maintenance  
    Electric 2-15-3  
Inspections 1-1-6  
Instructions  
    General 2-1-6a.  
    Machine Shop Area 2-11-5a.  
    Personnel 2-9-2  
    Steward Dept. 2-4-1j.  
Invitees; Injury to 1-3-2d(2)

J

Jacking Gear 2-16-1b.  
Jig 2-13-6c.  
Jointers 2-13-13  
Joints in Piping 2-9-21  
JP-4 Fuel  
    Characteristics of 2-9-39  
    Special Precautions 2-9-41  
    Toxicity 2-9-40

K

Ketones 2-14-18  
Kettle; Steam-Jacketed 2-4-6g.  
Knives; Storing 2-4-6a(3)

L

Labels; Information on 2-8-39e.  
Ladders 2-2-2c., 2-1-3i., 2-7-3  
    Cargo Hold 2-1-6c(1)  
    Extension 2-7-3e.  
    Prohibited 2-2-2c(7), 2-7-3b(4)  
    Painting 2-7-3a(2)  
    Step 2-7-3d.  
    Warning Signs 2-7-3b(4), 2-2-3a(4)  
Lamps; Naked 2-16-24a(1)(c)  
Lathes 2-11-9, 2-13-14  
Laundry 2-4-10  
Lead Poisoning 2-9-11  
Lead, Zinc, Beryllium 2-11-25  
Lifeboats 2-2-3m.  
Lifeboat Winch Sign 2-2-3m(3)  
Lifelines & Life Bouys 2-2-3f.  
    Safety Belts 2-8-10  
    Turnbuckles 2-2-2b(12)  
Lights  
    Minimum Levels 2-1-10d.  
    Naked Incandescent 2-16-24a(1)  
        and 2-9-19a.  
    Vapor Globes 2-9-19b.  
    Vicinity of Gasoline 2-9-32  
Lines, Heaving 2-2-3a(8)  
    General 2-2-3a.  
Locking Panels 2-15-1c(7)  
Lockers 2-1-13h.  
Luminous Compound, Radioactive  
    2-11-26

M

Machine Shops 2-11-1  
Machinery; Office 2-1-3f.

Machinery

Operating 2-11-7  
Preliminary Precautions 2-11-5  
Repairing 2-11-6  
Magazines 2-18-2g.  
Magnesium Alloys 2-11-24  
Manhole Plates 2-16-20d.  
Manifolds; Portable 2-8-19  
Mast; Aloft 2-2-3a(4)  
Masts; Grounding 2-15-7c.  
Matching Machines 2-13-14  
Material Stacking 2-1-19  
Materials Handling 2-1-14  
Mechanical, General 2-1-22  
Handling 2-1-17  
Medical Facilities 2-3-1  
Medical Treatment 1-4-4, 1-4-6  
Outside CONUS 1-4-8  
Meetings; Safety  
Shipboard 1-1-5c(2)  
Shore 1-1-5b.  
Mess 2-4-7  
Message Notification Forms 1-2-8  
Metal  
Cleaning & Coating 2-11-20  
Molten (Handling) 2-11-23  
Methyl Metacrylate Monomer 2-14-22a.  
Milling Machines 2-11-10  
Mills; Boring 2-11-13  
Mirrors 2-1-3,1.  
Molding (Woodworking) 2-13-14  
Mortising Machines 2-13-16  
Motor Vehicle Reports 1-3-2g.  
MSTS Vessels (Welding) 2-8-43

N

Nets; Safety 2-2-2a(2), 2-16-21c.  
and 2-2-2b(7)  
Next of Kin  
Letter to 1-2-9  
Notification of 1-2-6  
Night Handling of Fuel 2-9-33  
Nitroparaffins 2-14-20  
Nylon Rope 2-2-3,1.

O

Office & Lounge Safety 2-1-3  
Oil Level Indicators 2-16-22f.  
Outlets; Electrical 2-15-1d.  
Ordnance  
General 2-18-1  
Safety Precautions 2-18-3  
Explosive Safety 2-18-4  
Oxygen 2-9-65  
Oxygen Cylinders 2-8-17  
Handling 2-3-1c.

P

Paint  
Removal with Torch 2-14-4  
Storage 2-14-3  
Painting  
Area 2-14-6  
Cylinders 2-9-50  
Spray 2-14-8  
Paint Lockers  
Metal Lined 2-14-3  
No Smoking 2-1-6b.  
Passenger Safety 2-2-1e.  
Personal Equipment 2-1-15, 2-2-1d.  
Recreational 2-15-8b.  
Protective 2-15-10a(6)  
Receptacles 2-15-7b(3)  
Physical Examination 2-1-8a.  
Pick-Axes 2-5-12  
Pictures & Bulletin Boards 2-1-3k.  
Pipe  
Cutters 2-5-9  
Handling 2-12-6  
Pipe Lines 2-12-13  
Piping  
Joints in 2-9-21  
Systems, Identification 2-12-11  
Systems Repair 2-12-7  
Work, New 2-12-12  
Work on 2-12-2  
Planers, Hand 2-13-15  
Planing (Woodworking) 2-13-14

Planers; Shapers and 2-11-11  
Plugs & Receptacles 2-15-7b.  
Poisonous Substances 2-14-5  
Portable Drums (Gasoline) 2-9-18b.  
Portable Electric Equip. 2-15-8  
Cables 2-15-8a.  
Posting Safety Precautions  
2-4-1j., 2-11-5a.  
Posters & Signs 2-1-6  
Potato Peeler 2-4-6c.  
Power Boats (Fire) 2-2-6  
Presses; Drill 2-11-12  
Pressing Up 2-8-49  
Pressure Cooker 2-4-6h.  
Propeller 2-16-10, 2-2-3j.  
Property Damage Reports 1-3-2d.  
Pumps 2-16-8  
Reciprocating 2-16-9  
Rotary 2-16-10  
Punches 2-5-5  
Push Block 2-13-6b.  
Push Stick 2-13-6a.

R

Radiation Hazards  
Radio Frequency 2-15-16  
X-ray 2-15-17  
Radio Frequency Circuits 2-15-15a.  
Radio Frequency Hazards to Combustible  
Materials 2-15-16b.  
Electrically Actuated Ordnance  
2-15-16c.  
Personnel 2-15-16d.  
Radioactive  
Luminous Compound 2-11-26  
Materials 2-15-20  
Radiological Safety 2-17-1  
Rails 2-2-3g.  
Guard Rails 2-11-4d.  
Handrails 2-1-6c(1)  
Rasps; Files 2-5-7  
Receiving Room 2-4-4  
Receptacles 2-15-7b.  
Reefer Boxes 2-4-5e.  
Daily Check 2-4-5e(2)

Refrigerant Cylinders 2-10-6c.  
Refrigeration  
Personnel Protection 2-10-2  
Plants, Safety in 2-10-6  
Qualified Workers 2-10-1  
Refrigerators; Walk-in 2-10-7  
Refrigerants 2-10-3  
Detection of Leaks 2-10-4  
Care of Cylinders 2-10-5  
Refuse Container 2-9-8h.  
Regulations 1-1-4k.  
Regulators 2-8-18  
Reimbursement (Medical) 1-4-7  
Reporting Procedures  
Accident 1-3-2  
Message 1-2-5  
Reporting Requirements 1-2-4  
Resaws  
Band 2-13-10b.  
Circular 2-13-9h.  
Research Projects 2-18-4  
Respirators & Air Masks 2-8-9  
Respirators; Use of 2-1-11b.  
Responsibilities; Organization  
of 1-1-5  
Ripsaws; Hand-fed 2-13-9c.  
Rodent Control 2-1-12  
Rope  
Fiber 2-6-6  
Wire, and Slings 2-6-7  
Nylon 2-2-3,1.  
Rubber Gloves 2-15-1b(2)  
Rubber Matting 2-15-1c.

S

Safety  
Deck 2-2-3  
Steward 2-4-1 - 2-4-10  
Personnel 2-2-1  
Deck Safety Check List 1-1-9a.  
Engine " " " 1-1-9b.  
Steward " " " 1-1-9c.  
Safety Belts 2-8-10  
Safety Cap Backed 2-9-49d.  
Unbacked 2-9-49c.

20 Mar 1968

Safety Check List 1-1-9  
 Safety Notations; Definitions 2-8-40  
 Safety Switch (Gasoline) 2-9-30d.  
 Safety Treads (Nonslip) 2-1-2z.  
 Sanding Machines 2-13-17  
 Saws 2-5-11  
   Band 2-11-16, 2-13-10  
   Circular 2-11-15, 2-13-9  
   Circular, Portable 2-5-23  
   Metal, General 2-11-14  
 Screwdrivers 2-5-13  
 Scuba Diving 2-2-7  
 Scullery 2-4-8  
 Sea Valves, Inspection 2-12-9  
 Seamanship  
   General for Personnel 2-2-1  
   General in Work Areas 2-2-2  
 Sewing Machines 2-2-3h.  
 Shafting 2-16-16  
 Shapers 2-13-11, 2-11-11  
 Sheaves and Drums 2-6-8  
 Sheet Metal Work 2-11-17  
 Ship Fitting 2-6-14  
 Shipyard Repair Periods 2-16-21  
 Shock; Protection From 2-8-24  
 Shops; Machine 2-11-1  
 Shovels & Pick-Axes 2-5-12  
 Showers 2-1-13f.  
   Emergency Flood 2-11-20d.  
 Sight Conservation Program 1-1-6d(2)  
 Sight Gauges 2-16-22f.  
 Signs  
   Battery Room 2-15-10a(5)  
   "Caution, Open Door Slowly"  
     2-1-2bb(6)  
   Electronic Warning 2-15-14 2-15-18  
   Explosive Vapors 2-15-14  
   "No Smoking" 2-1-6b., 2-1-2cc.  
   (Sewage & Water) 2-12-19  
   Smokestack Gases 2-2-3k(4)  
   Warning 2-1-6  
 Skin  
   Burns (Gasoline) 2-9-46  
   Injury to 2-9-12  
 Slings; Wire Rope and 2-6-7  
 Small Arms 2-18-3a.  
 Smokeless Powder 2-18-2d.  
 Smokestacks 2-2-3k.  
   Brass Warning Plate 2-2-3k(4)  
 Smoking  
   In Bed 2-1-2cc., 2-2-3,1.  
   On Vessels 2-2-4b(14)  
   Signs 2-4-3e., 2-14-6b.  
 Smoking & Naked Lights 2-9-19  
 Soap 2-1-13e.  
 Soapsuds; Use of in Detecting  
   Leaks 2-10-4a.  
 Sodium Hydroxide 2-14-22b.  
 Sodium Hypochlorite 2-12-21b.  
 Solvents  
   Hand Protection 2-14-7d.  
   Disposal of 2-14-23  
   Storage 2-14-12  
   Miscellaneous 2-14-22  
 Space Classification 2-8-31  
 Spark-Proof Equip. 2-9-20  
 Special Projects 2-18-4  
 Spontaneous Ignition 2-9-8h.  
 Spray Painting 2-14-8  
 Spring-Loaded Device 2-9-49b.  
 Sprockets 2-16-14  
 Stack 2-2-3k.  
 Stages, General 2-7-4  
 Stairs 2-1-2aa.  
 Stairways; Marking 2-1-6c(1)  
 Static Electricity 2-9-8e.  
 Steam Engines 2-16-5  
 Steam; Using Live 2-9-38  
 Steam Table 2-4-7a.  
 Steels; Whetstones and 2-5-15  
 Sticking (Woodworking) 2-13-14  
 Stock Room 2-4-3  
 Storage  
   Buildings (Fuel) 2-9-4  
   Chemical 2-12-21  
   Weather Deck 2-9-56  
 Storage Batteries  
   Charging 2-15-10c.  
   Ventilation of 2-15-10b.  
 Store; Ships 2-4-2  
 Storm Rails 2-2-3g.  
 Stowage; General 2-9-53  
   Compressed Gases 2-9-55  
   Good Housekeeping 2-1-2,1.

20 Mar 1968

Stowage Plans 2-2-5h.  
 Stowing Portable Containers 2-9-23  
 Strainers 2-16-4  
 Suspect Materials 2-2-5j.  
 Suspended Stage Platforms 2-7-2  
 Swimming From Ship 2-2-1c.  
 Switches & Circuit Breakers 2-15-11  
 Switchboards 2-15-1c(8)  
 Switches; Securing 2-15-6

I

Tags 2-15-8b.  
 Tagging Switches 2-15-6b.  
 Tanks  
   Capacity 2-9-37a.  
   Empty 2-9-37b.  
   Entering 2-9-14  
   Filling 2-9-34  
   Safety belt, Lifeline 2-12-3c.  
 Tenoning Machines 2-13-12  
 Tetraethyl Lead 2-9-11a.  
 Threading Dies 2-5-14  
 Tools  
   General (Piping) 2-12-4  
   Hand 2-5-2  
   Pneumatic 2-5-20  
   Portable Power 2-5-18  
 Tool Rest 2-11-18c(9)  
 Torch 2-8-20  
 Toxic Hazard (Fuel) 2-9-10  
 Toxic Substances 2-14-5  
 Tractor-Trailer Trains 2-1-24  
 Training; On the Job 1-1-6c.  
 Transformers; Working on 2-15-12  
 Traps & Aircaps 2-12-12b.  
 Traps; Inspection of 2-12-10  
 Trash Cans 2-9-8h.  
 Treatment  
   Authorizing 1-4-5  
   Covered Medical 1-4-6  
   Medical 1-4-4  
   Outside CONUS 1-4-6  
 Turnbuckles 2-2-2b(12)  
 Turpentine 2-14-22c.  
 Typewriters 2-1-3e.

U

Underwater Operations 2-2-7  
 Uprights 2-16-17a.

V

Valve Safety Devices 2-9-49  
 Valves  
   Cylinder 2-8-15  
   Quick Closing 2-16-22j.  
   Relief 2-16-2  
   Repairing 2-9-51  
   Sea, Inspection of 2-12-9  
   Stems 2-12-8  
 Vapor  
   Behavior of Gasoline 2-9-17  
   Explosion Proof Fixtures  
     2-15-2d.  
   Fuel Oil 2-9-6  
   Naked Lamps 2-16-24a(1)(c)  
 Vapors and Gases 2-14-11  
 Vegetable Chopper 2-4-6b.  
 Vehicles; Transporting 2-2-5k.  
 Vending Machines 2-4-7e.  
 Ventilation  
   (Gasoline) 2-9-18  
   General Shop or Space 2-8-34  
   Hazards 2-8-28  
   (Hygiene) 2-1-9  
   Individual Devices 2-8-33  
   Positive Not Required 2-8-32  
   Required 2-8-29  
   Variables 2-8-30  
 Ventilating; Portable 2-12-17  
 Venting Containers 2-8-49d.  
 Vessels; MSTs (Welding) 2-8-43  
 Voltage  
   Antennas Warning Sign 2-15-14  
   High Voltage Signs 2-15-1c(1)

W

Warning of Hot Metal 2-8-12  
 Warning Signs 2-1-6, 2-15-14

COMSTSINST 5100.17 CH-1

20 Mar 1968

Warnings to Personnel 2-15-5

Wash & Locker Rooms 2-1-13

Water Hammer 2-9-37d.

Water Treatment Plants 2-12-20

Weight Handling & Construction

General Definition 2-6-1

Operating 2-6-3

Principal Causes of Accidents

2-6-2

Riggers Rules 2-6-5

Signals 2-6-4

Welding

Apparatus 2-8-5

Clothing 2-8-7

Communication 2-8-11

Dangers 2-8-4

Eye Protection 2-8-8

Fire Extinguishing 2-8-6

Indoor 2-8-35

Location 2-8-3

Terms Used 2-8-2, 2-8-38

Scope 2-8-1

Shipboard 2-8-22

Whetstones 2-5-15

Wiring 2-11-8

No Splices 2-15-8a.

Woodworking 2-13-1 - 2-13-18

Working Aisles 2-1-20

Wrecking Bars 2-5-16

Wrenches 2-5-17

Pipe 2-12-5

Power 2-5-22

X

X-ray Radiation Hazards From  
High Voltage Electronic  
Equipment 2-15-17

Z

Zinc, Lead, Beryllium 2-11-25

**RECEIVED**

**APR 12 1968**

**USNS POPE T-AP110**