

16. Statement of immediate supervisor:

Mr. Kemmer was assigned to remove the return steam manifold from the Makeup Compressor. In the process of loosening the union type connections, he placed his foot on top of the floor plate boundary bar as a brace, as per his statement in item #8.