

27		OAKLAND, CALIFORNIA 94625		9/22/69
SHIP		USNS GEN. JOHN POPE (T-AP 110)		CONTRACTOR
				TRIPLE "A"
SPECIFICATION NO.		SPECIFIC ITEM NO.		ADDENDUM NO.
70-11		304		1
ITEM NO.				
BOILERS REPAIR:				
DESCRIPTION OF WORK				

1. Drill and tap out broken bolt $\frac{1}{2}$ X $2\frac{1}{2}$ and replace same on center register #1 Boiler.
2. Replace broken $\frac{1}{2}$ X 3" nipple on steam atomizer piping on center register #1 Boiler.
3. Weld crack on top of water column #2 Boiler (broken weld.)

RECEIVED

OCT 20 1969

USNS POPE T-AP110