

SHIP'S FILE

DEPARTMENT OF THE NAVY
MSTSO YOK M & R DIV.

SPECIFICATION NO: 54-4496
VESSEL: USNS GEN JOHN POPE


DATE: 23 June 1954
ASSIGNMENT: MSTSPACAREA

DESCRIPTION OF WORK: Boiler Economizer; Repairs to
SYMBOL NO: Item 1 / Code 1213 / T-AP 110 / S 51 / Boiler

Furnish labor to weld two(2) economizer tubes to header and secure from leaks on #4 Boiler in after engine room. Conduct hydrostatically test to 450 psi. assisting ship's crew on presence of ABS inspector. All work to be completed to satisfaction of MSTS inspector and ship's chief engineer. Ship furnish welding equipments and replacing parts.

W. W. CHRISTENSEN
Inspector

APPROVED:


H. E. SOMMERS, LT. USN
M & R Officer
Yokohama, Japan.

Page - 1 - of - 1 - Page.