

INFORMAL SANITATION AND HABITABILITY INSPECTION
USNS WEIGEL (T-AP 119)
30 April 1969

1. (D) 03-91-1-L CH Radio Officer S.R.
a. No shower curtain.
b. Bleeding rust around commode.
c. Verdigris pipes.
d. No light bulb overhead light.
e. Dirty electric fan.

(R) General clean up.

2. (D) 02-87-1-Q Captain Pantry.
a. No thermometer in refrigerator.

(R) Provide thermometer.

3. (D) 02-87-2-L First Officer S.R.
a. Mattress cover dirty.
b. No shower curtain.
c. Head dirty.
d. Light bulb out above sink.

(R) General clean up.

4. (D) 02-97-1-L 2nd Officer S.R.
a. No shower curtain.
b. Dirty mattress cover.
c. Head dirty.
d. No overhead light.

5. (D) 01-81-3-L Second Assistant Engineer.
a. No shower curtain.
b. Light bulb missing overhead.
c. Mattress cover dirty.
d. No covers on pillows.
e. Bleeding rust around commode.
f. Head dirty.

6. Officers Country: General housekeeping recommended in this area. The above condition exist in all berthing areas. It is noted that a majority of the pipes are not stenciled to indicate the liquid carried including arrows to indicate the direction of flow.

Enclosure (1)

7. (D) 01-109-0-Q Pharmacy. No thermometer in refrigerator.
(R) Provide thermometer.
8. (D) Medical Record Office. Desk top and typewriter well broken.
(R) Repair.
9. (D) Stokes Stretchers. No blankets and handling lines.
(R) Provide.
10. (D) Diet Kitchen. No thermometer in refrigerator.
(R) Provide thermometer.
11. (D) General Ward. 25 mattresses missing. 4 bunks missing.
(R) Replace.
12. (D) X-Ray Department. No X-Ray machine.
(R) Install.
13. (D) Medical Ward. Holes in weather deck door.
(R) Repair.
14. (D) Surgical Ward. Rust around port holes.
(R) Chip and Paint.
15. (D) Scullery Troop. Missing grill top.
(R) Replace.
16. (D) Starboard Troop Cafeteria. Severe rust on pans.
(R) Replace.

GENERAL COMMENTS

A complete IOL is required to keep the medical department in operational status. General housecleaning required in all berthing spaces; otherwise, the material condition of the ship as far as sanitation and habitability is considered excellent. Pest control services recommended before taking stores aboard and a de-ratization certificate renewed.