

AT/PASSAGE FROM		TO	
Pier 2, Berth 30 Hunters Point		San Francisco California	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
(H) 8		8 Dec. 1968	Sunday.
TIME	REMARKS		
	0000-0800		
	Moored As Before		
	On Watch: Mr. Barrett ^{R/O} , Mr. Daigle ^{R/E} , Dion ^{R/O} , Fruta ^{R/O} & Celada ^{R/O} Fruta ^{R/O} Making Detex Rounds On The Weigel & Celada On The Pope. Rat Guards & Lines All In Apparent Good Order.		
0000	Flw Reports All Secure. ^{R/O} Made Rounds Of Weigel.		
0100	Flw Reports All Secure.		
0200	Flw Reports All Secure. ^{R/O} Made Rounds Of Weigel.		
0300	Flw Reports All Secure.		
0400	Flw Reports All Secure. ^{R/O} Made Rounds Of Weigel.		
0500	Flw Reports All Secure.		
0600	Flw Reports All Secure. ^{R/O} Made Rounds Of Weigel.		
0630	Relieved Of Gangway Duties. E.A. Dim.		
0630	ASSUMED THE WATCH.		
	0800-1400		
0800	MR BARRETT ^{R/O} = MR DAIGLE ^{R/E} = CAMERON ^{R/O} = ORR ^{R/O} = FLYNN ^{R/O} All SECURE ON BOTH SHIPS. ^{R/O} MAKING CLOCK ROUNDS AND TAKING SOUNDINGS.		
0900	MR DAIGLE MAKING ROUNDS OF WEIGEL. All SECURE ON BOTH SHIPS.		
1000	All SECURE.		
1045	MR BRIDY ^{R/O} ABOARD. MR CHRISTENSEN ^{R/O} ABOARD.		
1050	MR BARRETT ^{R/O} = MR DAIGLE ^{R/E} ASHORE.		
1100	^{R/O} MADE INSPECTION OF BOTH POPE & WEIGEL. All SECURE.		
1200	All SECURE ON BOTH SHIPS.		
1300	^{R/O} = ^{R/E} MAKING ROUNDS OF BOTH SHIPS. All SECURE.		
1400	All SECURE.		
1420	WATCH RELIEVED BY BLUE ^{R/O} Wong J. J. ^{R/O}		
	JACKSON ^{R/O} - DANACH ^{R/O} (1600-2400) MR CHRISTENSEN ^{R/O} - MR BRIDY ^{R/O}		
1430	Assumed The Watch, All In Order.		
1500	JACKSON/DANACH TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE POPE AND WEIGEL. R/O AND R/E INSPECTING WEIGEL.		
1600	All In Order. R/E TIGHTENED UP LATCH ON STEAM LINE TO THE POPE.		
1700	R/O AND R/E INSPECTING WEIGEL, All In Order.		
1800	All In Order.		
1900	R/O AND R/E INSPECTING WEIGEL, All In Order.		
1935	PERKINS, L.M. (145-10) CALLED IN STATING HE HAS THE FLY AND WILL NOT BE IN FOR WORK TOMORROW (08-1600, 9000 AUG) AS HE IS GOING TO MARINE HOSP.		
2000	All In Order.		
2040	R/O AND R/E INSPECTING WEIGEL, All In Order.		
2100	All In Order.		
2200	R/O AND R/E INSPECTING WEIGEL, All In Order.		
2230	WATCH RELIEVED BY SERRAZ ^{R/O} SERRAZ ^{R/O}		

USNS GEN. John Pope

AT/PASSAGE FROM

BERTH 30 PIER 2 HUNTERS POINT
ZONE DESCRIPTION + 8

TO

San Francisco Calif

DATE (Day, month, year)

9 DEC-68

DAY OF WEEK

Monday

TIME

REMARKS

0000-0800

2300 ON Watch: MR. BARRETT $\frac{R}{O}$ MR. DAIGLE $\frac{R}{O}$
FRUTAZ $\frac{FW}{FW}$ CELADA $\frac{FW}{FW}$ TIPTON $\frac{FW}{FW}$
CELADA $\frac{FW}{FW}$ made his Round on the Pope
every hour and Report to the bridge.
TIPTON $\frac{FW}{FW}$ on the Weigel made his Round
every hour and Report to the Pope's
Gangway.

2400 ALL Lines and Rat Guard in both ship are in
Good Order.

0000 MR. BARRETT $\frac{R}{O}$ and MR. DAIGLE $\frac{R}{O}$ made their
Round on both ship.

0100 ALL Secure.

0200 ALL Secure.

0300 MR. BARRETT $\frac{R}{O}$ made his Round both ship.

0400 ALL Secure.

0500 ALL Lines and Rat Guard are in good order.

0600 MR. BARRETT $\frac{R}{O}$ and MR. DAIGLE $\frac{R}{O}$ made their
Round on the Pope.

0630 Watch Relieved by Goe. ORR

0650 $\frac{1}{2}$ ABOARD --- $\frac{R}{O}$ + $\frac{R}{O}$ ASHORE 0655 CH. ENG. ABOARD

0700 MR. GOCKLEY 1ST ASSISTANT REPORTED ABOARD

0720 CAPTAIN PETROSKY ABOARD. DECK LIGHTS TURNED OFF

MR. COLLINGS $\frac{R}{O}$ (0800-1600) ORR $\frac{R}{O}$ GANGWAY DABALOS $\frac{FW}{FW}$

0800 MOORED AS BEFORE. LINES, GANGWAY, + RATE GUARDS ALL SECURE.

0805 TEST OF ALARM SYSTEMS — O.K. P.A. SYSTEM KAPUT. 0815 SHORE STEAM SHUT DOWN

1030 SHORE STEAM ON — P.A. SYSTEM A-O.K. NOW. DABALOS MAKING DETEX ROUNDS.

1125 "CHIC" REHILL MSTU ABOARD 1250 ASHORE

1255 SMALL CRAFT WARNING --- SOUTH WINDS 14-20 MPH GUSTS TO 26 BEGINNING 1300
INCREASING TO 15-25 GUSTS TO 30 AT 1600 --- RELAYED FROM BASE BY USNS (RDATAN.

1325 PURSER TO POST OFFICE 1350 RETURNS

1430 WATCH RELIEVED BY BLUE $\frac{R}{O}$ Geo. Orr

MOULTON $\frac{R}{O}$ CAMERON $\frac{R}{O}$ (1600-2400) MR. CHRISTENSEN $\frac{R}{O}$ MR. BRIDGES $\frac{R}{O}$

1430 ASSUMED THE WATCH, ALL IN ORDER.

1500 CAMERON/MOULTON TAKING SOUNDINGS AND MAKING DETEX ROUNDS
ABOARD THE POPE AND WEIGEL. $\frac{R}{O}$ AND $\frac{R}{O}$ INSPECTING WEIGEL.

1510 MASTER ASHORE.

1600 ALL IN ORDER.

1700 $\frac{R}{O}$ AND $\frac{R}{O}$ INSPECTING THE WEIGEL, ALL IN ORDER.

1800 ALL IN ORDER.

1900 $\frac{R}{O}$ AND $\frac{R}{O}$ INSPECTING WEIGEL, ALL IN ORDER.

2000 ALL IN ORDER.

2040 $\frac{R}{O}$ AND $\frac{R}{O}$ INSPECTING WEIGEL, ALL IN ORDER.

2100 ALL IN ORDER.

2200 $\frac{R}{O}$ AND $\frac{R}{O}$ INSPECTING WEIGEL, ALL IN ORDER.

2330 WATCH RELIEVED BY FRUTAZ $\frac{R}{O}$.

USNS GEN John Pope

AT/PASSAGE FROM	TO	
BORTH 30 Pier 2 HUNTERS POINT	San Francisco California	
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
1 8	10 Dec, -68	Tuesday

TIME	REMARKS
	0000 - 0800
2300	On Watch: MR. BARRETT R/O MR. Daigle R/E FRUTAZ F/W Dabalos F/W Tipton F/W Dabalos F/W on the Pope made his round every hour and Report to the bridge. Tipton F/W on the Weigel made his round every hour and Report to the Pape's Gangway.
2400	All Lines and Rat Guard are in good order.
0000	MR. BARRETT R/O and MR. Daigle made their Round in both ship the Pope and the Weigel.
0100	All secure. 0200 All secure.
0300	MR. BARRETT R/O made his round.
0400	All secure.
0500	MR. BARRETT R/O MR. Daigle R/E made their round in both ship.
0600	All Lines and Rat Guard are in good order.
0630	Watch Relieved by POE. ORR Chris Murphy
0645	R/O + CH. ENG. ABOARD — R/O + R/E ASHORE
0715	CAPTAIN PETROSKY ABOARD. SUNRISE. DECK LIGHTS OFF.
0730	TEST OF FIRE ALARM SYSTEM ---- O.K. MR. COLLINGE R/O (0800-1600) ORR R/B GANGWAY - CAPELL F/W
0800	MOORED AS BEFORE. LINES, GANGWAY, AND RATEGUARDS ALL SECURE
0915	SAFETY AND MORAL LEADERSHIP MEETING FOR DECK DEPT. — R/O PRESIDING — 10 MEN IN ATTENDANCE — ADJOURNED AT 0945.
1100	ALL SECURE. F/W MAKING REGULAR ROUNDS
1300	ROUTINE WATCH. ALL IN APPARENT GOOD ORDER
1430	WATCH RELIEVED BY CHESTER BLUE R/B Geo. Orr CAMERON R/B. MOVILLION R/B (1600-2400) MR. CHRISTIANSEN R/O. MR. WILSON R/E
1430	ASSUMED THE WATCH, ALL IN ORDER.
1500	CAMERON/MOVILLION TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE POPE AND WEIGEL. R/O AND R/E INSPECTING WEIGEL.
1515	MASTER ASHORE.
1600	All In Order.
1700	R/O AND R/E INSPECTING WEIGEL, All In Order.
1800	All In Order.
1830	STAFF DUTY OFFICER CALLED AUSTING OF SMALL CRAFT WARNINGS (9 HOUR PERIOD AS OF 1600 LOCAL - WESTERLY WINDS 20-30 MPH, GUSTS TO 40 - SEAS, MODERATE)
1900	R/O AND R/E INSPECTING THE WEIGEL, All In Order.
2000	All In Order.
2040	R/O AND R/E INSPECTING THE WEIGEL, All In Order.
2100	All In Order.
2200	R/O AND R/E INSPECTING THE WEIGEL, All In Order.
2230	Watch Relieved By Dion R/B.

AT/PASSAGE FROM

ZONE DESCRIPTION

Pier 2 Berth 30 Hunters Point

(+)8

TO

San Francisco, California

DATE (Day, month, year)

DAY OF WEEK

Wednesday 11 Dec '68 Wednesday

TIME	REMARKS
	0000-0800
	Moored As Before.
	On Watch: Mr. Barrett P/O, Mr. Daigle P/E, Dion P/W, Tipton & Dabalos P/W, Tipton Making Detex Rounds On The Weigel & Dabalos On The Pope. Rat Guards + Lines All In Apparent Good Order.
0000	Flw Reported All Secure. No Made Rounds Of The Weigel.
0100	Flw Reported All Secure.
0200	Flw Reported All Secure. No Made Rounds Of The Weigel.
0300	Flw Reported All Secure.
0400	Flw Reported All Secure. No Made Rounds Of The Weigel.
0500	Flw Reported All Secure.
0600	Flw Reported All Secure. No Made Rounds Of The Weigel.
0630	Relieved Of Gangway Duties. E. A. Dim.
	0800-1600
	Moored as before Mr. Cockling P/O Flynn P/B AT gangway Capell Flw
0700	Captain Petrosky aboard
07300	Kidde Fire & Smoke Detector, Test, both in good working condition
0900	Capell Flw making clock rounds on Gen Weigel & Gen Pope, and reporting all secure
1315	Parser Mr. Smith to Post Office
1430	Relieved by Blue P/B Paul H. Flynn
	DAVACA P/B · MOVILLON P/B (1600-2400) MR. CHRISTENSEN P/O · MR. WILSON P/E
1430	Assumed The Watch, All In Order.
1500	DAVACA, MOVILLON TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE POPE AND WEIGEL. P/O AND P/E INSPECTING WATCH.
1505	MASTER ASKED.
1600	All In Order.
1700	P/O AND P/E INSPECTING WEIGEL, All In Order.
1800	All In Order.
1900	P/O AND P/E INSPECTING WEIGEL, All In Order.
2000	All In Order.
2040	P/O AND P/E INSPECTING WEIGEL, All In Order.
2100	All In Order.
2200	P/O AND P/E INSPECTING WEIGEL, All In Order.
2230	WATCH RELIEVED BY DION P/B

AT/PASSAGE FROM	TO
Pier 2 Berth 30 Hunters Point	San Francisco, California.
ZONE DESCRIPTION	DATE (Day, month, year)
(+) 8	12 Dec '68
	DAY OF WEEK
	Thursday

TIME	REMARKS
	0000-0800
	Moored As Before.
	On Watch: Mr Barrett R/O, Mr Daigle R/E, Dixon F/W, Celada + Tipton F/W
	Tipton Making Detex Rounds On The Weigel + Celada On The Pope.
	Rat Guards + Lines All In Apparent Good Order.
0000	F/W Reported All Secure. R/O Made Rounds Of Weigel.
0100	F/W Reported All Secure.
0200	F/W Reported All Secure. R/O Made Rounds Of Weigel.
0300	F/W Reported All Secure.
0400	F/W Reported All Secure. R/O Made Rounds Of Weigel.
0500	F/W Reported All Secure.
0600	F/W Reported All Secure. R/O Made Rounds Of Weigel.
0630	Relieved Of Gangway Duties.
	C. A. Dim.
	0800 - 1600
	Moored as before, On Watch Mr Collinge R/O
	Flynn R/B AT gangway Capell F/W
0715	Master Aboard
0800	Kiddie Fire Alarm + Smoke Detector bell
	Alarm Test, both in good working condition
0930	Captain Petrovsky ashore
1130	Capell F/W making clock rounds on Gen Weigel
	av Gen Pope and reporting all secure
1435	Watch Relieved by Dabalos R/B Paul H. Flynn
	1600 - 2400
1500	Ships moored as before - Mr Christen R/O - Mr Shelton R/E - O.
	Dabalos R/B G-W Davaco F/W on the Weigel - Novillion F/W
	on the Gen Pope. Both fire watch making rounds with
	Detex Station Clock in both ships.
1450	Capt. Petrovsky Master of the ^{ship} ashore
1510	R/O inspection made on the Gen. Weigel all in good order
1600	fire watch made rounds in both ships with Detex Station Clock
1700	R/O inspection made on Gen. Weigel all well about the ship
	fire watch in both ships made rounds with Detex Station Clock
1730	R/E-O inspection made on the Gen. Weigel's Engine Rooms
1800	fire watch in both ships made rounds with Detex Station Clock
1900	R/O made inspection on Gen. Weigel all in good order
	fire watch made rounds in both ships with Detex Station Clock
2000	fire watch made rounds in both ships with Detex Station Clock
2040	R/O inspection made on the Gen. Weigel fore + aft all lines
	and rat guards all in good order.
2100	fire watch in both ships made rounds with Detex Station Clock
2140	R/E-O inspection made on Gen. Weigel in Engine Rooms
2200	R/O inspection made on the Gen. Weigel all in good order
	fire watch made rounds in both ships with Detex Station Clock
	Watch relieved by Dixon.
	Dabalos R/B

AT/PASSAGE FROM		TO	
Pier 2 Berth 30 Hunters Point		San Francisco California	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
(+) 8		13 Dec. 1968	Friday.
TIME	REMARKS		
	0000-0800		
	Moored As Before		
	On Watch: Mr. Barrett ^{PO} , Mr. Daigle ^{PE} , Dion ^{FW} , Celada & Tipton ^{FW} . Tipton Making Detex Rounds On The Weigel & Celada On The Pope. Rat Guards & Lines All In Apparent Good Order.		
0000	FW Reported All Secure. ^{PO} Made Rounds Of Weigel.		
0100	FW Reported All Secure		
0200	FW Reported All Secure. ^{PO} Made Rounds Of Weigel.		
0300	FW Reported All Secure.		
0400	FW Reported All Secure ^{PO} Made Rounds Of Weigel.		
0500	FW Reported All Secure.		
0600	FW Reported All Secure. ^{PO} Made Rounds Of Weigel.		
0630	Relieved Of Gangway Duties. E. A. Orr		
	0800-1600		
	Moored as before Mr Collinge ^{PO} , Flynn ^{A/B} AT GANGWAY, FRUTAZ ^{FW}		
0715	CAPTAIN PETROSKY ABOARD		
0800	FRUTAZ ^{FW} making clock rounds on Gen. Weigel, AN reporting all secure		
1130	Pay day S & O.		
1230	SMALL CRAFT WARNING		
1400	GANGWAY, all in good order		
1445	Watch relieved by Mouvillon ^{A/B} Paul H. Flynn		
	MR. CHRISTENSEN ^{PO} (1600 - 2400) ORR ^{A/B} GANGWAY DAVACOL ^{FW} WEIGEL MR. WILSON ^{BE} MOUVILLON ^{FW} POPE		
1600	MOORED AS BEFORE. LINES, GANGWAY, & RATE GUARDS ALL SECURE.		
1700	^{PO} MADE ROUTINE INSPECTION OF GEN. WEIGEL		
1730	SMALL CRAFT WARNING & STORM WARNINGS --- SO. WINDS 40-60 M.P.H.		
1800	^{BE} MADE INSPECTION GEN. WEIGEL - ALL SECURE		
1900	^{PO} MADE INSPECTION GEN. WEIGEL - ALL SECURE		
2000	ALL SECURE		
2040	^{PO} & ^{BE} MADE INSPECTION OF WEIGEL		
2100	ROUTINE WATCH - ^{FW} MAKING REGULAR ROUNDS		
2200	^{PO} MADE INSPECTION OF WEIGEL		
2230	WATCH RELIEVED BY DION ^{PO} Ler. Orr		

AT/PASSAGE FROM		TO	
Pier 2 Berth 30 Hunters Point, S		San Francisco California	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
(+) 8		14 Dec. 1968	Saturday
TIME	REMARKS		
	0000-0800		
	Moored As Before.		
	on watch: Mr. Barrett ^{P/O} , Mr. Daigle ^{P/E} , Dion ^{G/W} , Celada & Frutaz ^{Flw} Frutaz Making Detex Rounds On The Weigel + Celada On The Pope. Bat Guards + Lines All In Apparent Good Order.		
0000	Flw Reported All Secure. ^{P/O} Made Rounds Of Weigel.		
0100	Flw Reported All Secure.		
0200	Flw Reported All Secure. ^{P/O} Made Rounds Of Weigel.		
0300	Flw Reported All Secure.		
0400	Flw Reported All Secure. ^{P/O} Made Rounds Of Weigel.		
0500	Flw Reported All Secure.		
0600	Flw Reported All Secure. ^{P/O} Made Rounds Of Weigel.		
0630	Relieved Of Gangway Duties. ASSUMED THE WATCH. <i>E. A. L. Orr.</i>		
	0800-1600		
0800	MR BARRETT ^{P/O} - MR DAIGLE ^{P/E} - CAMERON ^{G/W} - ORR ^{Flw} - FLYNN ^{Flw} . ^{Flw} MAKING CLOCK ROUNDS + TAKING SOUNDINGS. ALL SECURE.		
0900	MR BARRETT - MR DAIGLE MAKING ROUNDS OF POPE AND WEIGEL. ^{Flw} REPORTS ALL SECURE.		
1000	ALL SECURE ON BOTH SHIPS.		
1045	MR BRIDY ^{P/O} ABOARD - MR DAIGLE ASHORE		
1055	MR CHRISTENSEN ^{P/O} ABOARD - MR BARRETT ^{P/O} ASHORE.		
1100	^{P/O} & ^{P/E} MAKING ROUNDS OF WEIGEL.		
1200	ALL SECURE ON BOTH SHIPS		
1300	^{P/O} MAKING INSPECTION AT BOTH POPE & WEIGEL. ALL SECURE.		
1335	JACKSON, J. F. ^{P/O} CALLED IN - WILL BE LATE.		
1400	ALL SECURE ON BOTH SHIPS		
1410	WATCH RELIEVED BY BLUE ^{P/O} <i>Don Johnson</i> ^{P/O}		
	DAVACOL ^{P/O} - JACKSON ^{P/O} (1600-2400) MR CHRISTENSEN ^{P/O} - MR BRIDY ^{P/O}		
1430	ASSUMED THE WATCH, ALL IN ORDER.		
1440	JACKSON ^{P/O} (1435-9) CALLED IN STATING HIS INVOLVEMENT IN A TRAFFIC ACCIDENT AND UNABLE TO COME IN FOR WATCH, ALSO THAT HE WILL BE IN FOR TOMORROW'S WATCH (1600-2400, 15 DEC. 1968)		
1500	BLUE/DAVACOL TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE POPE AND WEIGEL. ^{P/O} AND ^{P/E} INSPECTING THE WEIGEL.		
1600	Flw report all in good order		
1700	Flw report all in good order		
1730	slight Steam Leak on Weigel at 4-16-1-L ^{P/E} notified		
1900	Flw report all in good order		
2000	Flw report all in good order		
2100	Flw report all in good order		
2200	Flw report all in good order		
	watch relieved <i>MS</i> ^{P/O}		

AT/PASSAGE FROM		TO	
Pier 2 Berth 30 Hunters Point, San Francisco, California			
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
(+) 8		15 Dec. 1968	Sunday
TIME	REMARKS		
	0000-0800		
	Moored As Before.		
	On Watch: Mr. Barrett P/O Mr. Daigle P/E, Dixon P/W, Celada & Frutaz P/W. Frutaz Making Detex Rounds on The Weigel & Celada on The Pope. Rat Guards & Lines All In Apparent Good Order.		
0000	P/W Reported All Secure, P/O Made Rounds Of Weigel.		
0100	P/W Reported All Secure.		
0200	P/W Reported All Secure, P/O Made Rounds Of Weigel.		
0300	P/W Reported All Secure.		
0400	P/W Reported All Secure, P/O Made Rounds Of Weigel.		
0500	P/W Reported All Secure.		
0600	P/W Reported All Secure, P/O Made Rounds Of Weigel.		
0630	P/W Relieved Of Gangway Duties. E. A. Dinn.		
	ASSUMED THE WATCH.		
	0800-1600		
	MR. BARRETT P/O MR. DAIGLE P/E CAMERON P/W ORR P/W FLYNN P/W		
0800	P/W MAKING CLOCK ROUNDS & TAKING SOUNDINGS. ALL SECURE ON BOTH SHIPS.		
0900	P/O - P/E MADE ROUNDS OF BOTH POPE & WEIGEL. ALL SECURE.		
1000	ALL SECURE ON BOTH SHIPS		
1030	MR. BRIDY P/O ABOARD.		
1050	MR. CHRISTENSEN P/O ABOARD. MR. BARRETT P/O MR. DAIGLE P/E ASHORE.		
1100	P/O INSPECTED BOTH WEIGEL & POPE. ALL SECURE.		
1200	ALL SECURE		
1300	ALL SECURE, MR. CHRISTENSEN P/O MADE ROUNDS OF BOTH SHIPS		
1400	ALL SECURE ON BOTH SHIPS.		
1430	WATCH RELIEVED. Hlong Johnson P/O		
	JACKSON P/O DAVACON P/O (1600-2000) CHRISTIANSEN P/O MR. BRIDY P/E		
1430	ASSUMED THE WATCH, ALL IN ORDER.		
1500	JACKSON/DAVACON TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE POPE AND WEIGEL. P/O AND P/E INSPECTING THE WEIGEL.		
1600	ALL IN ORDER.		
1700	P/O AND P/E INSPECTING THE WEIGEL, ALL IN ORDER.		
1800	ALL IN ORDER.		
1900	P/O AND P/E INSPECTING THE WEIGEL, ALL IN ORDER.		
2000	ALL IN ORDER.		
2040	P/O AND P/E INSPECTING THE WEIGEL.		
2100	ALL IN ORDER.		
2200	P/O AND P/E INSPECTING THE WEIGEL, ALL IN ORDER.		
2230	WATCH RELIEVED BY FRUTAZ P/O.		

USNS Gen John Pope

AT/PASSAGE FROM Berth 30 Area 2	Hunters Hunt	TO San Francisco California
ZONE DESCRIPTION + 8	DATE (Day, month, year) 16 Dec. - 68	DAY OF WEEK Monday

TIME	REMARKS
	0000 - 0800
2300	ON watch MR. Barrett ^R / ₆ MR. Daigle ^R / ₆ Frutkin ^G / _W Celada ^F / _W Tipton ^F / _W Celada ^F / _W on the Pope made his round every hour and report to the bridge. Tipton ^F / _W on the Weigel made his round every hour and report to the Pope Gangway every hour.
2400	Lines and Rat guards are in good order.
0000	MR. Barrett ^R / ₆ made his round on the Weigel.
0100	ALL SECURE.
0200	MR. Barrett ^R / ₆ made his round on the Pope.
0300	ALL SECURE.
0400	MR. Barrett ^R / ₆ made his round on the Weigel.
0500	ALL SECURE.
0600	MR. Barrett ^R / ₆ MR. Daigle ^R / ₆ made their round on both ship Weigel & Pope. ALL SECURE Watch reviewed by ORR
0645	¹ / ₂ + CH. ENG. ABOARD - ^R / ₆ + ^R / ₆ ASHORE <i>RM Fortney</i>
0715	CAPTAIN PETROSKY ABOARD MR. COLLINGE ¹ / ₂ (0800-1600) ORR ^A / _B GANGWAY CAPELL ^A / _B FIREWATCH
0800	MOORED AS BEFORE. LINES, RAT GUARDS, & GANGWAY ALL SECURE
0900	ROUTINE WATCH. F/W MAKING REGULAR ROUNDS.
0945	TEST OF ALARM SYSTEM O.K. - CAPTAIN ASHORE TO HDQTRS.
1130	CAPTAIN RETURNS
1245	PURSER TO POST OFFICE 1300 RETURNS
1430	WATCH RELIEVED BY CAMERON ^A / _B Gen. Orr ASSUMED THE WATCH. Mr. Christensen ^R / ₆ aboard
1540	MR. BRIDGY ^R / ₆ ABOARD.
1600-2400	on watch Mr. Christensen ^R / ₆ Mr. Bryedy ^R / ₆ , Mouillon ^F / _W , Cameron ^F / _W
1600	F/W report all in good order
1700	F/W report all in good order
1800	F/W report all in good order
1900	F/W report all in good order
2000	F/W report all in good order
2100	F/W report all in good order
2200	F/W report all in good order watch relieved <i>HC ^R/₆</i>

U.S.N.S. Gen. John Pope

AT/PASSAGE FROM BERTH 30 Pier 2 HUNTERS	TO POINT San Francisco Calif
ZONE DESCRIPTION + 8	DATE (Day, month, year) 17-Dec.-68
	DAY OF WEEK Tuesday

TIME	REMARKS
	0000-0800
2300	On Watch; MR. BARRETT R/O MR. Daigle R/E FRUTAZ G/W SHAPIRO G/W TIPTON G/W Shapiro G/W made his round on the Pope and Report to the bridge every hour. Tipton G/W on the Weigel made his round and Report to the Pope G/W.
2400	ALL LINE and RAT GUARDS ARE IN GOOD ORDER.
0000	MR. BARRETT R/O and MR. Daigle R/E made their Round on both ship Weigel and Pope.
0000	ALL SECURE 0200 ALL SECURE.
0300	MR. BARRETT R/O made his round on the Pope.
0400	ALL SECURE.
0500	MR. BARRETT R/O and Daigle R/E made their Round on both ship Weigel and the Pope.
0600	ALL LINE and RAT GUARDS are in good order. Watch Relieved by Goe, Orr
0715	CAPTAIN ABOARD G.M. Frutaz
0719	SUNRISE. DECK LIGHTS TURNED OFF. MR COLLINGE Y/O (0800-1600) ORR A/B GANGWAY NIX A/B FIREWATCH
0800	MOORED AS BEFORE. LINES, GANGWAY, & RAT GUARDS ALL SECURE
0900	ROUTINE WATCH - ALL SECURE
0925	SYLVA, EDWARD --- REEFER ENG. ABOARD VICE GRAHAM
1340	D. VAN AUKE MS. TV ABOARD - 1345 ASHORE
1405	PURSER TO POST OFFICE
1410	WATCH RELIEVED BY CAPELL A/B Geo. Orr
1410	Watch assumed by Capell A/B Christiansen R/O (1600 - 2400) Capell A/B Gangway Cameron A/B Lane E/O Mouillien A/B
1423	Purser back on board
1455	Captain Ashore.
1500	Y/O Ashore
1505	Chief engr ashore
1600	All in order
1700	R/O made routine inspection of Weigel - all secure
1730	R/E made round of Weigel - all secure
1800	All Secure
1900	R/O made routine inspection of Weigel - all secure.
2000	All Secure
2045	R/O made routine inspection of Weigel - all secure
2100	All secure
2200	R/O made routine inspection of Weigel - all secure
2230	Relieved by Dien R. Capell

AT/PASSAGE FROM	Pier 2 Berth 30 Hunters Point		TO	San Francisco, California	
ZONE DESCRIPTION	(+) 8	DATE (Day, month, year)	18 Dec. 1968		DAY OF WEEK
					Wednesday

TIME	REMARKS
	0000-0800
	Moored As Before.
	On Watch: Mr. Barrett R/O, Mr. Deagle R/E, Diau S/W, Shapiro & Tipton Flw Tipton Making Detex Rounds On The Weigel & Shapiro On The Rope. Rat Guards & Lines All In Apparent Good Order.
0000	Flw Reported All Secure. R/O Made Rounds Of Weigel.
0100	Flw Reported All Secure.
0200	Flw Reported All Secure. R/O Made Rounds Of Weigel.
0300	Flw Reported All Secure.
0400	Flw Reported All Secure. R/O Made Rounds Of Weigel.
0500	Flw Reported All Secure.
0600	Flw Reported All Secure. R/O Made Rounds Of Weigel.
0630	Relieved Of Gangway Duties.
	Mr Collinge i/o (0800 - 1600) Capell R/O gangway Cameron R/B
0630	Assumed watch
0645	Mr Collinge i/o aboard.
0725	Captain Petrosky aboard
0900	All Secure Routine watches
0955	Erickson MSTS inspector aboard
1200	All Secure
1430	Watch relieved by Flynn R. Capell
	1600-2400
1445	Master ashore
	Flynn R/O - Davack R/B (1600-2400) Mr. Christensen R/O - Mr. Wilson R/E Blue R/W
1500	Assumed The Watch, All In Order. Flynn/Davack Taking Soundings And Making Detex Rounds Aboard The Rope And Weigel. R/O & R/E Inspecting The Weigel.
1600	All In Order.
1700	R/O And R/E Inspecting The Weigel, All In Order.
1800	All In Order.
1900	all in order Flw reported,
2000	Flw reports all in apparent good order
2100	Flw reports all in good order
2200	Flw reports all in good order
	watch relieved HS

AT/PASSAGE FROM		TO	
Pier 2 Berth 30 Hunters Point, S		San Francisco, California	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
(1) 8		19 Dec. 1968	Thursday
TIME	REMARKS		
	0000-0800		
	Moored As Before.		
	On Watch: Mr. Barrett R/O, Mr. Daigle R/O, Dion G/O, Tipton + Celada F/W. Tipton Making Detex Rounds On The Weigel + Celada On The Pope. Rat Guards & Lines All In Apparent Good Order.		
0000	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0100	F/W Reported All Secure.		
0200	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0300	F/W Reported All Secure.		
0400	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0500	F/W Reported All Secure.		
0600	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0630	Relieved Of Gangway Duties. C. A. Quinn.		
	0800 - 1600		
	Moored As Before; PIER 2, BERTH 30, HUNTERS POINT SAN FRANCISCO, CALIF. All SECURE		
0640	MR BARRETT R/O RELIEVED by MR. COLLINGS R/O, MR. DAIGLE RELIEVED by MR. GOCKLEY. NIX R/O RELIEVED DION GANGWAY.		
0720	CAPTAIN PETROSKY ABOARD.		
0800	All in APPARENT Good ORDER.		
0900	All in APPARENT Good ORDER.		
0920	TRUCK ARRIVED FOR STORES. LOADING STORES FOR PERESUS.		
1000	All in APPARENT Good ORDER.		
1100	All in APPARENT Good ORDER.		
1200	All in apparent good order		
1200	Eng dept. Safety meeting. Adjourned 1230		
1300	All in apparent good order		
1347	Purser to post office		
1402	Purser returned aboard		
1430	Watch relieved R. Lapell		
	1600-2400		
	Moored As Before		
	ON WATCH - MR. CHRISTIAN BERRY R/O MR. Wilson ENG. R/O DAVACO C/M/B SHAPIRO G/B FLYNN F/B		
1500	ASSUMED WATCH, All in APPARENT Good ORDER		
1600	All SECURE ON WIEGLE & POPE.		
1700	MR. C. R/O CHECKED LINES ON WIEGLE & POPE ALL SECURE		
1800	All SECURE ON WIEGLE & POPE		
1900	MR. C. R/O CHECKED LINES & SHIP IN GENERAL (WIEGLE) & ALL IS SECURE. MR. Wilson CHECK WIEGLE ENGINE COMPARTMENTS & REPORTS ALL SECURE.		
2000	All SECURE		
2100	ROUNDS MADE OF WIEGLE By MR. C. R/O AND ALL REPORTED SECURE		

AT/PASSAGE FROM

TO

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

Pier 2 Berth 30 Hunters Point San Francisco California.

(+) 8

20 Dec. 1968

Friday

TIME	REMARKS
	0000-0800
	Moored As Before.
	On Watch: Mr. Barrett $\frac{1}{2}$ Mr. Daigle $\frac{1}{2}$ Dion $\frac{1}{2}$ Celada + Tipton Flw.
	Tipton McKino Detex Rounds On The Weigel + Celada On The Pope.
0000	Flw Reported All Secure. No Made Rounds Of Weigel.
0100	Flw Reported All Secure. Rat Guards + Lines In Apparent Good Order.
0200	Flw Reported All Secure. No Made Rounds Of Weigel.
0300	Flw Reported All Secure.
0400	Flw Reported All Secure. No Made Rounds Of Weigel.
0500	Flw Reported All Secure.
0600	Flw Reported All Secure. No Made Rounds Of Weigel.
0630	Relieved Of Gangway Duties. E. A. Dim.
0645	$\frac{1}{2}$ + CH. ENG. ABOARD — $\frac{1}{2}$ + $\frac{1}{2}$ E ASHORE
0715	CAPTAIN PETROSKY ABOARD
	MR. COLLINGS $\frac{1}{2}$ (0800-1600) ORR $\frac{1}{2}$ GANGWAY CAPELL $\frac{1}{2}$ FIREWATCH
0800	MOORED AS BEFORE. LINES, GANGWAY, AND RAT GUARDS ALL SECURE
0942	MR. MEDINA MSTC COMPTROLLERS OFFICE ABOARD
1000	ALL SECURE. Flw MAKING ROUNDS
1100	ALL SECURE
1200	ROUTINE WATCH — ALL IN APPARENT GOOD ORDER
1300	ALL SECURE
1345	$\frac{1}{2}$ TO BASE MESSAGE CENTER
1402	MR. MEDINA ASHORE 1407 "CHIC" REHILL MSTU ABOARD
1410	$\frac{1}{2}$ RETURNS 1415 REHILL ASHORE
1430	WATCH RELIEVED BY FLYNN $\frac{1}{2}$ Sea. On
	1600-2400
	MR. CHRISTENSEN $\frac{1}{2}$ MR. WILSON $\frac{1}{2}$ SHAPIRO $\frac{1}{2}$ BG
	DAVACOL $\frac{1}{2}$ BF (WIEGEL) FLYNN $\frac{1}{2}$ F (POPE)
1430	ASSUMED WATCH — MOORED AS BEFORE & ALL IN APPARENT GOOD ORDER
1450	CAPTAIN PETROSKY ASHORE
1455	FIRST OFFICER ASHORE / START OF LEAVE
1500	ALL SECURE
1600	MR. C. MADE ROUNDS OF WIEGEL REPORTS ALL SECURE.
1700	ALL SECURE ALL LIGHTS BRIGHT
1800	ALL SECURE ROUNDS OF WIEGEL MADE BY MR. C. REPORTS ALL SECURE — MR. WILSON MADE ROUNDS OF WIEGEL ENGINE SPACES & REPORTS ALL SECURE
1850	MRS. CELADA CALLED AND REPORTED CELADA ILL, WITH 104° TEMPT. UNABLE TO STAND WATCH
1900	ALL SECURE
2000	ALL SECURE, FIRST OFFICER REPORTS ALL SECURE AFTER MAKING ROUNDS ON WIEGEL
2100	ALL SECURE
2200	ALL SECURE ROUNDS MADE BY Flw ON WIEGEL AND REPORTS ALL SECURE — GANGWAY BULB BURNED OUT

AT/PASSAGE FROM		TO	
Pier 2 Berth 30 Hunters Point, S		San Francisco, California.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
(H) 8		21 Dec. 1968	Saturday
TIME	REMARKS		
	0000-0800		
	Moored As Before.		
	(On Watch: Mr. Barrett ^{R/O} , Mr. Daigle ^{R/E} , Dion ^{G/W} , Fruto ^{2 F/W} .		
	Fruto ² Making Detex Rounds On The Weigel And On The Pope.		
	Rat Guards And Lines All In Apparent Good Order.		
0000	R/O Made Rounds On The Weigel - F/W Reported All Secure.		
0100	F/W Reported All Secure.		
0200	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0300	F/W Reported All Secure.		
0400	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0500	F/W Reported All Secure.		
0600	F/W Reported All Secure. R/O Made Rounds Of Weigel.		
0630	Relieved Of Gangway Duties.		
	ASSUMED THE WATCH.		
	0800-1600		
	MR BARRETT ^{R/O} = MR DAIGLE ^{R/E} = CAMERON ^{G/W} = ORR ^{F/W}		
0800	F/W TAKING SOUNDINGS & MAKING CLOCK ROUNDS. ALL SECURE ON BOTH SHIPS		
0900	R/O = R/E MAKING ROUNDS OF BOTH SHIPS. F/W REPORT'S ALL SECURE.		
1000	ALL SECURE ON BOTH SHIPS.		
1045	MR BRIDDY ^{R/E} ABOARD. MR CHRISTENSEN ^{R/O} ABOARD = MR BARRETT = MR DAIGLE ^{R/E} A SHORE.		
1100	ALL SECURE ON BOTH SHIPS, R/O INSPECTED BOTH WEIGEL & POPE.		
1200	ALL SECURE		
1300	R/O & R/E MAKING ROUNDS OF BOTH POPE & WEIGEL. ALL SECURE.		
1400	ALL SECURE.		
1440	WATCH RELIEVED BY BLUE ^{R/O} .		
	Wong Johnson ^{R/O}		
1430	R/O REPORT ALL SECURE.		
1430	WATCH RELIEVED BY JACKSON A/B		
1430	ROUNDS BEING MADE ON POPE AND WEIGEL		
1600	ROUNDS BEING MADE ON GEN. POPE AND WEIGEL		
1700	ROUNDS BEING MADE ON GEN. POPE AND WEIGEL ALL SECURE		
1800	ROUNDS BEING MADE ON GEN. POPE AND WEIGEL ALL SECURE		
1900	R/O MADE AN INSPECTION OF GEN. WEIGEL.		
1900	ROUNDS BEING MADE ON GEN. POPE AND WEIGEL ALL SECURE		
2000	ROUNDS BEING MADE ON GEN. POPE AND WEIGEL ALL SECURE.		
2100	ROUNDS BEING MADE ON GEN. POPE AND WEIGEL ALL SECURE		
2140	R/O MADE AN INSPECTION OF GEN. WEIGEL ALL SECURE		
2200	ROUND BEING MADE ON GEN. POPE AND WEIGEL		
2300	WATCH RELIEVED BY DION A/B		

Pier 2 Berth 30 Hunters Point, San Francisco Calif.		
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
(+) 8	22 Dec. 1968	Sunday

DATE (Day, month, year)

DAY OF WEEK

Sunday

TIME

REMARKS

0000-0800

Moored As Before

on watch: Mr. Barrett^R, Mr. Dirole^{R/E}, Dion^{G/W}, Frutaz^{FW}

Detex Pounds Being Made On The Weigel + Pope.

Rat Guards & Lines All In Apparent Good Order

0000 Roll Made Pounds Of Weigh. All In Apparent Good Order.

0100	F/w Reported All Secure.
------	--------------------------

0200 Flw Reported All Secure. % Made Rounds Of Weigel

0300	Flw Reported All Secure
------	-------------------------

0400	Flw Reported All Secure. 140 Made Rounds Of Weigel
------	--

0500	Flw Reported All Secure.
------	--------------------------

0600 Flw Reported 1411 Secure. R/O made Rounds Of Weigel.

0630	Relieved Of Gangway Duties
------	----------------------------

ASSUMED THE WATCH.

① A. K. Dine

0800 - 1600

MC BARRETT $\frac{R}{D}$ = MR DAIGLE $\frac{R}{E}$ = CAMERON $\frac{G}{W}$ = ORR $\frac{F}{W}$

0800	F/W MAKING CLOTH ROUNDS & TAKING BRIDGE SOUNDINGS. ALL SECURE.
------	---

0900	ALL SECURE ON BOTH SHIPS. ^{R/R} _{P/E} MADE INSPECTING BOTH SHIPS
------	--

1000	All SECURE.
------	-------------

1040	MR BRIDY ⁰ / ₁ ABOARD.
------	--

1050	MR CHRISTENSEN ^R /D ABOARD. MR BARRETT ^R /D-MR DAIGLE ^R /E ASHORE
------	--

1100 $R/D = R/E$ MAKING ROUNDS of BOTH S.I.P. All SECURE

1200	ALL SECURE ON BOTH SHIPS
------	--------------------------

1300 R/D. R/ INSPECTING BOTH POPE & WEIGEL. ALL SECURE.

1400	AIL SECURE.
------	-------------

1480 WATCH RELIEVED BY BLUE ^{W/B.}

Wang Jiamou ^{A/B}

FLYNN A/B. DAVAROL A/B (1600-2400) MR. CHRISTIANSEAL A/B. MR. BRIDGY R/E

1430	Assumed the watch, all in order.
------	----------------------------------

1500 FLYNN/DAVACOL TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD
THE ROBE AND WEICHEL. R/O AND R/E INSPECTING THE WEICHEL.

1600 Ann In Order.

1605 FRUTAZ A/B (165-3) CALLED IN STATING HE HAS THE FLU AND WILL BE UNABLE TO COME IN TONIGHT FOR HIS ASSIGNED WATCH (00-08).

1700 R/G AND R/G INSPECTING THE WEIGEL ALL IN ORDER

1800	Am In Order.
------	--------------

1900	P/O AND P/E INSPECTING THE WEIGEL, ALL IN ORDER
------	---

2000 Am In Order

2010 R/O AND R/E INSPECTING THE WATCH

2100	Auto Tax Operator
------	-------------------

2200 R/O AND R/G INSPECTING THE WEIGHT AND IN ORDER

2230	WATCH RENTED BY CANADA P/B
------	----------------------------

AT/PASSAGE FROM PIER 2 Berth 30 Hunters Point	TO San Francisco, California
ZONE DESCRIPTION (+) 8	DATE (Day, month, year) 23 Dec 68
	DAY OF WEEK Monday

TIME	REMARKS
	0000-0800
	Moored as before.
	On Watch: Mr. Barratt R/O Mr. Daigle R/E, Celada G/Way
	Tipton T/W on both ships. The Pope & the Weigel
	Rat guards & lines are in good orders
0000	R/O made rounds on the Weigel. ALL secure.
0100	T/W reported all secure.
0200	R/O made rounds on the Weigel. F/W reported all secure.
0300	T/W reported all secure.
0400	R/O made rounds on the Weigel. T/W reported all secure.
0500	T/W reported all secure.
0600	R/O made rounds on the Weigel. T/W reported all secure.
0630	Watch relieved by G. ORT.
	J B Celada
0655	GARRETT, ARCHIE 3 RD ELECT. REPORTED ABOARD VICE GUITTEREZ
0700	CAPTAIN PETROSKY ABOARD — R/O ASHORE.
0720	SHIPS STEAM SECURED FWD. OF FR. 110 UNTIL FURTHER NOTICE
0745	TEST OF SHIPS FIRE ALARM SYSTEM O.K.
	CAPT. PETROSKY (0800-1600) ORR R/B GANGWAY SHAPIRO R/B FIREWATCH
0800	MOORED AS BEFORE. LINES, RATGUARDS & GANGWAY ALL SECURE
0810	STEAM BACK ON. 0825 CAPT. TO WEIGEL 0850 RETURNS
0900	ROUTINE WATCH. ALL SECURE.
1000	ALL IN GOOD ORDER
1100	ALL SECURE — F/W MAKING REGULAR ROUNDS ON BOTH VESSELS
1200	ALL SECURE
1300	ROUTINE WATCH — ALL IN GOOD ORDER
1430	WATCH RELIEVED BY BLUE R/B <i>See On</i>
	CAMERON R/B CAPELL R/B (1600-2400) MR. CHRISTIANSEN R/B · MR. BRIDY R/E
1430	ASSUMED THE WATCH, ALL IN ORDER.
1500	CAMERON/CAPELL TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE
	POPE AND WEIGEL. R/O AND R/E INSPECTING THE WEIGEL.
1515	MASTER ASHORE.
1600	ALL IN ORDER.
1700	R/O AND R/E INSPECTING THE WEIGEL, ALL IN ORDER.
1745	ORR R/B (165-8) CALLED IN STATING HE WILL BE UNABLE TO STAND HIS
	WATCH TOMORROW (24 DEC '68 DB-1600) DUE TO SICKNESS.
1800	ALL IN ORDER.
1900	R/O AND R/E INSPECTING THE WEIGEL, ALL IN ORDER.
2000	ALL IN ORDER.
2040	R/O AND R/E INSPECTING THE WEIGEL.
2100	ALL IN ORDER.
2200	R/O AND R/E INSPECTING THE WEIGEL, ALL IN ORDER.
2230	WATCH RELIEVED BY FRANK R/B SHAPIRO R/B

AT/PASSAGE FROM	TO	
PIER 2 BERTH 30 HUNTERS PT.	SAN FRANCISCO, CALIF.	
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
+8	24 DEC 1968	TUESDAY

TIME	REMARKS
	0000-0800
2230	MR. BARRETT ^{R/O} SHAPIRO ^{A/B} TIPTON ^{A/B} MR. DIGLE ^{R/E} ASSUMED WATCH ALL IN APPARENT GOOD ORDER. TIPTON MAKING DETEX ROUNDS OF USNS POPE & WEIGEL MOORED AS BEFORE. ALL LINES & RAT GUARDS SECURE.
2300	ALL SECURE F/W REPORTS ALL SECURE
2400	R/O BARRETT MADE ROUNDS OF WEIGEL REPORTS ALL SECURE
0100	F/W REPORTS ALL SECURE
0200	R/O MADE ROUNDS OF POPE & WEIGEL ALL SECURE
0225	BASE OPERATIONS CALLED AND RELAYED SMALL CRAFT WARNING; WARNING IN EFFECT FROM 1000 ZULU FOR 10 HOURS, WINDS SE 14-24 KNOTS WITH GUSTS TO 30 KNOTS, SEAS SLIGHT TO MODERATE WITH INCREASE IN EXPOSED SECTIONS OF THE BAY -
0300	F/W REPORTS ALL SECURE
0400	R/O MADE ROUNDS OF SHIPS REPORTS ALL SECURE
0500	F/W REPORTS ALL SECURE
0600	ALL SECURE DK. LIGHTS OUT
0650	WATCH RELIEVED BY PERKINS ^{A/B} Shapiro
	0800-0800 - Nix ^{F/W} PERKINS ^{R/B}
0710	CAPT. PETROSKY - ABOARD - MOORED AS BEFORE
0715	CAPT. BARRETT - ASHORE
0740	TEST MADE ON GENERAL ^{SMOKE-DETECTOR & KIDDE} FIRE SYSTEMS - ALL IN GOOD WORKING ORDER Nix ^{A/B} ON DETEX ROUNDS - BOTH VESSELS - ALL SECURE
1000	CAPT. PETROSKY TO WEIGEL
1025	CAPT. PETROSKY - ABOARD FROM WEIGEL WATCH RELIEVED
	(1600 - 2400) Cameron ^{M/B} FW Capell ^{A/B} FW
1430	MR BRIDDY ^{E/O} ABOARD.
1445	MR CHRISTENSEN ^O ABOARD. CAPTIAN PETROSKY ASHORE.
1500	CAMERON/CAPELL TAKING SOUNDINGS AND MAKING DETEX ROUNDS ABOARD THE POPE AND WEIGEL. R/O AND R/E INSPECTING THE WEIGEL.
1600	All In Order.
1700	R/O AND R/E INSPECTING THE WEIGEL, All In Order.
1800	All In Order.
1900	R/O AND R/E INSPECTING THE WEIGEL, All In Order.
2000	All In Order.
2010	R/O AND R/E INSPECTING THE WEIGEL.
2100	All In Order.
2200	R/O AND R/E INSPECTING THE WEIGEL, All In Order.
2230	WATCH RELIEVED BY DEAN ^{R/B}

AT/PASSAGE FROM

Pier 2 Berth 30 Hunters Point, San Francisco California

ZONE DESCRIPTION

(+) 8

TO

DATE (Day, month, year)

25 Dec. 1968

DAY OF WEEK

Wednesday

TIME	REMARKS
	0000-0800
	Moored As Before
	On Watch: Mr. Barrett R/o, Mr. Daigle R/E, Dion G/w, Shapiro & Tipton F/w. Tipton Making Detex Rounds On The Weigel & Shapiro On The Pope. Rat Guards & Lines All In Apparent Good Order.
0000	F/w Reported All Secure. R/o Made Rounds Of Weigel.
0100	F/w Reported All Secure.
0200	F/w Reported All Secure. R/o Made Rounds Of Weigel.
0300	F/w Reported All Secure.
0400	F/w Reported All Secure. R/o Made Rounds Of Weigel.
0500	F/w Reported All Secure.
0600	F/w Reported All Secure. R/o Made Rounds Of Weigel.
0630	Relieved Of Gangway Duties.
	Mr Daigle R/E & Mr Briddy R/o Christensen R/o & Barrett R/o (0800 - 1600) Cameron A/B, Jackson A/B Fw Capell A/B G
0630	Assumed watch Capell A/B
0700	All apparent good order
0800	All apparent good order
0855	J. Jackson's (A/B) wife called to say he's sick
0900	All apparent good order
1000	All apparent good order
1040	Mr Briddy R/o aboard
1050	Mr Christensen R/o aboard
1100	All apparent good order
1200	All apparent good order
1300	All apparent good order
1400	All apparent good order
1430	Relieved of the watch by Blue A/B
	Robert D. Capell
	Flynn R/B · Davacol R/B (1600-2400) MR. CHRISTIANSEN R/o · MR. BRIDDY R/o
1430	Assumed The Watch, All In Order.
1500	Flynn/Davacol Taking Soundings And Making Detex Rounds Aboard The Pope And Weigel. R/o And R/E Inspecting The Weigel.
1600	All In Order.
1700	R/o And R/E Inspecting The Weigel, All In Order.
1800	All In Order.
1900	R/o And R/E Inspecting The Weigel, All In Order.
2000	All In Order.
2040	R/o And R/E Inspecting The Weigel.
2100	All In Order.
2200	R/o And R/E Inspecting The Weigel, All In Order.
2230	Watch Relieved By Dion R/B.