

GENERAL SERVICES ADMINISTRATION
REGION 9
San Francisco, California 94103

November 18, 1968

GSA REGIONAL BULLETIN FPMR 9-E-24
SUPPLY AND PROCUREMENT

TO : Heads of Federal Agency Offices and Military Installations
Serviced by General Services Administration Region 9

SUBJECT: Safety hazard, FSN 8040-754-2685 adhesive

1. Purpose. This regional bulletin announces the omission of "Red Labels" on shipments of FSN 8040-754-2685 from the GSA Region 9 supply facilities.

2. Expiration date. This regional bulletin will expire on January 31, 1969.

3. Safety hazard. Some shipments of FSN 8040-754-2685 adhesive with the following identification were not marked with the "Red Label." With the flash point of 36 degrees F, this adhesive is highly inflammable.

Manufacturer : Baker Sealants & Coatings Company
Contract Number : GS-10S-23900
Purchase Order Nos.: S-61204; S-63163; S-63919; S-63098

"Red Labels" should contain following message:

KEEP AWAY FROM
FIRE
HEAT & OPEN FLAME
LIGHTS
CAUTION
LEAKING PACKAGES MUST BE REMOVED TO SAFE PLACE
DO NOT DROP

Agencies may submit requirements for the "Red Labels" to General Services Administration, Inventory Management Division, FSS, 49 4th Street, Mail Station 16A, San Francisco, California 94103.

T. E. Hannon
T. E. HANNON
Regional Administrator

Distribution: A-6f; B-6f; C-6f; F; G; H-6; I-6c3; J-6c3;
9-X-5; and Stores Stock Catalog Mailing List