

First Officer's Sub-Custody Cards

August 5, 1968

Article	: Allowance:	On hand	: Location	: Remarks
Light marker, Distress dry battery type	: 14 :	7	:	:
Tester Voltage	: 1 :	4 2	: REPAIR LOCKER NO 1 - 1 Repair locker no. 2 - 1	: ELECT. BELT
Cable Cutter, hydraulic	: 2 :	1	: Sail Locker SER# 205972	: 3 surveyed
DRILL HEAVY DUTY 1/2":	: 2 :	1	: REPAIR #2 LOCKER SER. 1139753	:
Tool Kit	: 2 :	1	: Damage Control No. 2	:
Lantern Head Type	: 10 :	0	: Missing	: Similar to Rustrite Co. 1704-7
Lantern, W.T. 2 1/4 W/lamp	: 4 :	4	: REPAIR NO 1 LOCKER	:
Cutting Outfit, Oxyacetylene	: 2 :	2	: ONE EACH REPAIR 1-2	:
Drill, Elect. HD Type 111 1/4" Cpa. chuck	: 4 :	2	: CARPENTER SHOP	SER. 6737045 SER. F54118
Drill, Elect. HD, Type 111 1/2" Cap. Chuck	: 2 :	0	: NONE	:
Port. Elect. sander Belt type 3"x24"	: 1 :	1	: Engine Room for Repair	: A148280 134.2988 W 155-4297
Port. Elect. Sander Disc Type	: 2 :	3	: BOSH STORE	: SER. NO. 585875 ROTARY BRUSH BOSH STORE
Reamer, Scaling, Elect. portable	: 2 :	1	: SER. NO. 585875 ROTARY BRUSH BOSH STORE	:
Tool Kit Automotive Electrical	: 1 :	0	: MISSING	: For repairing lifeboat engines
Scaler, Rotary Type Dual Bundle cutter	: unlisted	SER NOS 211 30 14243 130 56 14129 17769 15176 11957 130595	: sail Locker	:
Chipping Hammer, Arnessan Elect. Corrosion Dynamics	: unlisted	SER NOS G 6341 G 6526 G 6264 G 6258 C 6476 G 6554	:	: