

USNS GENERAL DANIEL I. SULTAN (T-AP 120)
c/o Fleet Post Office
San Francisco, California

T-AP 120/JH:oy
L650
15 October 1963

SHIP'S INSTRUCTION 4650.2

From: Master
To: Distribution

Subj: Internal and External Security

1. The Senior Watch Officer will be responsible for the following security measures during his watch:

a. To discourage thieves, stowaways and/or saboteurs from boarding the vessel, have all docks, sides of vessel and mooring lines illuminated at night, utilizing fixed general lighting system, debarkation lights, cluster lights, and kingpost lights.

b. Keep sides of vessel free of unnecessary lines which might provide a means of unauthorized boarding.

c. Quartermaster to check identification of all persons boarding. Visitors to log themselves aboard and ashore.

d. When stevedores are boarding, require foreman to produce name-list and check all stevedores aboard and ashore.

e. Stevedores to utilize open deck in getting to and from cargo hatches. They will not transit through passenger areas otherwise. If deemed necessary, close WDD's to restrict stevedores to the immediate vicinity of the cargo holds and hatches.

f. Junior Watch Officer will make security rounds of all passenger areas, including weather decks used by passengers, at least once every two hours.

g. Duty MAA will make security rounds of all areas of the vessel, being extra vigilant in remote areas. These rounds will be frequent but at irregular intervals.

h. Watch Seaman to make security rounds. If two gangways are being used, one seaman will be stationed on the third deck gangway and will perform duties of quartermaster.

SHIP'S INSTRUCTION 4650.2
15 October 1963

i. Fire-Watchmen will maintain their regular fire patrols, but will be extra vigilant for signs of unusual occurrences or loiterers.

j. Security watch will pay particular attention to remote areas. Examine locking devices on storerooms, and report immediately any signs of tampering which indicate attempts at forcible entry.

k. Attempt to identify any loiterers in remote areas and report immediately.


JOHN HARRINGTON

Distribution:

Bulletin Boards
Bridge
All gangways
File