

649-6 2 NOV 1967

1520

USNS POPE

JO 82-712 REPRODUCER REPAIR

SHOP X67

PICK UP TWO REMLER TYPE M-256 REPRODUCERS AT MSTIS ELECTRONICS BLDG.
310.

DISASSEMBLE REPRODUCERS. SAND BLAST AS REQUIRED AND REPAINT.

REASSEMBLE REPRODUCERS USING NEW HORNS AND GUARDS TO BE FURNISHED BY
MSTIS ELECTRONICS.

SIGNED: WEBER/CATRON