

VA4-225 \*VI THANH 0947N 10529E (WR537822)

VFR4/NC48-11/K10D (VVVH)

VNA 7 23 (M8A1) 60' 08-26

Fuel: JP-4 AVGAS

Remarks: Touchdown opposite E twy when  
ldg Rwy 26. Extv copter t/c at  
times. E twy and E ramp clsd.  
West taxiing deteriorating.

Hazards: Apch Rwy 08 over 4' lip, 4' fence  
and ruf terrain 315' prior to thld.  
9' ammo storage bunkers S side  
rwy, 6' fence and 7' bunkers 12'  
fr SW corner of W end. R/W  
pads 60' either side of Rwy at  
midpoint. Sunken PSP app. and  
Rwy 08. Surface under Rwy  
eroded Taxiing poor.

Traffic Pattern: Recommend ldg Rwy 08,  
wind permitting.

Radio: 47.3

OPEN TO STOL Acft

\*ICCS/UH-1H (Check out for VTB pending)

---

VA3-226 \*XUAN LOC 1055N 10715E (YT460082)

VFR3/NC48-7 & 48-8/K10D (VXU)

VNA 525 H35 (ASP) 80' 10-28

Remarks: Opr SR-SS.

Fuel: JP-4 (Truck)

Hazards: Apch Rwy 10 over 30' trees and  
bldg 1200' fr Rwy end. 160' twr  
700' N apch end Rwy 10. 160'  
twr 700' N of midfield. Apch  
Rwy 28 over 5' fence 570' fr Rwy  
end. 2' drainage ditches adj to  
shoulders. 15' drop-off around  
culvert on N side, midfield. 6'  
drop-off S side, midfield. 5'  
fence 30' fr side. Rwy shoulders  
in poor cond. E end of Rwy ruf.  
Deteriorating ramp. Slick when  
wet.

Radio: 36.0

AN LOC NDB AC 318 10°57'N 107°13'E  
120° 2.6 NM to Field

\*ICCS/VTB

---

VA2-229 PLEIKU/NANSTEPH 1402N 10759E  
(ZA228536)

VNA 2580 11 (GRADED EARTH) 60' 06-24

CLOSED

---

VA2-232 ENGLISH 1428N 10902E (BS879010)

VNA 98 L4 H36 (ASP) 60' 03-21

CLOSED

---

VA4-236 KIEN LONG 0930N 10516E (WR286505)

VLG

MACV 5 17 (PSP) 60' 05-23

CLOSED

---

VA1-239 TIEN PHUOC 1529N 10819E (BT116128)

VNA 197 20 (M8A1) 60' 15-33 (VTP)

CLOSED

---

1 April 1973

121

SVN/CAMBI

VA3-240 BLACKHORSE 1049N 10713E (YS437963)

VFR4/NC48-7/K10D SLT

VNA 820 H23 (ASP) 60' 11-29

Remarks: Opr SR-SS. 350' ovrn E, 250' W end, ruf. Parallel Rwy used as twy and offload/onload, as well as R/W prk.

Hazards: Apch Rwy 11 over 75' trees 1 mile out, bldg and 20' p-line 800', 6' drainage ditch 500' fr thld. Apch Rwy 29 over 75' trees 1 mile out, 20' p-line, bldg and road 1000' fr apch end. Trng area adj to Rwy S side. 25' water twr 80' fr S edge W ovrn. 5' barriers 30' fr S edge and 20' bldg 57' fr S edge, 282' fr E end. Obstacle crs adj to Rwy. Culverts and ditches in clear areas. Extensive pedestrian and vehicular tfc. Rwy 29, first 500' clsd, not marked. Deep ruts between Rwys and over run.

Open to STOL Acft.

---

VA2-241 POLEI CLENG 1424N 10749E (ZA029933)

VFR2/ND48-8/K10A

VNA 1870 35 (MFAI) 59 08-26

CLOSED/UNFRIENDLY

---

VA4-242 SADEC 1017N 10545E (WS830373)

20 H16 (ASP) 15' 05-23

CLOSED

---

VA3-243 SONG BE CITY 1151N 10700E (YU182109)

VFR3/NC48-4/K10D

VNA 722 H22 (ASP) 25' 18-36

Fuel: A+J4

Remarks: Extv R/W tfc.

Hazards: 2400' mt 1 NM prior to apch end  
Rwy 36. Apch Rwy 18 over city  
hall 300', 20' p-line and barri-  
cades 100', 200' prior to thld.  
Public road crosses apch end  
Rwy 36. 189' unlgtd microwave  
twr midfield W side 1000' fr Rwy.  
130' rdo twr NE of fld. R/W prk  
and reful close to Rwy W side  
midfield. Unctl vehicle and  
pedestrian tfc.

OPEN TO PORTERS

---

1 April 1973

123

SVN/CAMBI

VA1-246 TAM KY ALT 1525N 10828E (BT302245)

VFR 1 ND49-1/K-10A  
16 6 (SOD) 65' 04-22

Remarks: Recommend ldg to SW. Rwy slick  
when wet. Telephone wire across  
Rwy 10' above ground.

Hazards: Numerous tall antennas west of  
fld. Watch for pedestrians and  
cattle on Rwy.

CLOSED TO C-46, C-47  
VTB Max T/O wt. 9,000L. Closed to VTB  
when wet.

---

VA3-247 \*LONG AN 1033N 10624E (XS524656)

VFR4/NC48-1/K10D (VON)  
VNA 7 H15 (ASP) 60' 10-28

Remarks: Opr SR-SS.

Hazards: Apch Rwy 10 over road, ditch  
and 6' fence 200' fr thld. Apch  
Rwy 28 over bldg, 8' bunkers  
and 20' poles 900' prior to thld.  
Shoulders ruf and overgrown, ruf  
terrain adj to both edges.  
Helipads 100' fr N edge. Revet-  
ments 50' fr S edge E end.  
Helipad along N edge of E ovrn.  
162' twr 1.5 NM SE (XS547647)  
lgtd O/R. 160' twr 2.1 NM  
aligned with Rwy 28, lgtd O/R.  
No windsock. Watch for cattle  
near Rwy.

CLOSED TO C-46, C-47  
\*ICCS/VTB

VA3-248 TANH LINH 1105N 10741E (YT935256)

VNA 420 20 (M8A1) 60' 17-35

CLOSED/UNFRIENDLY

---

VA2-252 OASIS 1348N 10752E (ZA104274)

VNA 1770 35 (LATERITE) 60' 05-23

CLOSED

---

VA3-256 TAY NINH WEST 1119N 10604E (XT168518)

VFR3/NC48-3/K-10D (VVTN/TAV)

VNA 26 H38 (ASP) 80' 02-20

Fuel: J4

Remarks:

Hazards: Apch Rwy 20 over 5' embankment 364' and road 274' fr thld and two 6' bunkers either side of center-line 300' fr thld. Apch Rwy 02 over berm, road and drainage ditch 458' fr thld. 3235' mt 7 NM NE. 3 cement walls 43' fr E edge of Rwy 5' high.

R/W in clear zone and debris blowing onto Rwy 20 touchdown area. Unctl vehicles and pedestrians on Rwy.

Traffic Pattern: 360 overhead approaches not authorized

---

VA3-258 BINH GIA 1039N 10715E (YS465780)

VNA 344 20 (M8A1) 60' 08-26

CLOSED

---

VA2-259 VINH THANH 1406N 10847E (BR614606)

VNA 190 L H19 (ASP) 60' 17-35

CLOSED

---

VA2-260 \*BAO LOC 1134N 10749E (ZT065792)

VFR3/NC48-4/K10D

VNA 2822 35 (M8A1) 59' 09-27

Fuel: A+J4

Remarks: Opr 2300-1030Z. R/W opr fr  
prk area. Penprimed laterites  
ovrns, 220' E, 126' W end. Rwy  
PSP deteriorating.

Hazards: Full Rwy cannot be seen fr touch-  
down pt. Apch Rwy 09 over deep  
ravine abrupt upslope 4' fence  
126' fr thld, 8' beveled lip btn  
ovrn and twy. Apch Rwy 27 over  
downslope 4' fence 300' fr thld.  
2' ditch 25' fr Rwy edge both sides.

Traffic Pattern

Caution: Tfc ptn conflicts with Tan Phat  
1 $\frac{1}{4}$  NM East F/W pattern north  
side, R/W pattern south side.  
Land Rwy 27 wind permitting.  
Circle field prior to landing.

Radio: Ctc as per CORDS SOL - 47.3

CLOSED TO C-46

VTB Max T/O wt. 9,600L

\*ICCS/VTB

---

VA4-262 LONG KHOT #2 1055N 10550E (WT912069)

VNA 6 12 (CLAY) 50' 06-24

CLOSED

---

1 April 1973

127

SVN/CAMBI

VA1-263 QUANG TRI/LA VANG 1644N 10712E  
(YD343509)

40 19 (LATERITE) 50' 11-29

CLOSED

---

VA4-264 AN THOI 1001N 10402E (US940070)

VFR4/NC48-5/K10D (DDG)

N 15 L 36 (M8A1) 60' 13-31

Fuel: A+J4. Emergency refuel hand pump  
only. Call TAIL PIPE ALPHA 126.2

Remarks: Opr SR-SS. Left hand tfc circuits  
to Rwy 31 are recommended in  
view of 200' hill  $\frac{1}{2}$  mile W. 105'  
antenna 1000' NE of afd with red  
lgt at 70' height, unlgtd above.  
150' x 150' M8A1 turnaround/ovrn  
ea end, additional 185' hardened  
ovrn NW end, 275' SE end. 30'  
trees 500' fr apch end Rwy 13.

Hazards: Vehicular tfc crossing Rwy at  
midfield. Watch for livestock.

Traffic Pattern: Recommend land Rwy 31,  
tkof Rwy 13.

Radio: Call An Thoi 37.5

CLOSED TO C-46

---

VA2-265 TIEU ATAR 1313N 10747E (ZV020622)(TUA)

VNA 588 15 (LATERITE) 60' 07-25

CLOSED

---

VA3-269 DUC PHONG 1148N 10714E (YU440047)

VFR3/NC48-4/K-10D

VNA 919 30 65' 02-20

Remarks: Opr SR-SS. Ascertain security prior to landing. Rwy cntr ruts easily, use turnaround. Rwy in poor cond and deteriorating.

First 400' Rwy 20 M8A1.

Hazards: Full Rwy cannot be seen fr touch-down pt. Apch Rwy 02 over ridge with trees  $\frac{1}{2}$  mile out. Road and steep embankment 211', ditch 164' prior to thld. Apch Rwy 20 has small hill 1 mile out. Sharp 15' upslope 200' prior to thld. Shoulders poor cond and steep. 8' drop-off 20' fr edges of Rwy, S end. 2' ditches extending 3' above Rwy level adj to both shoulders. Road along both sides of Rwy 3'-4' above Rwy level on W side.

CLOSED TO C-46, C-47

---

VA1-272 BA TO NEW 1445N 10844E (BS557320)

VNA 196 23 (M8A1) 50' 07-25

CLOSED

---

VA4-273 HA TIEN SOUTH 1022N 10430E (VS457455)

VNA 10 L 13 (SOD/GRAVEL) 60' 06-24

CLOSED

---

VA3-274 LONG HAI 1024N 10713E (YS432512)

VFR4/NC48-7/K10D (LHI)

VNA 7 21 (M8A1) 60' 08-26

Fuel: JP-4

Remarks: Prior security arrangement required. End and 200' touchdown mtrs. Strong prevailing crosswinds.

Hazards: Apch Rwy 26 over 1073' hill 1½ miles, 6' fence 300', road 270' prior to thld. 6 inch lip E end btn matting and ovrn, 1' drop-off at end of E ovrn. 6-12 inch drop-off fr Rwy level to shoulder level ea side. Low area ea side of Rwy, 40' fr Rwy edge S side, 30' fr Rwy edge N side. Livestock and pedestrians on ramp and Rwy. No windsock.

CLOSED TO C-46

---

VA3-278 DI AN 1054N 10645E (XT909055)

VFR3/NC48-8/K-10D (VDJ)

VNA 108 28 (LATERITE/RC-3) 90' 18-36

Remarks: Opr SR-SS. 260' N ovrn some  
sfc as Rwy. 675' peneprimed  
packed dirt ovrn S.

Hazards: Apch Rwy 18 over 30' bldg and  
road 1000', 6' lip 270' prior to  
thld. Apch Rwy 36 over 8' bunker  
and 25' poles adj to bunkers 800'  
prior to Rwy. 120' com twr 1500'  
W of Rwy. Terrain slopes up-  
ward to SE corner of afld. Copter  
prk 100' W of Rwy. Acft revet-  
ments 110' fr W edge of Rwy.  
No windsock.

Traffic Pattern: Caution: Pattern conflicts  
with Tan Son Nhut and Bien  
Hoa tfc.

CLOSED TO C-46  
C-47 Max T/O weight 26,000L

---

VA2-279 ROK AAF 1345N 10906E (BR948209)

VPR-2/ND-49-9/K10A

VNAF (ROK) 60 L4 30(M8A1) 59' 05-23

Fuel: A+ Emergency only.

Remarks: Opr 2330-0930Z. 50' Clay ovrn  
W end, 50' laterite ovrn E end.  
N ramp for lt acft only. Wind-  
sock midfield S side.

Hazards: Hills to N and W. Apch Rwy 05  
over 20' guard twr 500', 5' fence  
75' fr thld. Apch Rwy 23 over  
6'-10' lip 60' and road 40' fr thld.  
10' bunkers and berms 30' fr Rwy  
edges midfield. Bldg, revetments,  
and 40' ctl twr 150' fr Rwy edge  
N side, first 1/3 or Rwy 23. 10'  
drop-off 15' fr both edges SW 1/3  
of Rwy. 4' concertina fence  
placed across Rwy SS-SR, stored  
on edges of Rwy SR-SS. Rwy not  
anti-skid treated.

Tiger Tower: 61.2 47.3 Ctc Lane Twr  
295.1 for advsy. Opr 0001-  
0900Z.

CLOSED TO C-46

---

VA2-283 DAK SEANG 1450N 10741E (BY895406)

VNA 2156 14 (CLAY) 45' 10-28

CLOSED

-----  
VA3-284 LUSCOMBE 1034N 10714E (YS437681)

VFR4/NC48-8/K10D (LUS)

VNA 115 H33 (ASP) 80' 10-28

Remarks: Opr SR-SS.

Hazards: Apch Rwy 10 over 15' upslope,  
5' fence and road with culverts  
250' fr thld. Apch Rwy 28 over  
75' trees and 20' embankment  
950' fr thld. 8' revetments S  
Side 740' fr thld. 15' power lines  
and poles in N lateral safety zone,  
72' ctl twr 112' N of Rwy. 60'  
antennas 100' N side, midfield.  
2' ditch S side 13' fr Rwy. 3'  
ditch N side 35' fr Rwy. Moderate  
risk ngt afld.

-----  
VA2-285 PLEI DJERENG NEW 1358N 10739E

(YA859457)

VNA 955 35 (MX19) 60' 10-28

CLOSED

-----  
VA3-289 DINH QUAN 111N 10721E (YT579391)

VNA 426 14 (LATERITE) 60' 04-22

CLOSED

VA2-291 \*KHANH DUONG NEW 1244N 10845E  
(BQ562087)

(VMD)  
MACV 1400 35 (M8A1) 60' 15-33

CLOSED

---

VA3-292 TONLE CHAM 1136N 10629E (XT625822)

VNA 33 30 (LATERITE) 60' (TOV)

CLOSED/UNFRIENDLY

---

VA2-293 DUC LAP #2 1226N 10740E (YU906752)

VFR3/ND48-16/K-10A (DAP)  
VNA 2264 33 60' 08-26

Remarks: Opr SR-SS.

Hazards: 7' dirt embankment 50' S of Rwy  
midfield. Lateral clnc not avbl  
when R/W parked in arming pit  
midfield, S side. Cattle have  
free access to Rwy. 60' tree  
300' S of Rwy midfield.

Radio: Ctc as per 11 M. R. SOI-47.3

Open only to PC-6 and VTB when R/W  
parked on side or end of Rwy.

---

VA4-295 DONG TAM 1021N 10617E (XS408435)

VFR4/NC48-7/K-10D (VDT)  
VNA 5 H23 (ASP) 60' 17-35

Remarks: Opr SR-SS. Strong crosswinds  
prevalent. 100' ASP ovrn N end.  
150' gravel ovrn S end.

Hazards: App Rwy 17 over camp road, and  
ditch 140', 15' vertical pipe 90'  
rgt of centerline 135' prior to  
thld. App Rwy 35 has 3" lip  
btwn ovrn and Rwy. 8' drop-off  
W side N half of Rwy 25' fr edge.  
Adequate lateral clnc may not be  
aval when acft prkd on ramp  
which is 42' W of Rwy edges.  
220' microwave twr 1800' E.

Traffic Pattern: All tfc flown at 1000' W of  
afd.

Radio: Ctc as per DRAC SOI-47.3

Fuel: JP-4. Mini-Pump

CLOSED TO C-46, C-47

1 April 1973

135

SVN/CAMBI

VA3-297 BUNARD 1139N 10705E (YT273887)

VFR3/NC-48-4/K10D BNQ

VNA 948 26 (LATERITE) 35' 03-21

Remarks: Only immediate area secure.  
Oprs SR-SS. 110' ovrn NE, 115'  
SW. 150' x 165' turnaround NE  
end has ditch adj all sides. 45'  
wide twy to 270' x 430' prk area.  
PSP end and culvert touchdown  
mkr.

Hazards: Opposite end of Rwy not visible  
fr touchdown pt. Apch Rwy 03  
over low terrain, 3' fence 120'  
prior to thld. Steep drop-off at  
end of ea ovrn. Sharp upslope  
prior to both thld. 3' drainage  
ditches adj to Rwy shoulders.  
Terrain slopes upward on W side  
20' fr Rwy edge.

CLOSED TO C-46, C-47

---

VA2-301 TAN PHAT 1134N 10750E (ZT100810)

VFR3/NC48-8/K-10D

VDCA 2800 H42 (ASP) 100' 07-25

Remarks: Opr 2300-1000Z. Bao Lac tfc in area.

Hazards: Opposite ends of Rwy cannot be seen dur ldg. App Rwy 07-60' lip 400' prior to thld. App Rwy 25-12'-14' lip 240' prior to thld. Pedestrians and vehicles have free access to Rwy.

Radio: Ctc 47.3

---

VA4-302 NAM CAN 0845N 10459E (VQ988674)

VFR4/NC 48-15/K10D

N 6 28 (M8A1) 71' 09-27

Remarks: Bears 207° 29 NM from Camau. Opr SR-SS. Acft will not land over active R/W ops without direct radio etc. Helipad 135' prior to thld.

Hazards: App Rwy 09 over 75' trees 200' and 4' lip prior to thld. App Rwy 27 (steep app rprd) over 150' antenna 500', 100' antenna 150', 50' antenna and poles in camp area. Watch for vehicles. Parking limited to 1 acft at a time.

Traffic Pattern: Recommend land Rwy 09, tkof Rwy 27, winds permitting. Overhead let down to avoid possible gnd fire.

Navy NAM CAN NOC - 47.3 LAW DRAC SOI

CLOSED TO C-46.

---

1 April 1973

137

SVN/CAMBI

3. HELIPORT INDEX-ALPHABETICAL

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
AN DIEM	VH1-500	ZC 085572
AN HOA	VH1-501	AT 873467
AN LAU	VH1-502	BT 221073
AN LONG	VH4-503	WS 400885
AN PHU	VH4-504	WS 106945
AP BAC	VH4-505	XS 153727
AROH	VH1-507	YC 815848
ATOU	VH1-508	YC 516495
BACH MA	VH1-514	ZC 059927
BA DUA	VH4-509	XS 240432
BA LONG	VH1-510	YD 155401
BAO TRAI	VH3-515	XT 513039
BA TRI	VH4-512	XS 46103
BARIA	VH3-511	YS 384622
BEARCAT	VH3-738	YT 162003
BE LOUNG	VH1-516	YC 583887
BEN CAT	VH3-517	XT 744331
BEN GIANG	VH1-518	YC 976366
BEN KEO	VH3-519	XT 236434
BEN LUC	VH3-766	XS 625765
BEN SUC	VH3-520	XT 575335
BEN TRANH	VH4-710	XS 474551
BEN TRE	VH4-521	XS 513317
BIEN HOA	VH3-522	XT 990105
BINH	VH3-754	XS 761784
BINH DIA	VH4-523	XS 857273
BINH GIA	VH3-524	YS 490777
BINH PHUOC	VH3-525	XS 611550
BINH TAN	VH4-711	XS 818405
BINH TAN TAN	VH4-712	WS 860035
BINH THUY	(Unnumbered)	WS 830130
BLACKHORSE	VH3-763	YT 062122
BOUN BENG	VH2-526	BQ 235820
BU DANG	VH3-527	YU 458065
BU DOP	VH3-528	XU 975225
BU GHIA	VH3-529	YU 185135
BU JA MOP	VH3-530	YU 344377

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
BU PRANG	VH2-531	YU 522545
CAI BE	VH4-533	XS 134424
CAI CAI	VH4-534	WT 620000
CAI LAY	VH4-535	XS 228504
CAI MON	VH4-536	XS 338285
CAI NHUM	VH4-537	XS 220245
CAI NUOC	VH4-538	VQ 849818
CA LU	VH1-532	YD 244597
CAM 77	VH3-539	XS 771988
CAMP EAGLE	VH1-751	YD 810149
CAMP MCDERMOTT (Unnumbered)		CP 051501
CAMP TRAN HUNG		
DAO	VH3-768	XT 7007
CAN DUOC	VH3-540	XS 758609
CAN GIO	VH3-541	YS 165518
CAN GIUOC	VH3-542	XS 831730
CAO LANH	VH4-543	WS 697558
CAU KE	VH4-544	XR 160913
CAU NGANG	VH4-545	XR 594826
CAU SOI	VH1-546	ZC 038310
CAU VIET	VH1-547	YD 332692
CHAU DOC	VH4-548	WS 136830
CHO GAO	VH3-550	XS 229342
CHON THANH	VH3-551	XT 767623
CORPUS CHRISTI		
BAY	VH2-742	YS 245455
CU CHI	VH3-552	XT 628125
DA BAC	VH1-553	ZD 055021
DA DAN	VH1-554	XD 962328
DAI DIEN	VH4-715	XS 591058
DAK DOA	VH2-555	AR 909675
DAM DOI	VH4-558	WQ 1291
DANANG	VH1-513	BT 0175
DEPCORDS TRAC	VH3-767	XT 999098
DIEM TRUONG	VH1-559	ZD 027143
DINH THANH	VH4-560	WR 295945
DONG BA THIN	VH2-739	CP 027295
DONG HOA	VH3-757	YS 063478
DONG TAM	VH4-752	XS 415448

1 April 1973

139

SVN/CAMBI

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
DONG TRE	VH2-561	BQ 909704
DONG XOAI	VH3-562	YT 075755
DUC HOA	VH3-563	XS 598968
DUC LONG	VH4-716	WR 590779
DUC PHO	VH1-564	BS 810385
DUNG LONG	VH1-565	YD 032452
EAGLE FARM	VH3-743	YS 442673
EMBASSY (U.S.)	VH3-749	XS 863922
FREE WORLD (SAIGON)	VH3-750	XS 835912
GIA DINH	VH3-756	XS 859945
GIA RAY	VH3-566	YT 636126
GIA RIA	VH4-567	WR 513213
GIAO DUC	VH4-568	WS 978403
GIONG TROM	VH4-569	XS 656219
GO CONG	VH3-570	XS 840460
GO DAU HA	VH3-571	XT 390250
GO QUAO	VH4-717	WR 306749
HAI LANG	VH1-573	YD 415482
HAM LONG	VH4-574	XS 367354
HAM TAN (MAAG)	VH3-575	ZS 045800
HAWK HILL (HILL 29)	VH1-714	BT 226320
HEADQUARTERS USARV	VH4-744	YT 038056
HIEP DUC	VH1-576	AT 912246
HIEU DUC	VH1-577	AT 929712
HIEU DUC	VH1-578	AT 935688
HIEU LIEM	VH3-579	YT 149285
HILL 40	VH1-580	AT 915692
HILL 59	VH1-581	BT 164233
HILL 60	VH1-582	AT 881578
HILL 69	VH1-583	BT 470070
HILL 76	VH1-584	BT 429072
HOA BINH	VH3-718	XS 787384
HOA CAM	VH1-585	AT 977729
HOA LONG	VH4-586	WS 727370
HOC MON	VH3-587	XT 755039
HOI AN	VH1-588	BT 146573

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
HONG NGU	VH4-590	WS 375945
HON QUAN	VH3-589	XT 760892
HUONG MY	VH4-592	XS 542070
KANGAROO	VH3-737	YS 434670
KE SACH	VH4-719	XR 085798
KHAI QUANG	VH4-593	WR 023300
KHE SANH	VH1-594	XD 858384
KHE TRE	VH1-595	YC 9189
KIEN BINH	VH4-596	WR 310980
KIENG PHUOC	VH3-598	XS 912488
KIEN TIEN	VH4-599	WP 480585
KINH CUNG	VH4-720	WS 960760
KON MAHAR	VH2-600	BR 045852
KONTUM (22d DIV FWD)	VH2-506	AR 779879
KONTUM (DISTRICT)	VH2-597	ZA 198900
KONTUM	VH2-601	AR 770894
KONTUM (SECTOR)	VH2-591	AR 778888
LAI KHE	VH3-753	XS 8095
LAM SON	VH3-632	XT 845148
LANE (AN SON) ARMY	VH2-713	BR 946265
LANG CHANH	VH1-602	XD 845415
LAP VO	VH4-603	WS 577455
LASSITER	VH3-755	YT 016153
LI TINH	VH1-604	BT 477081
LOC NINH	VH3-605	XU 737095
LONG BINH SUPPLY DEPOT	VH3-740	YT 046075
LONG BINH DEPOT (Unnumbered)		YT 085101
LONG BINH (24th EVAC HOSPITAL) (Unnumbered)		YT 046076
LONG DINH	VH4-606	XS 381496
LONG HAI	VH3-607	YS 449493
LONG KHANH	VH4-608	XR 590610
LONG KHOT	VH4-609	WT 917074
LONG MY	VH4-722	WR 631697
LONG PHU	VH4-610	WR 755666

1 April 1973

141

SVN/CAMBI

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
LONG PHU	VH4-723	XR 242619
LONG TOAN	VH4-611	XR 645630
LONG XUYEN	VH4-612	WS 485475
MAU CA	VH1-613	BS 044991
ME ANN	VH4-614	WS 933630
MO CAY	VH4-616	XS 463196
MOI LOI	VH3-709	XS 800563
MU DUC	VH1-617	BS 711625
MY AN	VH4-708	WS 933636
MY CHANH	VH1-618	YD 046339
MY PHUOC TAY	VH4-619	XS 203598
MY THO	VH4-620	XS 492449
NAI VAN	VH1-622	AT 933915
NAM CAN	VH4-621	WQ 0278
NEWPORT	VH3-758	XS 890950
NGA BA	VH1-623	YD 141693
NGOKTI	VH1-624	YB 930860
NHA BE	VH3-746	XS 937798
NHON NINH	VH4-724	XS 044746
NONG SON	VH1-625	AT 823394
NONG SON	VH1-626	AT 876399
NUI DAT (DUST OFF) PAD	VH3-736	YS 435668
OP #7	VH1-627	BT 164233
PHAN RANG	VH2-628	BN 770830
PHONG PHU	VH4-725	WS 688180
PHO TRACH	VH1-629	YD 525349
PHU CAT	VH2-630	BR 908477
PHU GIA	VH1-631	AT 845995
PHUNG HIEP	VH4-726	WR 906843
PHUOC CAM	VH1-634	BT 094301
PHUOC CHAU	VH1-635	BT 005095
PHUOC HA	VH1-636	BT 036216
PHUOC LAM	VH1-637	BT 073061
PHUOC LONG	VH4-638	WR 489422
PHUOC SON 1	VH1-639	BT 094201
PHUOC SON 2	VH1-640	AT 854217
PHUOC TIEN	VH1-641	BT 182153
PHUOC TUONG	VH1-642	ZD 118013

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
PHU THANH	VH3-663	YS 032870
PLEI DJIRING	VH2-644	AN 810800
PLEI DJRANG	VH2-645	YA 859531
PLEIKU (ARVN HOSP)	VH2-647	AR 770460
PLEIKU	VH2-648	ZA 239512
PLEIKU	VH2-649	ZA 240501
QUANG TIN	VH1-650	BT 292229
QUANG TRI	VH1-651	YD 328526
QUANG ZUYEN	VH3-759	XS 962713
QUE SON	VH1-652	BT 042349
RACH GIA	VH4-741	XS 410153
RED CARPET	VH3-764	YT 048106
RO	VH1-653	ZC 042233
(ROKA LOGISTICAL COMMAND)	VH2-760	CP 022584
SABRE	VH3-765	XT 901062
SA DEC	VH4-654	WS 845384
SAIGON (HOTEL-3)	VH3-707	XS 810946
SAINT KILDA	VH3-747	YS 298438
SONG BE	VH3-655	YU 183112
SONG ON DOC	VH4-727	VQ 804986
SUOI DA	VH3-656	XT 331575
TAC VAN	VH4-728	WR 296130
TAKO	VH1-659	YC 530525
TALON	VH1-660	YC 886325
TA LUONG	VH1-658	YD 553027
TAM BINH	VH4-661	XS 090118
TAM KY	VH1-662	BT 307216
TAM LICH	VH1-663	YD 197727
TAN AN	VH4-664	WS 204045
TAN AN	VH3-665	XS 543650
TAN AN (TNG CEN)	VH4-666	WS 650580
TAN BA	VH3-667	XT 935140
TAN CANH	VH2-668	ZB 054218
TAN CHAU	VH4-669	WS 265935
TANG HOA	VH3-675	XS 880408
TAN HUNG	VH4-729	WQ 141973
TAN NIEN TAY	VH3-670	XS 884495

1 April 1973

143

SVN/CAMBI

<u>NAME</u>	<u>VH-NUMBER</u>	<u>UTM</u>
TAN PHU	VH4-671	WR 195410
TAN TRU	VH3-673	XS 669631
TAN UYEN	VH3-674	XT 965230
THAC NUC	VH1-676	ZC 029229
THANH BINH	VH4-677	WS 545660
THANH HOA	VH1-678	BT 328115
THANH MY	VH1-679	ZC 026439
THANH PHU	VH4-680	XR 668999
THAT SON	VH4-681	WS 020650
THIEN PHUOC	VH1-682	BT 113137
THOI BINH	VH4-730	WR 109335
THOT NOT	VH4-683	WS 588352
THUAN HOA	VH4-731	WR 893648
THUAN NHON	VH4-732	WR 648971
THUAN TRUNG	VH4-733	WR 476156
THU DUC	VH3-761	XT 922000
TIEU CAN	VH4-685	XR 305845
TIGER 5	VH3-748	YS 438685
TINH BIEN	VH4-686	VS 940725
TRA BONG	VH1-687	BS 348378
TRA ON	VH4-688	XS 016014
TRAM VANG	VH3-689	XT 414270
TRANG BANG	VH3-690	XT 490190
TRANG SUP	VH3-691	XT 177550
TRI TON	VH4-692	WS 005520
TRIEU PHOUNG	VH1-693	YD 340538
TU CAM	VH1-694	BT 175225
TUY HOA	VH2-695	CQ 180480
VAN CANH	VH2-696	BR 835070
VIET AN	VH1-697	BT 028286
VINH CHAU	VH4-698	XR 082311
VINH GIA	VH4-699	VS 766609
VINH KIM	VH4-700	XS 369477
VINH LOI	VH3-701	XS 734437
VINH QUOI	VH3-734	WR 660570
VUNG LIEM	VH3-702	XS 304158
XUAN HOA	VH1-703	YD 111700
XUAN LOC	VH3-704	YT 460094
XUYEN MOC	VH3-705	YS 655690
YANKEC	VH2-706	BP 010460
1-April 1973	144	SVN/CAMBI

4. VIETNAM HELIPIRT INFORMATION

AN DIEM HELIPIRT, 1553N 10753E (ZC085572)  
66 VH1-500

AN HOA HELIPIRT, 1547N 10805E (AT873467)  
49 VH1-501

Fuel: Refueling point at Danang. Emerg fuel aval  
for F/W acft.

AN LAU HELIPIRT, 1522N 10825E (BT221073)  
115 VH1-502

AN LONG HELIPIRT, 1045N 10522E (WS400885)  
7 (SOD) VH4-503

AN PHU HELIPIRT, 1047N 10506E (WS106945)  
10 (WOODEN) VH4-504

Remarks: End of F/W strip, by compound.

AP BAC HELIPIRT, 1037N 10603E (XS153727)  
7 (SOD) VH4-505

Remarks: Confined, barbed wire and antennas.

AROH HELIPIRT, 1608N 10739E (YC815848)  
427 VH1-507

ATOU HELIPIRT, 1549N 10722E (YC516495)  
3740 VH1-508

BACH MA HELIPIRT, 1612N 10752E (ZC059927)  
4003 VH1-514

BA DUA HELIPIRT, 1021N 10608E (XS240432)  
7 (EARTH) VH4-509

Remarks: Check security.

BA LONG HELIPIRT, 1638N 10702E (YD155401)  
65 VH1-510

1 April 1973

145

SVN/CAMBI

BAO TRAI HELIPIORT, 1053N 10623E (XT513039)  
 17 \*L (UNK) VH3-515

BA TRI HELIPIORT, 1003N 10636E (XS46103)  
 10 (EARTH) VH4-512  
 Remarks: May also land on dusty road.

BARIA HELIPIORT, 1031N 10711E (YS384622)  
 17 \*L (SOCCER FIELD) VH3-511  
 Fuel: J4  
 Tower: 124.7 40.7

BEARCAT HELIPIORT, 1051N 10659E (YT162003)  
 164 1986' x 100' VH3-738  
 (CON/RC-3)  
 1986' x 100'  
 (CON/RC-3)  
 Remarks: Heliport divided into two nearly equal  
 heliports by bldg and roads.

BE LOUNG HELIPIORT, 1610N 10725E (YC583887)  
 1903 VH1-516

\*BEN CAT HELIPIORT, 1109N 10636E (XT744331)  
 17 \*L (UNK) VH3-517  
 Fuel: J4 Tanker  
 \*ICCS/UH-1H

BEN GIANG HELIPIORT, 1542N 1074E (YC976366)  
 558 VH1-518

BEN KEO HELIPIORT, 1115N 10608E (XT236434)  
 33 (SOCCER FIELD) VH3-519

BEN LUC HELIPIORT, 1038N 10629E (XS625765)  
 5 VH3-766  
 Remarks: Opr 2400-1200Z dly.

BEN SUC HELIPIORT, 1109N 10722E (XT575335)  
 VH3-520

1 April 1973 146 SVN/CAMBI

BEN TRANH HELIPOINT, 1027N 10621E (XS474551)  
7 (SOCCER FIELD) VH4-710

BEN TRE HELIPOINT, 1014N 10623E (XS513317)  
16 (SCOOER FIELD) VH4-521  
Remarks: Reserved for VIP only.

BIEN HOA (SPARTAN) HELIPOINT,  
1037N 10649E (XT990105)  
VNAH (A) 36 L 1ea 1000' x 140' (PSP) VH3-522  
6ea 900 x 120 (ASP) Lanes and others

Fuel: J4 Check availability

Remarks: CAUTION-Hvy tfc. Opr 2100-1500Z.  
HAZARDS-Con twr 84' to all ops fr lane  
#4. Micro-wave ant 203' AGL 1/8 mi  
NNE of Soccer Fld.

Traffic Pattern: No left tfc at main heliport when  
ldg to S. (Left tfc only to Soccer  
Fld.) Refer to ES.

Communications

Spartan Tower: 321.0 121.4 35.2 2901.5 USB  
Opr 2100-1500Z

GND CON: 282.9 (E)

BINH CHANH, 1039N 10637E (XS761784)  
10 VH3-754  
Remarks: PSP Pad outside compound.

BINH DIA HELIPOINT, 1012N 10642E (XS857273)  
7 (SOD) VH4-523  
Remarks: Wires on South.

BINH GIA HELIPOINT, 1039N 10717E (YS490777)  
350 \*L (CHURCH YARD) VH3-524

BINH PHUOC HELIPOINT, 1027N 10629E (XS611550)  
7 VH3-525

BINH TAN HELIPOINT, 1019N 10640E (XS818405)  
3 (EARTH ROAD) VH4-711

1 April 1973

147

SVN/CAMBI

BINH TAN TAN HELIPORT, 1000N 10547E (WS860035)  
7 (EARTH) VH4-712

Remarks: Obstructions S & W. Dusty.

BINH THUY HELIPORT, 1004N 10544E (WS830130)  
VNAF 9 L4 1900' x 100' (M8A1/ASP)

Fuel: J4

Remarks: Extv copter tfc. No F/W acft. All tfc remain SE of fld. Tran prk ltd to 3 acft. HAZARDS: Apch Rwy 21 over river, 20' bldg 300', 10' fence 150' NE of thld. 76' lgtd twr 145' S of N end. 80' power poles 100' rgt and left of apch 150' prior to thld. Apch Rwy 03 over 40' poles 700' 20' bldg 300', 10' fence 125' SW of thld. Periodic LST masts and crane barges on river.

Traffic Pattern: Rgt tfc Rwy 03, left tfc Rwy 21.

Tower: Ctc Binh Thuy twr for advsy 312.0 118.1 34.2

BLACKHORSE HELIPORT, 1058N 10654E (YT062122)  
156 (UNK) 05-23 VH3-763

BOUN BENG HELIPORT, 1324N 10827E (BQ235820)  
623 VH2-526

BU DANG HELIPORT, 1149N 10715E (YU458065)  
853 (SOCCER FIELD) VH3-527

Remarks: Trees border West side.

BU DOP HELIPORT, 1158N 10649E (XU975225)  
7 (EARTH) VH3-528

CLOSED, INSECURE.

BU GHIA HELIPORT, 1153N 10700E (YU185135)  
565 VH3-529

BU JA MOP HELIPORT, 1206N 10709E (YU344377)  
1260 \*L NE end of air strip VH3-530