

DECLASSIFIED
Authority <u>MWD 9276 2.2</u>
By <u>MWD</u> NARA Date <u>7/9/76</u>

CONFIDENTIAL

AVHAV-OPT (29 Jun 68)

S-7 Jul 68


SUBJECT: Analysis and Evaluation of Operational Report - Lessons Learned for
the 52nd Combat Aviation Battalion (U)

TO: G3

FROM: Aviation

DATE: 4 JUL 1968 CMT 2
MAJ Scoggins/db/LBN 6786

1. (U) Attached ORLL, 52nd Combat Aviation Battalion, for the quarterly period ending 30 April 1968, has been reviewed in accordance with Comment 1.
2. (C) Reference item concerning UH-1H transmission input quill seal, page 70, paragraph G(1). Concur. The proper maintenance procedure is to determine if the component can be repaired locally before the shaft is turned in and a replacement item installed. Bell Helicopter Company and USAAVCOM are investigating this problem area. Units should continue to submit an EIR when the problem is encountered. No further action by higher headquarters is recommended.



EUGENE M. LYNCH
Colonel, Infantry
Deputy Aviation Officer

2 Incl
nc

DECLASSIFIED	
Authority <u>MND 927622</u>	
By <u>MSD</u> NARA Date <u>7/9/76</u>	

CONFIDENTIAL

AVHGC-DST (10 May 68) 4th ind (C)

CPT Arnold/ms/LBN 4485

SUBJECT: Operational Report for quarterly period ending 30 April 1968,
1 CAV/CFOR-65 (R) (C)

HEADQUARTERS, US ARMY VIETNAM, APO San Francisco 96375

JUL 1968

TO: Commander in Chief, United States Army, Pacific, ATTN: CPOP-DT,
APO 96558

1. (U) This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1968 from Headquarters, 52d Combat Aviation Battalion.

2. (C) Reference item concerning UH-1H transmission input quill seal, page 70, paragraph C(1): Concur. The proper maintenance procedure is to determine if the component can be repaired locally before the shaft is turned in and a replacement item installed. Bell Helicopter Company and USAIVCOM are investigating this problem area. Units should continue to submit an EIR when the problem is encountered.

FOR THE COMMANDER:

6 Incl
nc

C. S. NAKATSUKASA
 Captain, AGC
 Assistant Adjutant General

Copies furnished:
 H, 52d Cbt Avn Bn
 H, 1st Avn Bde528-03
DODMFR: ORLL was staffed through:
 Avn MAJ Scoggins/6786

ACTION OFFICER: CPT ARNOLD/LBN 4485

CH DST DIV	<i>AC</i>
CH MS BR	
CH DOC BR	<i>C</i>
CH TNG BR	
A/O	<i>dn</i>

RMP

AS