

APPENDIX

APPENDIX 1

AWARDS AND DECORATIONS

<u>Decoration</u>	<u>Number Presented</u>
Silver Star	11
Distinguished Flying Cross	37
Bronze Star Medal	16
Air Medal	120
Air Force Commendation Medal	40
Purple Heart	1
Total	225

Sanitary Unit, Apr-Jun 1971

APPENDIX 2

COMBAT/Non-COMBAT SAVES

	<u>Combat</u>	<u>Non-Combat</u>	<u>Totals</u>
April	11	13	24
May	5	12	17
June	10	1	11
	26	26	52

TOTAL SAVES

FOR 1971

83

41

124

TOTAL SAVES

SINCE

1 DEC 1969

207

107

326

3 May 1964, 10:00-11:00

25

EXPERIMENT 3

DURING HOURS

	<u>HE-127/2</u>	<u>HE-227/2</u>	<u>HE-122/2</u>	<u>TOTAL</u>
April	633.3	716.5	1021.0	2370.8
May	594.5	657.6	1118.5	2370.6
June	647.1	816.5	1105.1	2568.7
Total	1874.9	2390.6	3244.6	7510.1

STANDARD TESTS

<u>Date</u>	<u>Test Name</u>	<u>Action</u>
8 - 12 June	Det 4, 100000	1. Initial flight. Spot check of test.
12 - 14 June	Det 4, 100000	2. Initial performance checks (1. Initial flight examiner and 1. Initial proficiency.) Spot check of results.
15 - 16 June	Det 4, 100000	Spot check of results.
17 - 18 June	Det 4, 100000	Spot check of results.
19 - 20 June	Det 4, 100000	Spot check of results.
21 - 23 June	Det 4, 100000	2. Review for aircraft examiner upgrade (1. Initial flight examiner and 1. Initial proficiency.) Spot check of results.

7-11-66

31

NOV 1966

RECEIVED

NAME	NAME	NAME	NAME
NO-1301	66-194	7 Apr	3 Jul
NO-1302	66-215	19 Apr	5 Jun
NO-1303	66-215	17 May	21 Jul
NO-1304	66-212	25 Jun	9 Apr

APPENDIX 6

APPENDIX 6, LISTING OF CASES, 10/10/1961

<u>Case</u>	<u>File Number</u>	<u>Ex-101</u>	<u>Ex-102</u>
FO-1302	66-213	29 Jul	12 Jul
FO-1304	66-215	2 Aug	31 Jul

REPORT

ANALYSIS OF THE RESULTS OF THE

<u>Type</u>	<u>Mail Number</u>	<u>Number of Inspections</u>
HC-130P	65-923	3
HC-130P	66-215	2
HC-130P	65-991	2
HC-130P	66-212	2
HC-130P	66-213	2
HC-130P	66-214	2
HC-130P	66-215	2
HC-130P	66-216	2
HC-130P	66-217	2
HC-130P	66-218	2
HC-130P	66-219	2
HC-130P	66-220	2
HC-130P	66-221	2
HC-130P	66-222	2
HC-130P	66-223	2
HC-130P	66-224	2
HC-130P	66-225	2
HC-130P	66-226	2
HC-130P	66-227	2
HC-130P	66-228	2
HC-130P	66-229	2
HC-130P	66-230	2
HC-130P	66-231	2
HC-130P	66-232	2
HC-130P	66-233	2
HC-130P	66-234	2
HC-130P	66-235	2
HC-130P	66-236	2
HC-130P	66-237	2
HC-130P	66-238	2
HC-130P	66-239	2
HC-130P	66-240	2
HC-130P	66-241	2
HC-130P	66-242	2
HC-130P	66-243	2
HC-130P	66-244	2
HC-130P	66-245	2
HC-130P	66-246	2
HC-130P	66-247	2
HC-130P	66-248	2
HC-130P	66-249	2
HC-130P	66-250	2
HC-130P	66-251	2
HC-130P	66-252	2
HC-130P	66-253	2
HC-130P	66-254	2
HC-130P	66-255	2
HC-130P	66-256	2
HC-130P	66-257	2
HC-130P	66-258	2
HC-130P	66-259	2
HC-130P	66-260	2
HC-130P	66-261	2
HC-130P	66-262	2
HC-130P	66-263	2
HC-130P	66-264	2
HC-130P	66-265	2
HC-130P	66-266	2
HC-130P	66-267	2
HC-130P	66-268	2
HC-130P	66-269	2
HC-130P	66-270	2
HC-130P	66-271	2
HC-130P	66-272	2
HC-130P	66-273	2
HC-130P	66-274	2
HC-130P	66-275	2
HC-130P	66-276	2
HC-130P	66-277	2
HC-130P	66-278	2
HC-130P	66-279	2
HC-130P	66-280	2
HC-130P	66-281	2
HC-130P	66-282	2
HC-130P	66-283	2
HC-130P	66-284	2
HC-130P	66-285	2
HC-130P	66-286	2
HC-130P	66-287	2
HC-130P	66-288	2
HC-130P	66-289	2
HC-130P	66-290	2
HC-130P	66-291	2
HC-130P	66-292	2
HC-130P	66-293	2
HC-130P	66-294	2
HC-130P	66-295	2
HC-130P	66-296	2
HC-130P	66-297	2
HC-130P	66-298	2
HC-130P	66-299	2
HC-130P	66-300	2

Three inspections of the 31418g at Clark AB, Philippines.

3 May 71, 10:00 AM

MEMO

TO: CHIEF, ENGINEERING

The following one-time inspections were performed on the HH-43 helicopters:

1. One-time inspection of the Cargo Manual Release - 13023000 May 71 message from HLRNG and ARRS/DAF 222010Z May 71.
2. One-time inspection of the H-53 Engines on both HH-43 B and F aircraft for installation of tailcone W/T 1-010-150-01 or 1-010-200-01.

ARRS/DAF 204615Z Apr 71.

3. One-time inspection of HH-43/F stability control units - ARRS/DAF 204615Z Apr 71.

The following one-time inspections were performed on HH-43 aircraft:

2. Generator Efficiency Test - ARRS/DAF 222010Z May 71 or 322 010 010 010.

These one-time inspections were accomplished because of MTRs submitted and considered pertinent enough to warrant a one-time inspection by the 3040p.

SECRET, 1971

UNCLASSIFIED

41

APPENDIX 2

RESEARCH PROJECT

	<u>HC-130/7</u>	<u>HC-530/6</u>	<u>HC-130/8</u>	<u>Total</u>
April	0	1	0	1
May	0	0	0	0
June	0	1	0	1
	<u>0</u>	<u>2</u>	<u>0</u>	<u>2</u>

UNCLASSIFIED

[illegible]

Form number	2	2
Department of Health and Social Services, New York State		
Administrative	1	1
Form No. 100-1 (Rev. 1-75)	(1)	(1)

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS MILITARY AIRLIFT COMMAND
SCOTT AIR FORCE BASE, ILLINOIS 62225

SPECIAL ORDER
G-227

26 May 1971

1. By order of the Secretary of the Air Force, the 33d Aerospace Rescue and Recovery Squadron, having been assigned to MAC, is activated at Kadena AB, Ryukyu (LXEZ) effective 1 July 1971, and further assigned to the 41 ARRWg. Any future redesignation or inactivation of this unit will be accomplished by Hq USAF. Upon activation, the 33d Aerospace Rescue and Recovery Squadron is entitled to all honors and approved emblems belonging to the unit inactivated 1 Oct 1970. Historical data, including information on all honors and approved emblems will be forwarded automatically to MAC by the USAF Historical Division, Air University. Any flag or streamers authorized for this unit may be requisitioned in accordance with current directives. Manpower authorizations will be in accordance with the Unit Detail Listing (UDL). Personnel will be requisitioned in accordance with AFMs 36-11/39-11. Equipment will be authorized in accordance with EAID 0033AER70000. The PAS is KBQVZF. Personnel data changes will be required in accordance with AFM 30-3. Action will be reported in accordance with AFR 20-49. Authority: Hq USAF Ltr, DAF/PRM 436p, 18 May 1971, Organization Actions Affecting Certain Military Airlift Command Units and AFM 26-2.

2. The following dets are designated and activated at locations indicated effective 1 July 1971.

<u>Det</u>	<u>Location & Base Code</u>	<u>EAID</u>	<u>PAS</u>
Det 1, 33 ARRSq	Osan AB, Korea (SMYU)	0033AER70001	OPQVY7
Det 2, 33 ARRSq	Kunsan AB, Korea (MLWR)	0033AER70002	KUQNSJ
Det 1, 3 ARRGp	Phan Rang AB, Vietnam (TDTE)	0033AER60001	PRQHFFQ
Det 3, 3 ARRGp	Ubon Afd, Thailand(XMPA)	0033AER60003	UBQHFS
Det 4, 3 ARRGp	Korat AB, Thailand(MLER)	0033AER60004	KZQHFT
Det 5, 3 ARRGp	Udorn Afd, Thailand (XMTG)	0033AER60005	UDQHFFV
Det 6, 3 ARRGp	Bien Hoa AB, Vietnam (BNPQ)	0033AER60006	BKQHFW
Det 7, 3 ARRGp	Da Nang Aprt, Vietnam (EZEM)	0033AER60007	DAQHFX
Det 9, 3 ARRGp	Nakhon Phanom Aprt, Thailand (RFCV)	0033AER60009	NAQJRW
Det 12, 3 ARRGp	U-Tapao Afd, Thailand (UYZP)	0033AER60012	UCQKXT
Det 13, 3 ARRGp	Phu Cat AB, Vietnam (TWCZ)	0033AER60013	PQQNQ3

G-227

30 G-227, DAF, HQ MAC, SCOTT AFB, IL 62225, 26 May 71

Para 2 (Continued)

Det 14, 3 ARRGp Tan Son Nhut AB, Vietnam 0003AER60014 TDQPXG
(WRMC)

Manpower authorizations will be in accordance with the Unit Detail Listing (UDL). Personnel will be requisitioned in accordance with AFMs 36-11/39-11. Personnel data changes will be required in accordance with AFM 30-3. Action will be reported in accordance with AFR 20-49. Authority: AFM 26-2.

FOR THE COMMANDER



ROBERT R. OSBORN, Colonel, USAF
Director of Administration

DISTRIBUTION:

- 1 - HQ USAF (AFDASA), 5240 Port Royal Road, Springfield, VA 22151
HQ USAF (AFADSA; AFADSLD3; AFOMOM)
USAFMPC (AFPMSAU); SAAMA (SANTTB)
- 2 - HQ USAF (AFOAPO; AFDG); USAFMPC (AFPMC); AU Library;
MACMET TRAVIS; 89 MAWg; 89 MAWg (PDP); 443 MAWg; MAC/DAPO, CSEH
- 3 - HQ USAF (AFMSG); MACMET MCGUIRE; 375 AAWg; MAC/SGE, ICE
- 7 - ARPC (PRCAS)
- 5 - 21AF(DA); 22AF(DA); 41 ARRWg; 436 MAWg/DAD; 438 MAWg (DASO);
AAVS; Each unit concerned; Comdr, each base concerned;
MACMET SCOTT; MAC/DE
- 1 - MAC/HC, JA, CSB, OA, 14OODAA (STOP 201), 14OODAD (STOP 253),
14OOAC (STOP 225), CBPO-PROC (STOP 208), AGRO, SCOTT AFB, IL
- 6 - MAC/DA, ACE
- 11 - MAC/DOE
- 22 - MAC/DME
- 10 - MAC/XPE
- 20 - MAC/DPE
- 20 - AWSDAF
- 4 - ACGS (ACGVH)
- 7 - ARRS
- 5 - 41 ARRWg; 3 ARRGp; PACAF; MACMET Hickam

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS MILITARY AIRLIFT COMMAND
SCOTT AIR FORCE BASE, ILLINOIS 62225

SPECIAL ORDER
G-228

28 May 1971

1. By order of the Secretary of the Air Force, the following squadrons are inactivated at locations indicated effective 1 July 1971.

<u>Unit</u>	<u>Location</u>	<u>EAID Voided</u>
38th Aerospace Rescue and Recovery Squadron	Tan Son Nhut AB, Vietnam	0038AER70000
47th Aerospace Rescue and Recovery Squadron	Fuchu AS, Japan	0047AER70000

Concurrently, the unit designation reverts to the control of the Department of the Air Force. Personnel will be reassigned in accordance with AFMs 36-11/39-11. Organizational documentation will be disposed of in accordance with AFM 12-50. Organizational funds will be disposed of in accordance with AFR 176-2. Personnel data changes will be required in accordance with AFM 30-3. Action will be reported in accordance with AFR 20-49. Authority: Hq USAF Ltr, DAF/PRM 436p, 18 May 1971, Organization Actions Affecting Certain Military Airlift Command Units and AFM 26-2.

2. The following dets and OL are inactivated at locations indicated effective 1 July 1971.

<u>Det/OL</u>	<u>Location</u>	<u>EAID Voided</u>
Det 1, 38 ARRSq	Phan Rang AB, Vietnam	0038AER70001
Det 3, 38 ARRSq	Ubon Afd, Thailand	0038AER70003
Det 4, 38 ARRSq	Korat AB, Thailand	0038AER70004
Det 5, 38 ARRSq	Udorn Afd, Thailand	0038AER70005
Det 6, 38 ARRSq	Bien Hoa AB, Vietnam	0038AER70006
Det 7, 38 ARRSq	Da Nang Aprt, Vietnam	0038AER70007
Det 9, 38 ARRSq	Nakhon Phanom Aprt, Thailand	0038AER70009
Det 12, 38 ARRSq	U-Tapao Afd, Thailand	0038AER70012
Det 13, 38 ARRSq	Phu Cat AB, Vietnam	0038AER70013
Det 14, 38 ARRSq	Tan Son Nhut AB, Vietnam	0038AER70014
Det 5, 47 ARRSq	Clark AB, Philippines	0047AER70005
Det 6, 47 ARRSq	Kadena AB, Ryukyu	0047AER70006
Det 9, 47 ARRSq	Osan AB, Korea	0047AER70009
Det 11, 47 ARRSq	Kunsan AB, Korea	0047AER70011
Det 12, 47 ARRSq	Andersen AFB, Guam	0047AER70012
Det 13, 41 ARRWg	Osan AB, Korea	0041AER50013
Det 14, 41 ARRWg	Kadena AB, Ryukyu	0041AER50014
OL B, 3 ARRGp	Udorn Afd, Thailand	0003AER60000

SO G-228, DAF, HQ MAC, SCOTT AFB, IL 62225, 28 May 71

Para 2 (Continued)

Personnel will be reassigned in accordance with AFMs 36-11/39-11. Organizational documentation will be disposed of in accordance with AFM 12-50. Organizational funds will be disposed of in accordance with AFR 176-2. Personnel data changes will be required in accordance with AFM 30-3. Action will be reported in accordance with AFR 20-49. Authority: AFM 26-2.

FOR THE COMMANDER



ROBERT R. OSBORN, Colonel, USAF
Director of Administration

DISTRIBUTION:

- 1 - HQ USAF (AFDASA), 5240 Port Royal Road, Springfield, VA 22151
HQ USAF (AFADSA; AFADSLD3; AFOMOM)
USAFMPC (AFFMSAU); SAAMA (SANTTB)
- 2 - HQ USAF (AFOAPO; AFPDG); USAFMPC (AFFMC); AU Library;
MACMET TRAVIS; 89 MAWg; 89 MAWg (PDP); 443 MAWg; MAC/DAPO, CSEH
- 3 - HQ USAF (AFMSG); MACMET MCGUIRE; 375 AAWg; MAC/SGE, IGE
- 7 - ARPC (PRCAS)
- 5 - 21AF(DA); 22AF(DA); 41 ARRWg; 436 MAWg/DAD; 438 MAWg (DASO);
AAVS; Each unit concerned; Comdr, each base concerned;
MACMET SCOTT; MAC/DE
- 1 - MAC/HC, JA, CSB, OA, 14OODAA (STOP 201), 14OODAD (STOP 253),
14OOAC (STOP 225), CBPO-PROC (STOP 208), AGRO, SCOTT AFB, IL
- 6 - MAC/DA, ACE
- 12 - MAC/DOE
- 22 - MAC/DME
- 19 - MAC/XPE
- 20 - MAC/DPE
- 20 - AWSRAP
- 4 - ACGS (AGCVH)
- 7 - ARRS
- 5 - 41 ARRWg; 3 ARRGp; 38 ARRSq; 47 ARRSq
- 5 - MACMET Hickam; PACAF