

5. Mr. Humer was assigned to remove the return steam manifold from the makeup evaporator. In the process of loosening the union type connections, he placed his foot on top of the floor plate, which is mounted on top of the original floor plate boundary bar, as per his statement noted in item #8 from CH-1.

This triangular floor plate was mounted, ~~one~~ <sup>one</sup> ~~like~~ and guard rail shaped to fit, for the purpose of access between ~~the~~ <sup>the</sup> Triplex Main Boiler Feed Pumps and Makeup Evaporator. However, when this was accomplished, the boundary bar was not installed. It is being installed this date.

8. Boundary bar being installed this date.