

USNS GENERAL JOHN POPE (TAP 110)
OFFICE OF THE CHIEF STEWARD
CAPTAIN'S INSPECTION

1. Clean valves at Fire Station 2-134-2 with crocus cloth and change hose.
2. Clean rust on Drinking Fountain near 2-145-2-L.
3. Clean bottom of toilet seats - 2-155-2-L.
4. In Cabin Class Passengers' Staterooms, MARK BOAT STATION ON INSTRUCTION SHEET.
5. Clean Drain - 2-164-2-L.
6. Clean Drain & Repaint 2-167-4-L.
7. Clean up the white work a little better 2-167-2-L.
8. Remove dirty glasses and tidy up room, especially the bunk shelves 2-176-2-L.
9. Clean paint from valve stem of Fire Hydrant WT BHD -186.
10. Clean rust from Drinking Fountain near WT BHD 186.
11. Top bunk un-made, basin dirty, mirror filthy- general appearance of this room IS TOTALLY UNSATISFACTORY.
12. Polish pipes under the sink. 3-177-1-L.
13. * Remove all swabs from sleeping quarters. / Secure heat 3-174-1-L.
14. Clean border tile 3-161-2-L.
15. * Prepare Station Bills for Master's signature.
16. Clean exhaust drain 3-166-2-L.
17. Polish brass on toilet seats, clean mirror & white work 3-167-1-L.
18. Urinal needs cleaning; clean and scour toilet seats 3-167-2-L.
19. Magazines could be straightened out on " Bookshelf ".
20. Clean out Drain 3-167-4-L.
21. Bunk un-made, untidy Bunk shelf and plenty of excess junk; GENERAL CONDITION OF THIS ROOM IS UNSATISFACTORY. - 3-170-2-L.
22. Vapor globe missing 3-178-4-L.
23. Occupant Card Missing 3-184-4-L.
24. Toilet seats need cleaning 3-150-2.
25. Clean valve stems with crocus cloth & tidy up this section 3-150-2.
26. Bowl needs cleaning 3-144-2-L.
27. Drain needs cleaning 3-140-4-L.
28. Frame for Occupant Card is missing 3-140-6-L.
29. Fire Station 3-126-2 is DUSTY AND DIRTY.
30. Re-adhere (tape or glue and or as necessary) vent duct S-2-143-1.
31. Clean rust from Drinking Fountain in Passageway 3-146-1-L.
32. Use Clorox and kill mold fungus in Crew Shower 3-149-4-L.
33. Clean vapor globe and water drain 3-149-6-L.
34. Vapor globes dirty 3-140-0-L.
35. Control Cabinet (F-125) Unlocked.

CAPTAIN'S REMARKS ON INSPECTION:

"I am very well pleased with the overall improvement of the Crew's Quarters, - the cleaning and general housekeeping are generally good.

There was only one room that was toatlly unsatisfactory in every way belonging to the Engine Dept.'s Wipers # 3-170-2-L.

Paint Fire Hydrant valves and clean stems with crocus cloth where indicated.

Require Engine Dept. to follow up on Lint Disposal from the dryers in the Crew Laundry rooms."

H.C. Heins