

USNS GENERAL JOHN POPE (T- AP 110)
c/o Fleet Post Office
San Francisco, California 96601

13 July 1967


From: Master
To: All Ship's Personnel.

Subj: Inspection of Crew's Quarters and facilities, report of.

1. The following were the results of Master's Inspection conducted this date:

01-102-2	Dirty vapor globe
FSD-1-102-1	Closer does not work
2-133-2-L	Install louver back, and do not remove same anymore
2-141-2-L	Replace logging where necessary; also install logging on tube in washroom area (About 2 feet) 1" thick.
Chief Electrician's	No table door plate; bunk card frame missing
Chief Plumber's	Bunk card missing
2-153-2-L	Dirty bottom of shower curtain
2-155-2-L (W/R.)	Urinal leaking
FMCV-2-157-2	Wire-brush and paint same
E-01-162-1	Exhaust vent dirty
2-164-4-L	Polish plugs on deck (Brass) and do not stain. Adjust same
3-172-2-L	Install panel on water fountain
3-184-4-L	Replace wash basin. At present there is none installed
3-167-4-L	Very good
Steward Department area and Washrooms	Make signs reading "Off Limits for Troops" around this area.
3-166-1-L	Re-Install louver, and do not remove same anymore.
3-170-1-L	Very good
Fire Key Station	
E-24 (3-141-1-L)	Seals Missing
3-155-1-L	Dirty Deck
FS-3-125-1	Fire Station Area dirty
3-126-1-L	Dirty Deck
CPO Mess	Paint all valves Black
WTD-3-102-1	Knife Edges painted
3-112-2 FIRE STATION	Dirty
WTD-3-146-2	Knife Edge painted. Remove wiring from same
3-130-1-L	Valve on ceiling leaking
P. X. Area - 3rd Deck	Install ash trays (Can Type) to bulkheads all around this area

2. General comments: The over-all inspection was very satisfactory.


H. L. Heinz, Master