

USNS GENERAL JOHN POPE (T-AP110)

DATE 10/24/67

PRIORITY 3

REPAIR LIST REQUEST

SUBJECT VALVE SCUPPER, REPAIR OF:

DATA 3" INLET AND 6" OUTLET

LOCATION 4-187-1

CONDITION CLAPPER AND CLAPPER MOUNT CARRIED AWAY

QUANTITY/SIZE ONE (1) 3" INLET AND 6" OUTLET

RECOMMENDATION FURNISH LABOR AND MATERIAL TO REPAIR OR RENEW AS REQUIRED.

Completed

  
E.C. QUINN  
SIGNATURE