

AT/PASSAGE FROM		TO	
BORTH 30 PIER 2 HUNTER'S POINT		NOVAL SHIP YARD SAN FRANCISCO, CALIF.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+ 7		21 July 19-69	Monday (MOONDAY)
TIME	REMARKS		
	0000-0800		
	ON WATCH! MR. BARRETT R/O MR. SPECTOR R/E FRUTAZ G/W.		
	CALADAW ON THE POPE MAKING ROUNDS WITH DETEX CLOCK		
	EVERY HOUR. TIPTON G/W ON THE WEIGEL MAKING HIS ROUND.		
0000	BOTH SHIP WITH DETEX CLOCK EVERY HOUR & REPORT TO POPE.		
0000	BOTH SHIPS LINES RATGUARD GANGWAY ARE IN GOOD ORDER.		
0100	MR. BARRETT R/O MR. SPECTOR R/E MADE THEIR ROUND		
	IN BOTH SHIP.		
0200	ALL LINES RATGUARD ARE IN GOOD ORDER.		
0300	BOTH SHIPS GANGWAY LINES RATGUARD IN GOOD ORDER.		
0400	MR. BARRETT R/O MADE HIS ROUND ON THE WEIGEL.		
0500	BOTH SHIPS ARE SECURE.		
0600	ALL LINES RATGUARD GANGWAY ARE IN GOOD ORDER.		
0630	WATCH RELIEVED BY LARKIN G/W.		
0700	F/W MAKES DETEX RDS WEIGEL, ALL IN GOOD ORDER.		
	0800-1600		
	MR. BARRETT R/O MR. SPECTOR R/ENG. LARRING G/W ORR F/W WEIGEL & POPE.		
0800	F/W REPORTS RD OF POPE, ALL SECURE, COLORS EXECUTED.		
0900	F/W REPORTS WEIGEL SECURE. SECURITY RD MADE, POPE R/O.		
1000	MR. HURLEY R/ENG ON BOARD RELIEVES MR. SPECTOR. ALL IN GOOD		
	ORDER, RD. MADE WEIGEL. R/ENG SPECTOR LEFT SHIP		
1100	MR. SHERMAN R/O ON BD. MR. BARRETT LEFT SHIP, F/W REPORTS		
	SECURE. ALL IN GOOD ORDER.		
1200	RD. MADE POPE, SECURE. R/ENG HURLEY TO WEIGEL FOR		
	CHECK - ALL ENG. SPACES SECURE. ALL IN GOOD ORDER.		
1300	ALL IN GOOD ORDER. DETEX RD MADE		
1400	ALL SECURE R/M CHECKS VESSELS, ALL IN GOOD ORDER.		
1430	WATCH RELIEVED BY PERKINS R/O.		
	Dated C. Larkin		
1430	watch assumed - lines - ratguards - secure - soundings being taken		
1500	F/W'S CAPPELL (WEIGEL), MATED (POPE), ON DETEX ROUNDS - REPORTING HOURLY		
	MR. SHERMAN R/O MR. HURLEY R/ENG (1600-2400) PERKINS R/O MATED W/ POPE, CAPPELL & WEIGEL.		
1600	F/W'S BOTH VESSELS - DETEX RDS - REPORT - ALL IN GOOD ORDER		
	R/O ON ROUNDS - BOTH VESSELS - ALL IN GOOD ORDER		
1700	R/E ON ROUNDS - BOTH VESSELS - F/W ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER		
1800	ALL IN APPARENT GOOD ORDER - ALL ROUNDS MADE		
1900	F/W - BOTH VESSELS - DETEX ROUNDS - ALL IN GOOD ORDER		
2000	F/W - BOTH VESSELS - DETEX ROUNDS - ALL IN GOOD ORDER		
2027	SUN REPORT: COLORS OBSERVED - R/O ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER		
2100	R/E - F/W BOTH VESSELS ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER		
2200	F/W - BOTH VESSELS - REPORT - ALL IN GOOD ORDER		
2215	MR. SPECTOR R/E ABOARD - MR. HURLEY R/E ASHORE		
"	watch assumed relieved by Frutas R/O		
	Dated Perkins		

AT/PASSAGE FROM	TO	
BERTH 30 Pier 2 HUNTER'S POINT NAVAL SHIP YARD SAN FRANCISCO		
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
T 7	22 July 19-69	Tuesday

TIME	REMARKS
	0000-0800
	ON Watch MR. BARRETT To MR. SPECTOR IE FRITAZ G/W Larkin T/w making his round with Detex clock every hour Report to the gangway.
	Tipton T/w on the Weigel making his round every hour Report to the Pope gangway
0000	Both ships Gangway Lines Rat Guard are in good order.
0100	MR. BARRETT To MR SPECTOR made their on Path ship
0200	Gangway Rat Guard Lines are in good order.
0300	Both ships Lines Rat Guard Gangway in good order.
0400	MR. BARRETT To made his round on the Weigel.
0500	Both ships Gangway Lines Rat Guard in good order.
0530	MR. SPECTOR IE made his round on the Weigel Eng. Room
0600	Gangway, Lines Rat Guard in both ship are in good order.
0700	WATCH RELIEVED BY GEORGE ORR (HE GOT UP LATE).
	DAYWORKERS TURN TO.
	MR SKOVOTH To (0800-1600) ORR-GWY MOVILLION F/W
0800	MOORED AS BEFORE. COLORS EXECUTED.
0837	CAPTAIN HASKELL ABOARD
0900	ALL IN APPARENT GOOD ORDER
1000	ROUTINE WATCH. ALL SECURE.
1117	IREDALE, GEORGE J. REPORTED ABOARD FOR DUTY-VICE CAMERON
1200	THE FOLLOWING TESTS WERE CONDUCTED ABOARD BOTH VESSELS 0 DIESEL GENERATOR STARTING, LIGHTING, AND KIDDE FIRE. ALARM BATTERIES; DEGAUSSING FOR 4 HOURS. DIESEL FIRE PUMP BATTERIES & I.C. BATTERIES TESTED ABOARD POPE.
1300	ALL SECURE
1405	CAPTAIN ASHORE
1420	WATCH RELIEVED BY LARRY PERKINS Geo. Orr
1420	watch assumed - LINES - RAT GUARDS -
1500	Flw Mate (POPE); Flw CAPELL (EIGEN); ON DETEX RDS. Soundings taken
1510	MR. SHERMAN To ABOARD - GEO GREEN MSTR - REP ABOARD MR. SHERMAN To (1600-2400) PERKINS T/w Mated Flw POPE; CAPELL Flw Weigel
1600	R/O ON RDS. BOTH VESSELS - Flw BOTH VESSELS - DETEX RDS - ALL IN GOOD ORDER
1700	R/O ON ROUNDS BOTH VESSELS - Flw BOTH VESSELS ON DETEX ROUNDS - ALL IN GOOD ORDER
1800	Flw BOTH VESSELS - DETEX ROUNDS - REPORT - ALL IN APPARENT GOOD ORDER
1900	Flw BOTH VESSELS - DETEX ROUNDS - REPORT - ALL IN GOOD ORDER
2000	SUNSET - colors observed - R/O ON ROUNDS BOTH VESSELS - All in good order
2100	ALL IN APPARENT GOOD ORDER - ROUTINE ROUNDS MADE - R/O ON ROUNDS
2200	Flw BOTH VESSELS - REPORT all in good order
2235	watch relieved by Iredale
2300	Flw both vessels report all secure
	L. M. Perkins

AT/PASSAGE FROM
 ZONE DESCRIPTION

Berth 30 - Hunters Point
 +7

TO
 Naval Shipyard
 DATE (Day, month, year)
 23 July 69

San Francisco
 DAY OF WEEK
 Wednesday

TIME	REMARKS
	0000-0800
	Mr. Barrett, RDO, - Mr. Spector, R/E - IREDALE, A/B. Larkin, F/W & Tipton, F/W aboard Weigel - Moored as before - Receiving services from shore as before. Firewatches making hourly rounds & reporting hourly -
0030	Mr. Spector, R/E, on inspection Tour of USNS Weigel.
0040	Mr. Barrett completes inspection Tour of Weigel
0100	All secure both vessels
0200	All's well both vessels -
0300	F/W Pope & Weigel report all secure -
0400	All secure both vessels.
0500	All secure Pope & Weigel.
0512	Gangway phone noted as inoperative -
0600	All secure both vessels -
0615	Watch relieved by Capell A/B
	IT Smedley
0615	Mr. Skoveth 1/0 (0800 ~ 1600) Capell A/B G, J. Mateo A/B FW Assumed the watch. All in apparent good order. Phone back in order.
0700	All in apparent good order.
0750	Van Gorder O/S aboard to call M.S.T.S. to locate USNS Card
0800	Colors. All in apparent good order.
0810	Test of fire alarm system, diesel gen. (1/2 hr.), anchor windlass (1 hr.), capstans #1 & 2 (1 hr.), emergency diesel fire pumps #1 & 2 (1 hr.), bilge air valves.
0845	Captain Haskell, Master, aboard
0900	All in apparent good order.
1000	All in apparent good order.
1100	All in apparent good order.
1200	All in apparent good order.
1300	All in apparent good order.
1400	All in apparent good order.
1430	Relieved gangway duties by Perkins A/B
	Robert A. Capell
1420	watch assumed - Mr. HURLEY R/E ABOARD
1430	CAPT HASKELL ASHORE
1500	F/W PERKINS (WEIGEL); F/W MATEO (POPE); ON DETEX-RDS - SOUNDINGS TAKEN
1515	MR. SHERMAN R/E ABOARD
	Mr. Silverman & Mr. Hurley R/E (1600-2400) PERKINS 1/0; DAVOL 1/0 (POPE) PERKINS 1/0
1600	F/W BOTH VESSELS - ON ROUNDS - R/E ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
1700	R/E ON ROUNDS BOTH VESSELS - F/W BOTH VESSELS ON ROUNDS - ALL IN GOOD ORDER
1800	F/W BOTH VESSELS - DETEX ROUNDS - REPORT ALL IN GOOD ORDER
1900	F/W BOTH VESSELS - REPORT - ALL IN GOOD ORDER - LINES PATROLS - ALL IN GOOD ORDER
2000	R/E ON ROUNDS BOTH VESSELS - F/W ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
2026	SUNSET - colors observed - LIT'S ON - all in apparent good order
2100	R/E - F/W ON ROUNDS - BOTH VESSELS - ALL IN GOOD ORDER -
2215	all in good order - Mr. Spector R/E ABOARD - Mr. Hurley R/E ASHORE
2225	watch relieved by IREDALE R/B -
	Tom Tipton

AT/PASSAGE FROM Hunters Point Naval Shipyard, ZONE DESCRIPTION	TO San Francisco DATE (Day, month, year) 24 Jul 69	Berth 30, Pier 2 DAY OF WEEK THURS.
---	---	--

TIME	REMARKS
	Mr. Barrett, RDO (0000-0800) Mr. Spector, R/E
	1 REDALE, A/B - Celada, F/W Tipton, F/W (Weigel)
	Moored as before - Services from shore as before - F/W, both vessels, making hourly rounds of detex stations & reporting to Quarter deck.
0000	Firewatches, Pope & Weigel, report all secure.
0100	F/W indicate all secure both vessels.
0200	F/W, both ships, report all secure.
0300	F/W report all's well both vessels.
0400	F/W report all secure, both vessels.
0500	F/W report all secure, both vessels.
0600	F/W reports all secure.
0632	Relieved of watch by Capell A/B, CT Wheel
	Mr Skovoth (0800 ~ 1600) Capell A/B G, Morillion A/B F/W.
0632	Assumed the watch. All in apparent good order.
0700	All in apparent good order.
0715	Test of ships fire alarm system. All in order.
0700	All in apparent good order.
0800	Colors. All in apparent good order.
0855	Purser to the U.S.N.S. Sunnyvale to pick up surplus funds. Accompanied by purser from U.S.N.S. Croatan, Mr. Schorse, in Navy vehicle.
0900	All in apparent good order.
0943	Purser returns w/ \$7000 ⁰⁰ . Mr. Schorse to Croatan.
0956	Apollo 11 splash down. Earth invaded by Moon men.
1000	All in good order.
1100	All in apparent good order.
1200	All in apparent good order.
1300	All in apparent good order.
1350	Electric power off. Brief shore side shut down. (3 min.)
1400	All in apparent good order. (R/ENG HURLEY ON BD)
1430	Watch relieved by Larkin A/B
	Robert A. Capell
1500	MR SHERMAN ON BD (R/DO.) MR SKOVOTH 1/2 LEFT SHIP 1515
	1600 - 2400
	R/DO MR SHERMAN, R/ENG MR HURLEY, LARKIN G/WAY PELETI F/W WEIGEL - DAVACOLA/B A/W POPE.
1600	F/W'S BOTH VESSELS REPORT RDS MADE, SECURE
	R/ENG HURLEY CHECK W/T DOORS & ENG SPACES, SECURE.
1630	R/DO SHERMAN CHECKS WEIGEL, ALL SECURE.
1700	F/W'S REPORT ALL SECURE, R.D. MADE ALL AREAS
1800	ALL SECURE
1900	ALL SECURE. F/W'S MADE & REPORTED SECURE ALL AREAS.
2000	ALL SECURE - RDS MADE.
2025	COLORS EXECUTED, LIGHT GANGWAY, 2/3 WAVING & NIGHT US
2100	ALL SECURE 2000 + 2100 RDS MADE, R/ENG MADE INSPECTION, SECURE
2230	2200 RDS MADE, VESSELS SECURE. WATCH RELIEVED BY TREDALE A/B.

AT/PASSAGE FROM
S. F. B. N. S. Hunters Point, San Francisco - Berth 30 - Pier 2
ZONE DESCRIPTION + 7 DATE (Day, month, year) 25 Jul. 69 DAY OF WEEK FRI

TIME	REMARKS
	Mr. Barrett, RDO - IREDALE, 1/8 (0000-0800). Celada, Flw - Tipton, Flw (Weigel)
2230	Assumed the watch - Conditions normal & quiet - Firewatchers making rounds of detex stations, Pope & Weigel, & reporting hourly -
0000	Flw, both vessels, report all secure.
0100	Flw, both vessels, report all secure.
0140	R/E reports leaking water valve behind #2 boiler in Weigel
0200	All secure, both vessels
0300	All secure - both vessels -
0400	Flw, Pope & Weigel, report all's well -
0500	All secure both vessels -
0600	All secure both vessels -
0615	CAPT. HASKELL ABOARD -
0630	Watch relieved by ORR, A/B
0700	DAYWORKERS TURN TO <i>T. Schubert</i>
0715	TEST OF SMOKE DETECTING & KIDDE FIRE ALARMS LOUD & CLEAR. MR SKOVOTH 1/8 (0800-1600) ORR-GANGWAY CAPELL-FIREWATCH
0800	MOORED AS BEFORE. COLORS SMARTLY EXECUTED BY ROBERT CAPELL.
0900	ROUTINE WATCH. EVERYTHING IN ROUTINE GOOD ORDER.
1000	#1 & #6 WINCHES TEST RUN FOR ONE HOUR ABOARD WEIGEL. #6 WINCH TEST RUN ON POPE.
1100	ALL SECURE.
1130	CAPTAIN ASHORE. PAYDAY FOR CREW
1200	ELECTRICIANS TESTING LIFEBOAT LIMIT SWITCHES, MOTORS, & CONTROLLERS ABOARD WEIGEL & MAKING NECESSARY REPAIRS.
1300	ROUTINE WATCH. ALL IN ORDER.
1400	ALL SECURE. (R/ENG HURLEY ON BD)
1430	WATCH RELIEVED BY PAT LARKIN <i>Geo. Orr</i>
1500	F/W'S MAKE SECURITY RDS - ALL AREAS SECURE. MR SHERMAN, R/ENG.
1515	1/8 SKOVOTH ASHORE 1600-2400 ASSUMED THE WATCH, ALL IN GOOD ORDER. ON WATCH MR SHERMAN RDO, MR HURLEY R/ENG. LARKIN C/WAY, DELETTI 1/8 FLW WEIGEL, DAVACOL 1/8 FLW POPE.
1600	DETEX RDS MADE AND REPORTED. R/ENG TO WEIGEL FOR CHECK
1630	W/T DOORS CLOSED (BRIDGE) R/ENG FOUND ALL AREAS SECURE.
1700	DETEX RDS MADE ALL IN GOOD ORDER. R/ENG TO WEIGEL RDS VESSELS
1800	SECURITY WATCH REPORTS SECURE. R/ENG CHECK CONDITIONS SATISFACTORY
1900	SECURE BOTH SHIPS - REPORT RECEIVED.
2000	DETEX RD. MADE
2025	COLORS EXECUTED - CHECKED ALL WARNING LTS & GANGWAY LTS
2100	DETEX RD. MADE, ALL IN GOOD ORDER R/ENG MADE CHECK & INSPECTION OF ALL ENG. SPACES WEIGEL & POPE
2130	ALL IN GOOD ORDER.
2200	F/W'S REPORT HOURLY RDS. MADE BOTH VESSELS SECURE. COMPT 4-1 POPE NEEDS RELAMPING.
2230	F/W'S RELIEVED CELADA & TRUTAZ ON BD. WATCH RELIEVED BY IREDALE. 1/8 R/ENG ROBERT ON BD / R/ENG HURLEY LEFT. <i>Pat Larkin</i>

AT/PASSAGE FROM S.F.B.N.S. - Hunter's Point.	TO Berth 30, Pier 2
ZONE DESCRIPTION +7	DATE (Day, month, year) 26 Jul 69
	DAY OF WEEK SAT.

TIME	REMARKS
2230	Mr. Barrett, RDO - Mr Robert R/E (OWN-OFN) IREDALE, A/B. Frutaz Flw Celada, Flw Assumed the watch. Moored as before. Receiving services from shore as before - Firewatchers making rounds of deTex Stations and reporting hourly To quarterdeck.
2300	Flw Pope & Weigel report all secure -
2400	Flws indicate all's well. RDO & R/E make inspection Tour of Weigel.
0100	Flws note all secure -
0200	Flw both ships report all secure -
0300	Flws. note all secure -
0400	Flws report all's well -
0500	Flw Pope & Weigel, report all secure -
0600	Flw both ships report all secure -
0630	Watch relieved by Orr A/B
0700	R/O + R/E MAKE TOUR OF INSPECTION
	MR. BARRETT R/O MR. ROBERT R/E (0800-1600) ORR-GWY MATEO Flw WEIGEL BUNDY Flw POPE
0800	MOORED AS BEFORE. COLORS. NO ACTIVITY. Flw's MAKING ROUNDS
0900	R/O + R/E COMPLETE TOUR OF BOTH VESSELS.
1000	ROUTINE WATCH. ALL IN APPARENT GOOD ORDER.
1033	MRS. PELETI CALLED AND INFORMED SHIP THAT HUSBAND IS ILL & WILL BE UNABLE TO STAND 16-24 WATCH THIS EVENING.
1020	MR HURLEY R/E RELIEVED MR ROBERT R/E.
1050	MR SHAMAN R/O RELIEVED MR. BARRETT.
1100	ALL SECURE
1200	R/O + R/E INSPECT BOTH VESSELS
1300	ALL SECURE
1400	R/O + R/E COMPLETE INSPECTION OF BOTH VESSELS
1415	WATCH RELIEVED BY LARRY PERKINS <i>Geo. Orr</i> MR SHAMAN R/O - MR HURLEY R/E - 1600-2400 - PERKINS Flw - DRUACI Flw
1415	WATCH ASSUMED BY L.M. PERKINS - ALL IN - GOOD ORDER
1500	Flw - BOTH VESSELS ON DETEX ROUTES - SOUNDINGS TAKEN
1600	R/O ON ROUNDS - BOTH VESSELS - ALL IN GOOD ORDER R/E REPORTS - BLOWER ON KICKER SINCE 12/10 PM - ABOARD ^{115WS} WEIGEL (#1) IS - OUT
1700	Flw ON BOTH VESSELS - REPORT - ALL SECURE R/E ON ROUNDS - BOTH VESSELS - ALL IN GOOD ORDER
1800	Flw - ON BOTH VESSELS - REPORT ALL IN GOOD ORDER
1900	ALL IN APPARENT GOOD ORDER
2000	ALL IN APPARENT GOOD ORDER
2023	SUNSET: colors - observed
2100	R/O - ON ROUNDS - BOTH VESSELS - R/E ON ROUNDS - all in good order
2200	ALL IN APPARENT GOOD ORDER
2205	MR. ROBERT R/E ABOARD - MR HURLEY R/E ABOARD
2230	WATCH RELIEVED BY IREDALE

L.M. Perkins

ZONE DESCRIPTION

Pier 2

DATE (Day, month, year)

	DATE	DAY OF WEEK	TIME	LOCATION	REMARKS
1	7-10-68	TUE	1900	1000	1000
2	7-11-68	WED	1900	1000	1000
3	7-12-68	THU	1900	1000	1000
4	7-13-68	FRI	1900	1000	1000
5	7-14-68	SAT	1900	1000	1000
6	7-15-68	SUN	1900	1000	1000
7	7-16-68	MON	1900	1000	1000
8	7-17-68	TUE	1900	1000	1000
9	7-18-68	WED	1900	1000	1000
10	7-19-68	THU	1900	1000	1000
11	7-20-68	FRI	1900	1000	1000
12	7-21-68	SAT	1900	1000	1000
13	7-22-68	SUN	1900	1000	1000
14	7-23-68	MON	1900	1000	1000
15	7-24-68	TUE	1900	1000	1000
16	7-25-68	WED	1900	1000	1000
17	7-26-68	THU	1900	1000	1000
18	7-27-68	FRI	1900	1000	1000
19	7-28-68	SAT	1900	1000	1000
20	7-29-68	SUN	1900	1000	1000
21	7-30-68	MON	1900	1000	1000
22	7-31-68	TUE	1900	1000	1000

27 Jul 69

Sun.

+ 7

TIME	REMARKS
	Mr. Barrett, RDO - IREDALE (0000-0800) Celada, Flw - Frutaz (Weigel)
2230	Assumed the watch - Conditions normal. Firewatchers making rounds of detex stations & reporting hourly to Qtr. Deck
2300	Flws report all secure
0000	Flw, Pope & Weigel, report all secure
0100	Flws note all secure - RDO & R/E complete Tour of Weigel.
0200	Flws report all's well
0300	Flws report all's well.
0400	Flws indicate all secure
0500	Flws. report all secure.
0600	Flw report all secure.
0630	watch relieved by Orr A/B
0700	R/O & R/E MAKE TOUR OF INSPECTION MR BARRETT R/O MR ROBERT R/E (0800-1600) ORR-GNY MATEO F/W WEIGEL BUNDY F/W POPE
0800	MOORED AS BEFORE. COLORS. NO ACTIVITY. F/W'S MAKING ROUNDS
0900	R/O & R/E COMPLETE TOUR OF BOTH VESSELS.
1000	ALL SECURE. LINES, GANGWAY, & RAILGUARDS INSPECTED.
1010	MR HURLEY R/E ABOARD. MR ROBERT ASHORE.
1045	MR SHERMAN R/O RELIEVES MR. BARRETT
1100	ROUTINE WATCH. F/W'S REPORT ALL IN GOOD ORDER.
1200	R/O & R/E MADE TOUR OF INSPECTION
1300	ALL SECURE.
1400	R/O & R/E MADE ROUTINE INSPECTIONS.
1415	WATCH RELIEVED BY LARRY PERKINS Geo. Orr.
1415	WATCH ASSUMED - MOORED AS BEFORE -
1500	R/O ON ROUNDS F/W'S ON ROUNDS BOTH VESSELS - ALL IN APPARENT GOOD ORDER MR SHERMAN R/O - MR HURLEY R/E L 1600 - 2100 PERKINS Flw: Davaco (Flw Pope): Petek (Flw Weigel)
1600	R/E ON ROUNDS BOTH VESSELS F/W'S ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
1700	F/W'S REPORT ALL IN GOOD ORDER - R/O ON ROUNDS - R/E ON ROUNDS
1800	ALL IN APPARENT GOOD ORDER
1900	Flw ON BOTH VESSELS REPORT - ALL IN GOOD ORDER
2000	Flw - ON BOTH VESSELS REPORT - ALL IN GOOD ORDER
2022	SUNSET: colors observed
2100	R/E & R/O ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
2210	ALL IN APPARENT GOOD ORDER - watch relieved by Frutaz
	L. M. Perkins

AT/PASSAGE FROM		TO	
BERTH 30 DIER 2 HUNTER		POINT HAVEN SHIPYARD S.F.	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		28 July 1969	Monday
TIME	REMARKS		
	0000-0800		
	ON WATCH! MR. BARRETT ^R / ₀ MR. SPECTOR ^R / _E		
	FRUTAZ ^R / _A GANGWAY Celada Flw making his Round		
	With Detex Clock hourly and Report to the Gangway.		
	TIPTON Flw on the Weigel making his Round with		
	Detex Clock hourly and Report to the Gangway.		
0000	Both ships Rat Guard lines are in good order.		
0100	MR. BARRETT ^R / ₀ MR. SPECTOR ^R / _E made their Round on		
	both ships Pope and Weigel		
0200	Gangway, Rat Guard lines are in good order.		
0300	Both ships are in good order.		
0400	MR. BARRETT ^R / ₀ made his Round on the Weigel.		
0500	Both ships Lines Rat Guard in good order.		
0600	MR. BARRETT ^R / ₀ MR. SPECTOR ^R / _E made their Round		
	on both ships Pope and Weigel.		
0630	Watch Relieved by Goe Off MR. SPECTOR ASHORE.		
0700	MR. BARRETT ASHORE.		
0730	SMOKE DETECTOR + KIDDE ALARMS TESTED ON BOTH VESSELS		
0735	POPOFF, NICHOLAS (DECK YEOMAN) ABOARD - VICE BURTON.		
	MR SKOVOTH ^R / ₀ (0800-1600) ORR-GANGWAY LARKIN-FIREWATCH		
0800	MOORED AS BEFORE. LINES, GANGWAY, RAT GUARDS SECURE. COLORS EXECUTED.		
0850	CAPTAIN HASKELL ABOARD.		
0900	ALL SECURE.		
1110	KUYKENDALL, CALVIN W. (OILER) ABOARD - VICE GIBSON		
1200	ROUTINE WATCH. ALL IN GOOD ORDER		
1300	ALL SECURE		
1400	ROUTINE WATCH. ALL IN GOOD ORDER.		
1430	WATCH RELIEVED BY LARRY PERKINS ^R / _B <i>See On</i>		
1430	WATCH ASSUMED - LINES, RAT GUARDS - GANGWAY - SECURE		
	MR. HURLEY ^R / _E ABOARD SOUNDINGS TAKEN		
1500	MR. SHERMAN ^R / ₀ ABOARD. Flw BOTH VESSELS ON DETEX ROUNDS		
1550	MR. CASS FROM MOTOROLA CALLED MR. SKOVOTH. WILL CALL TOMORROW		
	MR. SHERMAN ^R / ₀ MR. HURLEY ^R / _E (1600-2400) PERKINS ^R / _B makes Flw Pope]. CAPELL ^R / _B		
1600	MR. HURLEY ^R / _E ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER		
1700	^R / ₀ ON ROUNDS BOTH VESSELS.		
1800	Flw BOTH VESSELS REPORT - ALL IN GOOD ORDER		
1900	Flw BOTH VESSELS REPORT ALL IN GOOD ORDER		
2021	SUNSET: COLORS OBSERVED - Flw BOTH VESSELS REPORT -		
	ALL IN GOOD ORDER		
2100	^R / ₀ ON ROUNDS BOTH VESSELS; ^R / _E ON ROUNDS BOTH VESSELS;		
	Flw BOTH VESSELS REPORT - ALL IN GOOD ORDER		
2200	Flw BOTH VESSELS SECURED - ALL IN APPARENT GOOD ORDER		
2210	MR. SPECTOR ^R / _E ABOARD - MR. HURLEY ^R / _E ASHORE		
	watch relieved by FRUTAZ ^R / _B .		
	<i>J. M. Perkins</i>		

AT/PASSAGE FROM	TO	
BERTH 30 PIER 2 HUNTER'S BAY	NAVAL SHIPYARD SAN FRANCISCO	
ZONE DESCRIPTION	DATE (Day, month, year)	DAY OF WEEK
+ 7	29 July 19-69	Tuesday


TIME	REMARKS
	0000-0800
	ON WATCH MR. BARRETT P/O MR. SPECTOR P/E FRUTOS G/W LARKIN P/W ON THE POPE MAKING HIS ROUND WITH DETEX CLOCK HOURLY AND REPORT TO THE GANGWAY. TIPTON P/W ON THE WEIGEL MAKING HIS ROUND HOURLY REPORT TO THE POPE GANGWAY.
0000	BOTH SHIPS LINES & RATGUARD ARE IN GOOD ORDER.
0100	MR. BARRETT P/O MR. SPECTOR P/E MADE THEIR ROUNDS ON THE WEIGEL.
0200	GANGWAY, LINES, RATGUARD ARE IN GOOD ORDER.
0300	MR. BARRETT P/O MADE HIS ROUND ON THE WEIGEL.
0400	LINES, RATGUARD & GANGWAY ARE IN GOOD ORDER.
0500	ALL LINES, GANGWAY, RATGUARD ARE IN GOOD ORDER.
0530	MR. BARRETT P/O MR. SPECTOR P/E MADE THEIR ROUNDS IN BOTH SHIPS.
0600	ALL GANGWAY, RATGUARD LINES ARE IN GOOD ORDER.
0630	WATCH RELIEVED BY GEE. ORR
0700	DAY WORKERS TURN TO. RECTIFIERS CHECKED - O.K.
0710	MR. BARRETT ASHORE. TEST OF SMOKE DETECTOR & KIDDE ALARMS - O.K. MR SKOVOTH P/O (0800-1600) ORR - GANGWAY GRAYSON - FIREWATCH
0800	MOORED AS BEFORE. LINES, GANGWAY, & RATGUARDS SECURE. COLORS EXECUTED
0810	CAPTAIN HASKELL ABOARD
0900	ROUTINE WATCH. ALL IN ORDER.
1000	ALL SECURE.
1100	ALL SECURE.
1200	ALL IN ORDER.
1300	ALL SECURE.
1400	ALL IN APPARENT GOOD ORDER WATCH RELIEVED BY LARRY PERKINS Det. Orr
1420	WATCH ASSUMED. LINES - RATGUARDS - GANGWAY - ALL SECURE MR. HURLEY P/E ABOARD CAPT. TILFANTE (USN) LT. HEATHERTON (USN) ABOARD
1500	FOR MATEO (POPE): FR. CAPELL (WEIGEL) ON DETEX ROUNDS - REPORTING HOURLY
1515	MR. SHERMAN P/O ABOARD - 1 - SOUNDINGS TAKEN
1520	CAPT (USN) TILFANTE; LT. HEATHERTON (USN) FIRST SPAG ASHORE
"	CAPT. HASKELL ASHORE 1545: 30 GALS WETS ALL DELIVERED TO POPE MR. SHERMAN P/O; MR. HURLEY P/E (1600-2400) PERKINS P/W; MATEO P/W POPE; CAPELL P/W WEIGEL.
1600	MR. HURLEY P/E - P/W BOTH VESSELS ON ROUNDS - ALL IN GOOD ORDER
1900	P/O ON ROUNDS BOTH VESSELS - P/W ON ROUNDS.
1800	ROUNDS MADE - ROUTINELY - ALL IN APPARENT GOOD ORDER
1900	P/W BOTH VESSELS - ON DETEX ROUNDS - ALL IN APPARENT GOOD ORDER
2021	SUNSET - COLORS OBSERVED
2040	P/O ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
2100	P/W'S - P/E ON ROUNDS BOTH VESSELS - RATGUARDS - LINES - GANGWAY - SECURED
2210	MR. SPECTOR P/E ABOARD - MR. HURLEY P/E ASHORE - WATCH RELIEVED BY IREDALE A/B L. M. Perkins

AT/PASSAGE FROM		TO	
S.F.B.N.S. Hunters Point		Berth 30 Pier 2	
ZONE DESCRIPTION		DATE (Day, month, year)	DAY OF WEEK
+7		30 Jul 69	Wed.
TIME	REMARKS		
	Mr. Barrett, RDO - /REDALE 1/2 (0000-0800) LARKIN, F/W - Tipton, F/W (Weigel) Moored as before - Receiving services from shore as before Fire watches making rounds of detex stations & reporting hourly to the quarterdeck.		
2300	Firewatches, Pope & Weigel, report all secure		
0000	RDO & R/E make inspection Tour of Weigel - All's well		
0100	F/W's, both ships, indicate all secure.		
0200	F/W's, both ships, report all secure		
0300	F/W's - report all's well.		
0400	F/W's, Pope & Weigel, report all secure		
0500	F/W's - report all's well		
0600	F/W, Pope & Weigel, note all secure.		
0615	Watch relieved by Capell, A/B		
	IT Shrub		
	Mr. Skovoth 1/2 (0800 ~ 1600) Capell A/B & J. Mateo A/B F/W.		
0618	Assumed the watch. All in apparent good order.		
0700	All in apparent good order.		
0730	Test of ship's fire alarm system. All in order.		
0731	Notified that feed water being fed into #1 boiler.		
0800	Colors. All in apparent good order.		
0900	All in apparent good order.		
0945	(Approx) Steam off.		
1000	All in apparent good order.		
1015	Captain Haskell, Master, aboard.		
1100	All in apparent good order.		
1200	All in apparent good order.		
1208	Electrician worked on Life boat switches this morning. Gangway informed at time indicated.		
1215	Gangway also informed of following tests this date: diesel gen (1/2 hr.), anchor windlass (1 hr.), capstans #1 & 2 (1 hr.), emergency fire pumps #1 & 2 (1 hr.), bilge air valves.		
1300	All in apparent good order.		
1326	Captain Haskell ashore		
1400	All in apparent good order.		
1415	Steam back on.		
1430	Relieved of gangway duties by Perkins 1/2 Robert A. Capell		
1425	watch assumed - lines - Retenards - gangway - secure		
1430	MR. HURLEY R/E ABOARD - Notice from Eng. Dept. "SAFETY MEETING FOR Eng. Dept. personnel @ 1630, Mon 30 JULY 1969, PRESIDED by 1st R/E. Twenty (20) men were present. - meeting adjourned 2100 hrs" Submitted by Eng. Yn. McCABE		
1500	F/W BOTH VESSELS ON DETEX ROUNDS - BOTH VESSELS - SOUNDINGS taken		
"	MR. SHERMAN R/O ON BOARD MR. SHERMAN R/O, MR. HURLEY R/E. (1600-2400), Perkins 1/2, Davaco 1/2, Pope 1/2, Weigel 1/2, 1600-2400 CONT. →		

AT/PASSAGE FROM HUNTER Point Naval Shipyard	TO St. Barth 30 Port 2
ZONE DESCRIPTION + 7	DATE (Day, month, year) 30 July '69
	DAY OF WEEK Wednesday

TIME	REMARKS
1600	1600
1700	MR. HURLEY R/E ON ROUNDS BOTH VESSELS
1800	FW BOTH VESSELS - REPORT - ALL IN GOOD ORDER
1900	R/E ON ROUNDS - BOTH VESSELS - ALL IN GOOD ORDER
2000	FW - BOTH VESSELS - REPORT - ALL IN GOOD ORDER
2100	FW - BOTH VESSELS - REPORT - all in apparent good order
2200	all in apparent good order
2300	all in apparent good order
2400	SUNSET - COBRs observed
2500	R/E + R/E - on rounds Weigel + Pope - all in good order
2600	FW - both vessels on Deck ROUNDS - ALL IN APPARENT GOOD ORDER
2700	FW - SECURED - all in APPARENT GOOD ORDER
2800	MR. SPECTOR R/E ABOARD - MR. HURLEY R/E ASHORE
2900	watch relieved by TREDALE

L. M. Perkins



AT/PASSAGE FROM S.F.B.N.S. <u>Hunters Point</u>	TO <u>Berth 30</u> <u>Pier 2</u>
ZONE DESCRIPTION <u>+7</u>	DATE (Day, month, year) <u>31 Jul 69</u>
	DAY OF WEEK <u>THURS</u>

TIME	REMARKS
0000/0800	WATCH: Mr. Barrett, RDO - IREDALE, A/B - Celada, F/W - Tipton F/W (Weigel) Moored as before - Receiving services from shore as before - Firewatches, Pope & Weigel making rounds of DETEX STATIONS & REPORTING hourly.
2300	F/W's report all secure
0000	RDO, R/E make inspection Tour of Weigel - Satisfactory
0100	F/W's, both vessels report all secure
0200	F/W's, both ships, indicate all secure
0300	Capell, A/B, phoned to report he'd be late in relieving the watch in the morning - F/W's both vessels, indicate all secure.
0400	F/W's report all secure
0500	F/W's, Pope & Weigel, indicate all's well.
0600	RDO makes inspection Tour of Weigel - All in apparent good order.
0630	WATCH relieved by Bundy, ABM
	at anchor.
	MR. Skrooth, I/O 0800-1600 GRAYSON-A/B NOVILLION 7/W
0700	Watch relieved by Grayson A/B
0707	Ship's fire alarm system tested - in good order.
0710	Mr. Barrett, R/O ashore.
0800	Colors executed.
0837	Captain Haskell aboard.
1000	Capell, A/B will not be aboard today, sick in bed.
1000	Deck Dept. Safety Meeting held from 0830-0900, 9 men present, subject: Use of OBA.
1055	Purser ashore to Bank.
1133	Purser aboard.
1420	Electrician continued work today on life boat limit switches.
1425	Mr. Hurley, R/E/O aboard.
1430	Watch relieved by Larkin, Mr. Hurley on Bd.
1500	Mr. Sherman to go on by 1/6 Skrooth left ship.
1500	Captain Haskell left ship (1500), Shore leave.
	MR. SHERMAN 1600-2400 Ensign G/P
	MR. HURLEY DATA COL F/W PELETI (WEIGEL)
1600	F/W'S REPORT ALL SECURE / WTD WEIGEL TO CHECK ENG/MT.
1700	DETEX RDS MADE SECURE - WTD CLOSED CHECKED - #LIGHT OUT
1800	SECURE, R/ENG CHECKS BOTH VESSELS, SATISFACTORY WTD PANEL WEIGEL BRIDGE
1900	F/W'S REPORT ALL SECURE.
2000	DETEX RDS MADE SECURE.
2022	COLORS EXECUTED - G/W LIGHTS & NIGHT LIGHTS CHECKED.
2100	R/O CHECKS BOTH VESSELS - SATISFACTORY
2200	ALL SECURE.
2230	WATCH RELIEVED BY IREDALE A/B

AT/PASSAGE FROM S.F. B. N. S.		Hunters Point		TO Borth 30, Pier 2	
ZONE DESCRIPTION		+7		DATE (Day, month, year) 1 AUG 69	
				DAY OF WEEK FRI.	
TIME	REMARKS				
0000/0800	WATCH: Mr. Barrett, RDO - IREDALE, A/B - Celada, Flw - Tipton, Flw (Weigel) Moored as before - Receiving services from shore as before. Firewatchers making rounds of detex stations, Pope & Weigel, and reporting hourly To quarter deck.				
2300	F/w's, Pope & Weigel, report all secure.				
0000	RDO & R/E on inspection Tour of Weigel - All in apparent good order.				
0100	F/w's both vessels, indicate all secure -				
0200	F/w's report all secure.				
0300	F/w's, Pope & Weigel, indicate all's well.				
0400	F/w, both ships, report all secure.				
0500	F/w's note all's well.				
0540	Capt. HASKELL ABOARD.				
0550	RDO - R/E complete inspection Tour of Weigel - All secure.				
0600	F/w's, Pope & Weigel, report all secure.				
0630	Relieved of watch by Orr, A/B				
0640	PULLEN, JOHN W A/BM REPORTED ABOARD VICE Barrett <i>Irish</i>				
0700	DAYWORKERS TURN TO.				
	MR SKOVOTH $\frac{1}{6}$ (0800-1600) ORR-GANGWAY CAPELL-FIREWATCH				
0800	MOORED AS BEFORE, LINES, GANGWAY, & RANGUARDS SECURE. COLORS EXECUTED.				
0825	TEST OF SMOKE DETECTOR & KIDDE ALARMS O.K. CAPTAIN ASHORE				
0830	STACK COVERS ON BOTH VESSELS ^{STACKS} TURNED TO OPEN POSITION ON POPE.				
0900	WINCHES #1 & 2 ON POPE & #5 & 6 ON WEIGEL TEST RUN. ELECTRICIANS CONTINUE WORK ON LIFEBOAT LIMIT SWITCHES.				
1000	ALL SECURE				
1130	PAYDAY FOR CREW (7 DAYS S+Q).				
1200	ALL SECURE				
1300	ALL SECURE				
1420	MR HURLEY R/E ABOARD				
1425	WATCH RELIEVED BY LARKIN A/B <i>Off. On</i>				
1500	F/W'S REPORT ALL IN GOOD ORDER.				
1515	MR SHERMAN R/M ON BD, MR SKOVOTH LEFT SHIP.				
	1600 - 2400				
1600	MR SHERMAN R/M ON BD, MR HURLEY R/E ON BD, LARKIN G/W				
1630	NTD CLOSED, BOTH VESSELS, R/ENG CHECKS BOTH VESSELS - ALL IN GOOD ORDER - SATISFACTORY				
1700	F/W'S REPORT CONDITIONS NORMAL				
1800	DETEX RDS. MADE, ALL IN GOOD ORDER.				
1900	RDS MADE, ALL SECURE.				
2000	F/W'S REPORT ALL SECURE.				
2020	COLORS EXECUTED - G/W LT + A/C TRUCK LTS ON.				
2100	RDO CHECKS WITH WEIGEL & POPE, INSPECTION SATISFACTORY				
2200	ALL SECURE R/ENG SPECTOR ON BD.				
2230	WATCH RELIEVED				

TIME	REMARKS
0000/0800	WATCH: MR. BARRETT, RDO. IREDALE A/B - Celada, FW, FRUTAZ, FW Moored as before. Receiving services from shore as before. Firewatches making rounds of Detex Stations and reporting hourly To Quarterdeck.
2300	Firewatches, Pope & Weigel, report all secure.
0000	RDO & R/E make inspection Tour of Weigel - All secure
0100	Flws, Pope & Weigel, indicate all's well.
0200	Flws - both vessels, note all's well.
0300	F/w's - both ships, report all secure.
0400	Flws - Pope & Weigel, report all secure.
0500	Flws - report all secure.
0600	RDO makes inspection Tour of Weigel - All well. -DO- F/W's-
0625	Relieved of watch by Orr, A/B
0700	ROUTINE WATCH, ALL SECURE MR BARRETT R/O MR SPECTOR R/E (0800-1600) ORR-GWY JACKSON F/W POPE MATED F/W WEIGEL
0800	MOORED AS BEFORE. LINES, GANGWAY, & RATCHARDS SECURE. COLORS EXECUTED.
0900	R/O & R/E COMPLETE A TOUR OF INSPECTION OF BOTH VESSELS.
1000	ALL IN APPARENT GOOD ORDER.
1015	R/O MR. SHERMAN ABOARD. R/E MR. HURLEY ABOARD. MR BARRETT & SPECTOR ASHORE
1100	R/O & R/E MADE TOUR OF INSPECTION
1200	F/W's REPORT ALL IN GOOD ORDER ABOARD BOTH VESSELS
1300	R/O & R/E MAKE ROUTINE INSPECTIONS
1400	ALL IN APPARENT GOOD ORDER.
1430	WATCH RELIEVED BY LARRY PERKINS <i>L.P.</i>
1430	watch assumed - lines - ratchards - gangway - all in good order
1500	fw both vessels - on Detex rounds - report all - secure Mr. "Edwards" aboard - taken to Mr. SHERMAN - Mr. Edwards formally "doctor" aboard USNS POPE (USN) - Mr. Edwards on brief tour - Mr. Edwards ashore - 1520
1520	MR. SHERMAN & MR. HURLEY R/E (1600-2400) Perkins R/O on watch. Pope: F/W Weigel: F/W
1600	Flw on both vessels report - all in good order -
"	R/E & R/O on rounds both vessels - all in good order
1700	Flw on both vessels report all in good order
1800	all in - apparent good order -
1900	Flw - BOTH VESSELS REPORT - all - SECURE
2017	SUNSET - COLORS OBSERVED
"	R/E on rounds - BOTH VESSELS - all in good order
2100	R/O on rounds - BOTH VESSELS - all in good order
2205	MR. SPECTOR R/E ABOARD - MR. HURLEY R/E - ASHORE
2235	MR. BARRETT R/O - ABOARD - MR. SHERMAN ASHORE
2300	Relieved of gangway DUTY
	L.M. Perkins

AT/PASSAGE FROM S.F.B.N.S. - Hunters Point +7	TO Berth 30 - Pier 2
ZONE DESCRIPTION	DATE (Day, month, year) 3 AUG 69
	DAY OF WEEK Sun-

TIME	REMARKS
0000/0800	On watch: Mr. Barrett, RDO - IREDALE, A/B - Celada, F/W - Frutaz, F/W (Weigel) Moored as before - Receiving services from shore as before - Firewatcher making rounds of detex stations ^{and} reporting hourly to quarter deck.
2300	Firewatchers, Pope ^{and} Weigel, report all secure -
0000	F/W's, both ships, indicate all's well -
0100	RDO ^{and} R/E make inspection tour of Weigel - All in apparent good order
0200	F/W's, Pope ^{and} Weigel, note all secure -
0300	F/W's note all secure
0400	F/W, both vessels, report all's well
0500	F/W, Pope ^{and} Weigel, note all secure
0600	All secure Pope ^{and} Weigel, F/W's report -
0630	Relieved of watch by Orr, A/B J. L. Sullivan
0700	ROUTINE WATCH. ALL SECURE. R/O + R/E MADE INSPECTIONS. MR. BARRETT R/O MR. SPECTOR R/E (0800 - 1600) ORR - GWY JACKSON F/W POPE MATEO F/W WEIGEL
0800	MOORED AS BEFORE. LINES, GANGWAY, RAT GUARDS SECURE. COLORS EXECUTED.
0900	F/W's REPORT ALL IN ORDER ABOARD POPE & WEIGEL
1000	R/O + R/E COMPLETE INSPECTIONS OF BOTH VESSEL
1005	R/O SHERMAN RELIEVES MR BARRETT. R/E HURLEY RELIEVES MR. SPECTOR.
1100	ALL IN APPARENT GOOD ORDER.
1200	R/O + R/E MAKE A TOUR OF BOTH VESSELS.
1300	ALL IN GOOD ORDER.
1400	R/O + R/E COMPLETE TOUR OF BOTH VESSELS
1415	WATCH RELIEVED BY LARRY PERKINS Geo. Orr
1415	WATCH - ASSUMED - LINES - RAT GUARDS - GANGWAY SECURE
1500	F/W - REPORT - ALL'S WELL - ON BOTH VESSELS
	1600 - 2400
	MR. SHERMAN R/O - HURLEY R/E - Perkins F/W - D'Amico F/W i, Peletti F/W
1600	F/W ON BOTH VESSELS REPORT - ALL SECURE
1700	R/O + R/E ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
1800	F/W ON BOTH VESSELS - REPORT - ALL IN GOOD ORDER
1900	ALL - IN APPARENT GOOD ORDER
2020	SUNSET - COLORS OBSERVED -
2100	R/E ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
2115	R/O - ON ROUNDS BOTH VESSELS - ALL IN GOOD ORDER
2200	F/W BOTH VESSELS - SECURE - ALL IN GOOD ORDER
2205	MR SPECTOR R/E ABOARD - MR HURLEY R/E ASHORE WATCH - GANGWAY OUTLET properly relieved
2235	MR BARRETT R/O REPORTED - MR SHERMAN R/O - ASHORE
2240	WATCH RELIEVED BY FRUTAZ

D. Perkins

AT/PASSAGE FROM

TO

Berth 30 Pier 2 HUNTER'S POINT Naval Shipyard S.F.

ZONE DESCRIPTION

DATE (Day, month, year)

DAY OF WEEK

+ 7

4 AUG, 19-69

Monday

TIME

REMARKS

0000 - 0800

ON WATCH MR BARRETT R/O MR. SPECTOR R/E
FRUTAZ R/O Gangway Watch. Celada Flw on the
Pope, making his round hourly and report to
Tipton Flw on the Weigel making his round
hourly and report to the Pope's Gangway.

0000 All ships Lines Rat Guard Gangway are in good order.

0100 MR. BARRETT R/O MR. SPECTOR R/E made their round

0200 on the Weigel and the Pope.

0200 Gangway Lines, Rat Guard are in good order.

0300 All Lines Rat Guard are in good order.

0400 Gangway Lines and Rat Guard are in good order.

0500 MR. BARRETT R/O made his round in both ships.

0600 All Lines Rat Guard Gangway are in good order.

0630 Watch Relieved by Goe. Orr.

0635 Y/O RELIEVES R/O BARRETT

0645 LARKIN R/O CALLED IN. GOING TO OAK KNOLL HOSPITAL AND DOCTOR TODAY.
WILL BE IN FOR 12-8 WATCH.

0658 JOE JACKSON CALLED IN. GOING TO DOCTOR TODAY.

0700 DAYWORKERS TURN TO. SMOKE DETECTOR & KIDDE ALARMS TESTED O.K.

MR SKOVOTH R/O

(0800 - 1600)

ORR - GANGWAY

GRAYSON - FIREWATCH

0800 MOORED AS BEFORE. LINES, GANGWAY, R/TE GUARDS SECURE. CAPTAIN HASKELL ABOARD.

0830 2 M/R WORKMEN ABOARD. (MACHINISTS)

0920 2 MEN FROM TRANSBAY ELECTRONICS ABOARD TO WORK ON P.A. SYSTEM

1045 ELECTRONIC MEN ASHORE WITH 2 P.A. AMPLIFIERS & CONTROLLER.

1410 YARD PHONE MAN ABOARD TO FIX PURSER'S PHONE EXTENSION 1415 ASHORE
PHONE O.K.

1425 CAPTAIN ASHORE

1430 WATCH RELIEVED BY LARRY PERKINS Geo. Orr

1430 watch assumed - Lines - R/TE GUARDS - GANGWAY - all in good order
MR. HURLEY R/O ABOARD

1445 MR. SHERMAN R/O ABOARD - MR

1500 Flw BOTH VESSELS REPORT - ALL IN GOOD ORDER - SOUNDINGS TIKED

1600 R/E ON ROUNDS BOTH VESSELS - Flw ON ROUNDS BOTH VESSELS - all in good order

1700 R/O Flw's ON ROUNDS BOTH VESSELS REPORT all in good order

1800 Flw BOTH VESSELS - REPORT - all in good order

1900 ALL IN APPARENT GOOD ORDER

2015 Sunset - colors observed

2100 R/E & R/O ON ROUNDS BOTH VESSELS - all in good order

2200 All in apparent good order

2200 watch relieved by Frutas

MR. SPECTOR R/E ABOARD MR. HURLEY R/O ABOARD

L. W. Perkins

AT/PASSAGE FROM Berth 30 Pier 2 Hunter's Point	TO Naval Ship Yard San Francisco, Calif.	
ZONE DESCRIPTION #7	DATE (Day, month, year) 5 Aug. 19-69	DAY OF WEEK Tuesday

TIME	REMARKS
	0000-0000 ON WATCH MR. BARRETT & MR. SPECTOR R/E FRUTAZ Flw Gangway Watch. Larkin Flw on the Weiger making his round hourly report POPE to the Gangway.
0000	All Gangway, Lines Rat Guard are in good order. Tipton Flw on the Weiger making his Round hourly and Report to the Gangway of the Pope.
0100	MR. BARRETT R/E MR. SPECTOR R/E made their Round in both ship Pope & Weiger.
0200	Both ships Lines Rat Guard are in good order.
0300	Gangway in both ships are in good order.
0400	All Lines Rat Guards in both ships in good order.
0500	MR. BARRETT R/E MR. SPECTOR R/E made their Round in both ships Weiger & Pope.
0600	Both ships Lines Rat Guard Gangway are in good order.
0630	Watch Relieved by MR. GOO ORR
0631	CAPTAIN HASKELL & V/SKOVOTH ABOARD <i>MT Sutan</i>
0700	DAYWORKERS TURN TO. MR SKOVOTH V/ (0800-1600) ORR-GANGWAY JOE JACKSON-FIREWAT
0800	MOORED AS BEFORE. LINES, GANGWAY, & RAT GUARDS SECURE. COLORS
0900	ROUTINE WATCH. ALL IN GOOD ORDER --- APPARENTLY.
1100	ALL SECURE
1400	ALL SECURE
1410	WATCH RELIEVED BY LARRY PERKINS <i>Geo. Orr</i>
1410	Watch assumed - Lines - RAT GUARDS - GANGWAY - ALL IN GOOD ORDER
1430	CAPT HASKELL ASHORE - MR. LUND R/E
1500	MR. SHERMAN V/ ABOARD - CAPELL Flw Weiger - Mateo Flw POPE
1530	R/E ON ROUNDS Weiger - all in good order MR. SHERMAN V/, MR. LUND R/E (1600-2400) PERKINS V/; Mateo Flw POPE; CAPELL Flw Weiger
1600	Flw ON BOTH JESSELS - DETEX ROUNDS - REPORT ALL IN GOOD ORDER
1615	COMMUNIQUE delivered to Pope for CHIEF ENGINEER
1700	R/E ON ROUNDS BOTH JESSELS - ALL IN APPARENT GOOD ORDER
1800	Flw BOTH JESSELS - REPORT - ALL IN GOOD ORDER
1900	Flw BOTH JESSELS - REPORT - ALL IN GOOD ORDER
1930	R/E ON ROUNDS POPE & WEIGER
2015	Sunset - colors observed - all in apparent good order
2200	Flw SECURE all in good order watch relieved by IREDALE <i>L.M. Rector</i>

AT/PASSAGE FROM S F B N S. Hunters Point	TO Berth 30 Pier 2
ZONE DESCRIPTION +7	DATE (Day, month, year) 6 AUG 69
	DAY OF WEEK Wed-

DATE (Day, month, year)
6 AUG 69

DAY OF WEEK
Wed

Lm-Perkins

AT/PASSAGE FROM S.F.B.N.S. Hunters Point	TO Berth 30 - Pier 2
ZONE DESCRIPTION +7	DATE (Day, month, year) 7 Aug 69
	DAY OF WEEK THURS.

TIME	REMARKS
0000-0800	On watch: Mr. Barrett, RDO. IREDALE, A/B - Celada, F/W - Tipton, F/W Weigel. Moored as before - Receiving services from shore as before - Fire-watches, Pope & Weigel, making rounds of detex stations & reporting hourly.
2300	F/W's, both ships, report all secure.
0000	RDO & R/E on inspection tour of Weigel.
0100	F/W's report all secure.
0200	F/W's, both vessels, report all's well.
0300	All secure, F/W's report.
0400	All's well throughout both ships, F/W's report.
0500	F/W's, Pope & Weigel, indicate all secure.
0600	RDO & R/E make inspection tour of Weigel - All secure.
0630	Mr. Skovoth aboard, Mr. Barrett ashore.
0630	Watch relieved by Capell, A/B
	<i>Mr. Skovoth (0800 ~ 1600) Capell, G. Crayson, F/W</i>
0630	Assumed the watch. All in order.
0700	All in apparent good order.
0725	Test of ship's fire alarm system. In order.
0800	Colors. All in apparent good order.
RC 0905	Captain Haskell & wife aboard. (0955) Ashore.
1000	All in apparent good order.
1055	Captain & wife ashore.
1110	Purser to bank via base transport U.S.N. 92-1333
1129	PURSER ABOARD.
1200	All in apparent good order.
1220	Lights out. Shore side. On again (1222)
1300	All in apparent good order.
1323	Lights out again. On again (1328)
1400	All in apparent good order.
1415	Watch relieved by Larkin A/Bs
	<i>R.A. Capell</i>
1500	MR HURLEY R/ENG ON BD, MR SHERMAN R/M ON BD.
1515	10 SKOVOTH LEFT SHIP. SHORE LEAVE COMMENCED
	<i>1600 - 2400</i>
1600	R/MATE SHERMAN R/ENG HURLEY LARKIN R/M DELETI F/W WEIGEL DAVAROL POPE
	ALL IN GOOD ORDER, DETEX RDS MADE BOTH VESSELS
1700	WTD CLOSED - F/W'S REPORT SECURE ENG/REL CHECKED BOTH VESSELS.
1800	SECURE - RDS MADE
1900	ALL IN GOOD ORDER RDS & REPORTS MADE.
2000	COLORS EXECUTED (2013) RDS MADE ALL SECURE
2100	R/OFF CHECKS VESSELS - SATISFACTORY BILGES SHARP ALLEY PUMPED. - VESSELS SECURE RDS MADE
2200	F/W'S REPORT SECURE R/ENG ON BD. MR HURLEY RELIEVED LEFT.
2230	WATCH RELIEVED BY IREDALE.
2300	F/W's indicate all secure (In) <i>Det Larkin</i>

TIME	REMARKS
0000/0800	On watch: Mr. Barrett, RDO - IREDALE, A/B - Celada, Flw - Tipton, Flw Moored as before - Receiving services from shore as before. Firewatches on rounds of deTex stations in Pope + Weigel, and reporting hourly To quarterdeck.
0000	RDO + R/E on inspection Tour of Weigel - All secure
0100	Flw's. report all's well
0200	All secure Pope + Weigel
0300	Flw's, both vessels, report all secure -
0400	Flw's. report all secure -
0500	Flw's. Report All's well.
0600	RDO + R/E make inspection Tour of Weigel - All's well.
0630	Watch relieved by Orr
0630	
0630	Assumed watch. Captain Haskell aboard
0700	DAY WORKERS TURN TO. 0705 MR BARRETT ASHORE. MR SKOVOTH $\frac{1}{6}$ (0800 - 1600) ERR-6WY CAPELL - Flw
0800	MOORED AS BEFORE. LINES, GANWAY, + RATEGUARDS SECURE. COLORS EXECUTED.
0805	SMOKE DETECTOR + KIDDE ALARMS TESTED O.K. RECTIFIERS CHECKED.
0845	CAPTAIN HASKELL TO HEADQUARTERS - CH. ENG. ALSO.
1045	BESSARD, WILLIAM (NMN) FIREMAN-WATERTENDER ABOARD - NEW POSITION DUNGCA, LINCOLN L.E. ENGINE UTILITY ABOARD - NEW POSITION
1200	ROUTINE WATCH. ALL IN GOOD ORDER
1300	ALL SECURE
1400	ALL IN GOOD ORDER
1415	WATCH RELIEVED BY LARKIN $\frac{1}{6}$ <i>Lp. On</i>
1500	Flw's REPORT ALL IN GOOD ORDER. R/O ON BD
1515	R/M SHERMAN ON BD $\frac{1}{6}$ SKOVOTH ASHORE.
	1600 - 2400 MR SHERMAN R/M MR HURLEY R/ENG LARKIN $\frac{1}{6}$ R/M WEIGEL DECTI Flw POPE DAVACOL
1600	DETEX RDS MADE, ALL SECURE
1700	WTDS CLOSED BOTH VESSELS. R/ENG MADE RDS ALL SECURE
1800	SECURE.
1900	Flw's REPORT VESSELS SECURE. R/M CHECKS WEIGEL + POPE.
2000	DETEX RDS MADE. REPORT SECURE
2012	COLORS EXECUTED NIGHT LTS. ON.
2100	SECURE. DETEX RDS MADE. R/M CHECKS WEIGEL + POPE SAT
2200	SECURE, ALL IN GOOD ORDER R/ENG PUMPS BILGES, CHECKS
2230	WATCH RELIEVED BY IREDALE $\frac{1}{6}$ <i>Pat Larkin</i>
2230	R/ENG. MR SPECTOR ON BD
2245	MR BARRETT R/O ON BD.
2300	Flw, both vessels, report all secure - <i>(Dr)</i>