

USNS GENERAL JOHN POPE (T- AP 110)

HLH: na
7 Sept. 1967

From: Master
To: All Ship's Personnel.

Subj: Inspection of Crew's Quarters and facilities, report of.

1. The following were the results of Master's Inspection conducted this date:

2-82-0-L Dust on top of door (Troop Mess Area)
2-130-4-L Dust on the overhead pipes
2-142-0-E ... Very Unsatisfactory; door sprung; area needs general cleaning (Fan Room)
2-146-4-L Drain needs polishing and cleaning on base tile of Washroom.
Very good.
2-150-2-L ... Leak underneath urinal (Washroom)
2-153-2-L ... Very good. Secure bracket on shower pipe
2-155-2-6 Leak under urinal.
2-155-4-L No comment
1-158-4-L Good
2-164-2-L Very good
2-165-2-L No comment
2-170-6-L This room needs a field day
2-176-2-L Bunk Cards missing
2-173-1-L Very Dirty
2-179-2-L ..., No comment
2-183-2-L Good
3-183-1-L Re-Install light fixture to bunk lights
3-181-3-L ... Very good
3-174-1-L do do
3-167-3-L ... Mold on corner of shower
3-166-1-L ... No comment
Crew Day room do do
3-141-1-L Improved
3-126-1-L Dirt in corners
3-140-0-L Paint the overhead pipes in washroom (Engine)
3-144-2-L ... Very good (Washroom)
3-146-4-L ... No comment
3-146-2-L Attn: Engine Department; remove stores from this area (P.X. Area) No. 3 deck Port side
NOTE: Install bunk card throughout the entire ship

General comments: The over-all inspection was very good.


H. L. HEINZ, Master