

U.S. GENERAL JOHN POPE (TAP 110)
OFFICE OF THE CHIEF STEWARD
CAPTAIN'S INSPECTION

File

21 APRIL 67

1. Clean valves at Fire Station 2-134-2 with crocus cloth and change hose.
2. Clean rust on Drinking Fountain near 2-145-2-L.
3. Clean bottom of toilet seats - 2-155-2-L.
4. In Cabin Class Passengers' Staterooms, MARK BOAT STATION ON INSTRUCTION SHEET.
5. Clean Drain - 2-164-2-L.
6. Clean Drain & Repaint 2-167-4-L.
7. Clean up the white work a little better 2-167-2-L.
8. Remove dirty glasses and tidy up room, especially the bunk shelves 2-176-2-L.
9. Clean paint from valve stem of Fire Hydrant WT BHD -186.
10. Clean rust from Drinking Fountain near WT BHD 186.
11. Top bunk un-made, basin dirty, mirror filthy- general appearance of this room IS TOTALLY UNSATISFACTORY.
12. Polish pipes under the sink. 3-177-1-L.
13. * Remove all swabs from sleeping quarters. / Secure heat 3-174-1-L.
14. Clean border tile 3-161-2-L.
15. * Prepare Station Bills for Master's signature.
16. Clean exhaust drain 3-166-2-L.
17. Polish brass on toilet seats, clean mirror & white work 3-167-1-L.
18. Urinal needs cleaning; clean and scour toilet seats 3-167-2-L.
19. Magazines could be straightened out on " Bookshelf ".
20. Clean out Drain 3-167-4-L.
21. Bunk un-made, untidy Bunk shelf and plenty of excess junk: GENERAL CONDITION OF THIS ROOM IS UNSATISFACTORY. - 3-170-2-L.
22. Vapor globe missing 3-178-4-L.
23. Occupant Card Missing 3-184-4-L.
24. Toilet seats need cleaning 3-150-2.
25. Clean valve stems with crocus cloth & tidy up this section 3-150-2.
26. Bowl needs cleaning 3-144-2-L.
27. Drain needs cleaning 3-140-4-L.
28. Frame for Occupant Card is missing 3-140-6-L.
29. Fire Station 3-126-2 is DUSTY AND DIRTY.
30. Re-adhere (tape or glue and or as necessary) vent duct S-2-143-1.
31. Clean rust from Drinking Fountain in Passageway 3-146-1-L.
32. Use Clorox and kill mold fungus in Crew Shower 3-149-4-L.
33. Clean vapor globe and water drain 3-149-6-L.
34. Vapor globes dirty 3-140-0-L.
35. Control Cabinet (F-125) Unlocked.

CAPTAIN'S REMARKS ON INSPECTION:

"I am very well pleased with the overall improvement of the Crew's Quarters,- the cleaning and general housekeeping are generally good.

There was only one room that was totally unsatisfactory in every way belonging to the Engine Dept.'s Wipers # 3-170-2-L.

Paint Fire Hydrant valves and clean stems with crocus cloth where indicated.

Require Engine Dept. to follow up on Lint Disposal from the dryers in the Crew Laundry rooms."

[Signature]

- MASTER -