

[illegible]

NAVSHIPS 827-A (REV. 8-64) BACK

15-5010-3

[illegible]

S-65

#2 Radio

INDEX

UNIT


CARD NO.

DATE

Apr. 19

PLOT ONLY INSULATION
RESISTANCE VALUES WHICH
HAVE BEEN CORRECTED TO

25° C. IN ACCORDANCE WITH
BUSHIPS MANUAL CHAPTER
60.



DATE

MEGOHMS

25° C. IN ACCORDANCE WITH
BUSHIPS MANUAL CHAPTER
60.50
40
30
20
15
10
8
6
4
3
2
1.5

1 MEGOHM

OHMS

PLOT ONLY INSULATION
RESISTANCE VALUES WHICH
HAVE BEEN CORRECTED TO500,000
400,000
300,000
200,000
150,000
100,000
50,000
40,000
30,000
20,000
15,000

INDEX

UNIT

CARD No.

8-63		Radio #1		SERVICE		CARD NO.
BUCK	UNIT					
Location: Deck	4	Frame	151-1	Compt.	Position	
Manufacturer	The Hallcrafters Co.		Contract No.	Mfg. Dwg. No.	Date Mfg.	
Voltage	National	Phase	Cycles	Amps.	PF	
Power Rating	RPM	Serial No.	C. R. No.			
Model No.	21-TEHL-183-MR		Class	Form	Mo. Fr.	
Exc. Volts	Res.	Winding	Enclosure: W. T.	N. W. T.	D. P.	
Duty	Load	Time	Temp. Rise	C°		
Bearings: Type	No. Fwd.	No. Aft	Spare Parts Box No.			
Plan No.	S. O. No.	Dwg. No.	Pressure: Cut In	Cut out		
Navy Spec. No.	Pc. No.					
DATE	REMARKS					HRS. IN USE
5-8-53	Clean					
6-28-53	Clean					
7-18-53	Clean					
8-17-53	Clean					
9-12-53	Clean					
10-15-53	Clean					
11-22-53	Clean					
12-23-53	Clean					
1-21-54	Clean					
2-22-54	Clean					
3-20-54	Clean					
4-21-54	Clean					
5-23-54	Clean					
10-65	REACTIVATED BY TODD'S SHIPYARD					

