

CLASSIFICATION

REPORT OF DEGAUSSSED MAGNETIC CONDITION

REPORT SYMBOL BUWEPS 8950-43

TO: (Ship name, type, and number, and nation)

DATE OF REPORT

USNS JOHN POPE (TAP 110)

7 May 1968

MEASURING ACTIVITY (Name and nation)

APPROVED (Signature)

U.S. Naval Degaussing Station, San Francisco

Philip B. Howe

DATE OF MEASUREMENTS

DG CODE NUMBER (Optional)

1 May 1968

CHECK APPLICABLE BLOCKS

 1. SHIP'S DEGAUSSSED MAGNETIC CONDITION IS SATISFACTORY WITH

- A. EXISTING DEGAUSSING CHARTS.
- B. REVISEO DEGAUSSING CHARTS WHICH HAVE ALREADY BEEN ISSUED TO SHIP.
- C. REVISED DEGAUSSING CHARTS WHICH ARE ATTACHED.

 2. DEGAUSSING ACTION IS REQUIRED

- A. RECOMMENDATION FOR ACTION HAS BEEN ISSUED TO SHIP.
- B. RECOMMENDATION FOR ACTION IS ATTACHED.

 3. FURTHER ANALYSIS OR DATA REQUIRED: RECOMMENDATION AND DATA HAVE BEEN FORWARDED TO _____

(ACTIVITY)

FOR EVALUATION IN CONJUNCTION WITH PRIOR MAGNETIC DATA, AND FOR REPORT TO SHIP.

REMARKS

Your West run of May 1, altho within prescribed limits shows rather high Longitudinal Magnetism. It is recommended that you make a check run at your next opportunity. It is desirable to run on an approximately true East or West heading at approximately 100 yds from either buoy.

RECEIVED

MAY 23 1968

/S-3

USNS POPE T-AP110

COPY TO:

COMSTSPACAREA

CLASSIFICATION AND GROUP MARKING

S/N 0140-895-0440

NAVWEPS FORM 8950/43A (12-64)
DG NO. 1